

EG91-NA-FB Release Notes

LTE Standard Module Series

Rev. EG91-NA-FB_Firmware_Release_Notes_V0507_30.003.30.003

Date: 2023-10-23



Our aim is to provide customers with timely and comprehensive service. For any assistance, please contact our company headquarters:

Quectel Wireless Solutions Co., Ltd.

Building 5, Shanghai Business Park Phase III (Area B), No.1016 Tianlin Road, Minhang District, Shanghai 200233, China

Tel: +86 21 5108 6236 Email: info@quectel.com

Or our local office. For more information, please visit:

http://www.quectel.com/support/sales.htm.

For technical support, or to report documentation errors, please visit:

http://www.quectel.com/support/technical.htm

Or email to support@quectel.com.

Disclaimer

While Quectel has made efforts to assure the accuracy of this document, unless otherwise provided by valid agreement, Quectel assumes no liability resulting from any inaccuracies or omissions in this document, or from use of the information obtained herein. Quectel reserves the right to make changes to any contents described herein and reserves the right to revise this document and to make changes from time to time in content hereof with no obligation to notify any person of revisions or changes. Before using any updated software, please read this statement carefully. By accessing or using the said software you irrevocably and unconditionally accept and confirm that you agree to be bound by this statement. In the event you disagree with any provision hereof and would not like to be bound by this statement you shall cease use of the said software immediately.

Duty of Confidentiality

The Receiving Party shall keep confidential all documentation and information provided by Quectel, except when the specific permission has been granted by Quectel. The Receiving Party shall not access or use Quectel's documentation and information for any purpose except as expressly provided herein. Furthermore, the Receiving Party shall not disclose any of the Quectel's documentation and information to any third party without the prior written consent by Quectel. For any noncompliance to the above requirements, unauthorized use, or other illegal or malicious use of the documentation and information, Quectel will reserve the right to take legal action.

Copyright

The information contained here is proprietary technical information of Quectel Wireless Solutions Co., Ltd. Transmitting, reproducing, disseminating and editing this document as well as using the content without permission are forbidden. Offenders will be held liable for payment of damages. All rights are reserved in the event of a patent grant or registration of a utility model or design.

Copyright © Quectel Wireless Solutions Co., Ltd. 2023. All rights reserved.



1. Preamble

This document provides the Release Notes for EG91-NA-FB firmware version **EG91NAFBR05A07M4G_30.003.30.003**. It describes major changes compared to EG91-NA-FB firmware version **EG91NAFBR05A07M4G_30.002.30.002**.

2. Matters Needing Attention

SN	Brief Description
[1]	To extend the service life of flash, the following operations should be avoided to be performed frequently: powering on/off the module, CFUN switching, SIM card hot swapping, dual-SIM switching, and repeated execution of NVM commands.
[2]	It is not recommended to directly modify the pre-set APN profiles. Please create an APN profile after the existed CID number. Suppose you modify the APN profile of IMS, SOS, etc. with added specific attributes, these attributes are hidden after modification, causing the profile to still be unavailable.
[3]	 AT+QGDCNT=1 and AT+QPDPGDCNT=1 will write data to the flash. Therefore, please do not execute the AT commands frequently. AT+QAUGDCNT is used in conjunction with the above commands to automatically save the packet data counter. 1. If there is no mandatory need, it is not recommended to use these AT commands; 2. The time interval set by the timer needs to be lengthened when you use these AT commands.
[4]	Cross-baseline software version update is not supported. For EG91NAFBR05A07M4G_30.003.30.003 , "R05" represents the baseline information. This Quectel module does not support updating to a firmware version other than R05. If you have any related requirements, please contact Quectel Technical Support.

3. New Features

Item/Category	Brief description	Since
AUDIO	Added the support of MAX9860 Codec.	R05A07_30 .003.30.003
NETWORK	Relevant technical controls have been carried out to restrict normal network registration in regions such as RUS and IRN, thus ensuring that the module can be used only for civilian applications.	R05A07_30 .003.30.003



NETWORK	Change the roaming state to home service when 313-100 SIM is	R05A07_30
	registered on a 310-410 PLMN.	.003.30.003
NETWORK	Added AT+QNWCFG="rej_cause_7_mapping" command to control	R05A07_30
	whether to map the network rejection reason value #7.	.002.30.002
TCP SSL	Enabled client renegotiation on the module through	R05A07_30 .002.30.002
	AT+QSSLCFG="renegotiation". Added the AT command AT+QCFG="TCP/SendMode" to configure	R05A07_30
TCP/UDP		.002.30.002
	TCP sending mode. Added the AT command AT+QAUDCFG="uac_fs" to configure UAC	R05A07_30
UAC	sampling rate.	.002.30.002
	Sampling rate.	R05A07_30
GENERAL	Supported T-Mobile SIM card (311-882).	.002.30.002
	Added ATLOCEC-"anoflag" to set EDC capability value in attach	
GENERAL	Added AT+QCFG="epcflag" to set EPC capability value in attach	R05A07_30 .002.30.002
	request.	R05A07_30
GENERAL	Updated the list of mbedtls encryption library kit.	.002.30.002
		R05A07 30
GENERAL	Added AT+QCFG="airplane" to configure airplane mode.	.002.30.002
	Added AT command AT+QCFG="fast/poweroff" to control whether	R05A07_30
GENERAL	to power off the module quickly.	.002.30.002
	to power on the module quickly.	R05A07_30
GENERAL	Added AT command AT+QCFG="usbmode" to get USB mode.	.002.30.002
		R05A07_30
GENERAL	Supported USCC MBN.	.002.30.002
	Added AT command AT+QCFG="secbootstat" to get SecBoot	R05A07_30
GENERAL	status.	.002.30.002
	Added AT command AT+QWDTMF to play DTMF files or send it to	R05A07_30
DTMF	Far-end.	.001.30.001
	Added AT command AT+QMTCFG="protocol/check" to configure	R05A07_30
MQTT	whether to check MQTT header information.	.001.30.001
	Added AT command AT+QFTPCFG="restenable" to control whether	R05A07_30
GENERAL	to enable FTP server to support REST command.	.001.30.001
		R05A07_30
GENERAL	Supported RDA PA.	.001.30.001
	Added AT command AT+QAPRDYIND to configure whether to report	R05A07_30
GENERAL	the specified URC.	.001.30.001
	·	R05A07_30
GENERAL	Supported Rogers MBN.	.001.30.001
		R05A07_30
GENERAL	Added Rogers back-off mechanism for certification.	.001.30.001
		R05A07_01
GENERAL	Added class 6 APN for Verizon.	.001.01.001
	Added AT+QDTMFDETSET to support configuring/obtaining DTMF	R05A07_01
DTMF	DETECTION module parameters in ACDB.	.001.01.001
	2	



	Added AT command AT+QCFG="voice_busytone" to	R05A07_01
Voice Call	enable/disable busy tone playback for Verizon network.	.001.01.001
SMS	0	R05A07_01
SMS	Supported SMS black and white list.	.001.01.001
	Added AT command AT+QICFG="recv/buffersize" to manually	R05A07_01
GENERAL	configure the threshold of wm_high in socket application layer.	.001.01.001
	Added AT commands AT+QSIMWRFREQ to record the frequency of	
SIMCARD	EF files written to SIM card and AT+QSIMVOL to configure SIM card	R05A07_01
	supply voltage.	.001.01.001
	Added AT command AT+QOPS to scan full frequency and display a	
GENERAL	list of network information of all available operators in the current	R05A07_01
	physical location.	.001.01.001
		R05A07_01
GENERAL	Enabled DSCI reporting for emergency call without SIM card inserted.	.001.01.001
		R05A07 01
FTP	Fixed the problem of FTPS not displaying SSL.	.001.01.001
		R05A07_01
GENERAL	Supported SMTP server's analysis of multiple responses.	.001.01.001
	Added AT command AT+QCFG="call_control" to control MO or MT	R05A07 01
Voice Call	of voice call.	.001.01.001
	Added AT command AT+QLBSCFG="contextid" to configure the	R05A07_01
QuecLocator2.0	QuecLocator context ID.	.001.01.001
		R05A06 01
FTP	Added commands EPSV/EPRT to match IPv6 FTP.	.001.01.001
	Supported publishing up to 10K messages at a time via	R05A06_01
MQTT	AT+QMTPUBEX.	.001.01.001
	711.5 5527.	R05A06 01
TCP SSL	Added AT command AT+QSSLRECV to read the remaining data.	.001.01.001
		R05A05 01
AUDIO	Added AT command AT+QAUDCFG="aig".	.005.01.005
		R05A05_01
AUDIO	Added ALC5660 codec.	.005.01.005
		R05A05_01
GENERAL	Added ADB and UART security features.	.005.01.005
		R05A05_01
GENERAL	Added AT command AT+QCFG="urcdelay".	.005.01.005
		R05A05_01
GENERAL	Supported AT&T OMA-DM to use the specified APN.	.005.01.005
QuecLocator		R05A05_01
2.0	Added the positioning function of AT+QLBS.	.005.01.005
4. 0		
NETWORK	Added AT command AT+QNWLOCK="common/lte".	R05A05_01 .005.01.005
Ougal agatar		
QuecLocator	Added AT command AT+QLBSCFG="latorder".	R05A05_01
2.0		.005.01.005



SIMCARD	Added AT command AT+CCHO, AT+CCHC and AT+CGLA.	R05A05_01
		.005.01.005
TCP SSL	Added command of AT+QSSLSEND=0 to query the cache status of	R05A05_01
	the AT+QSSLSEND.	.005.01.005
AUDIO	Added UAC function.	R05A05_01
		.005.01.005
GENERAL	Added AT command AT+QODM="hostdevice".	R05A05_01
		.005.01.005
MQTT	Added AT command AT+QMTCFG="willex" to configure will_msg.	R05A04_01
- India	Added At Command At Femilion 6 - Which to comigure will_mag.	.005.01.005
NETWORK	Added AT command AT+QCFG="cops_no_mode_change".	R05A04_01
METWORK	Added AT command ATTWOTO - cops_no_mode_change .	.004.01.004
NETWORK	Added AT command AT+QLTENGBR.	R05A04_01
NETWORK	Added AT command AT+QLTENGBR.	.004.01.004
TOD CCI	Added AT command AT, OCCI CEC, Holioptico.	R05A04_01
TCP SSL	Added AT command AT+QSSLCFG="clientkey".	.004.01.004
	Added AT command	D05404 04
TCP SSL	AT+QSSLCFG="closetimemode", <ssl_ctx_id>[,<closetime_mod< td=""><td>R05A04_01</td></closetime_mod<></ssl_ctx_id>	R05A04_01
	e>].	.004.01.004
SMS	Added AT command AT+QCFG="Itesms/format".	R05A04_01
SIVIO	Added AT Command ATTQCT G= Resilis/format .	.004.01.004
	Added below AT commands:	
	AT+QSSLCFG="ignoremulticertchainverify", <ssl_ctx_id>[,<igno< td=""><td>R05A04_01</td></igno<></ssl_ctx_id>	R05A04_01
TCP SSL	re_multicertchain_verify>]	.004.01.004
	AT+QSSLCFG="ignoreinvalidcertsign", <ssl_ctx_id>[,<ignore_in< td=""><td>.004.01.004</td></ignore_in<></ssl_ctx_id>	.004.01.004
	validcertsign>]	
GENERAL	Added new number 000 to emergency number list without sim card	R05A04_01
GENERAL	and added AT command AT+QECCNUM=4.	.004.01.004
NETWORK	A 11 14T	R05A04_01
NETWORK	Added AT command AT+QCOPSCFG.	.004.01.004
OFNEDA	ALLELAT CORM III COLOR ATOT COM	R05A04_01
GENERAL	Added AT command AT+QODM="hostdevice" for AT&T OMA.	.004.01.004
		R05A04_01
GENERAL	Added feature of ECBM for Verizon.	.004.01.004
	Refreshed NV settings for AT&T when inserting SIM card of AT&T.	R05A04
GENERAL		
GENERAL	Added AT command AT+QCFG="dhcppktfltr".	R05A04



4. Improved Features

Item/Category	Brief description	Since
MQTT	Fixed the problem that the Keepalive PING packet was not sent	R05A07_30
	successfully, which led to the abnormal disconnection of MQTT.	.003.30.003
Voice Call	Fixed the problem that the module may be abnormal due to hanging up	R05A07_30
	the phone.	.003.30.003
GENERAL	Restored AT+QLWCFG="startup" to configure the startup mode of	R05A07_30
	LwM2M client.	.003.30.003
	1. Fixed the problem that GALILEO satellite could not be obtained in	
GENERAL	the United States.	R05A07_30
	2. Fixed the problem that QZSS could not be used for positioning	.003.30.003
	after AT+QGPSCFG="gnssconfig" was executed.	
FTP	Optimized the status value of the implicit server Alert.	R05A07_30
	Spanial of the states of the implicit server / tiert.	.002.30.002
НТТР	Fixed the problem that the module was unstable after receiving RST	R05A07_30
	during HTTPS handshake.	.002.30.002
НТТР	Optimized the problem that the error code 702 was reported in a small	R05A07_30
	probability when HTTPS files were uploaded.	.002.30.002
SMTP	Solved the problem of slow sending 10 M files for SMTP.	R05A07_30
SWITT	Solved the problem of slow sending to writes for Switt.	.002.30.002
GENERAL	Extended AT+QDAI command to set number of slots and slot mapping	R05A07_30
GLINEINAL	values.	.002.30.002
GENERAL	Set voice centric for Verizon MBN.	R05A07_30
GLINEINAL	Set voice centric for verizon MBN.	.002.30.002
GENERAL	Solved the problem that AT+ODIS failed to set.	R05A07_30
GENERAL	Solved the problem that ATTODIS falled to Set.	.002.30.002
GENERAL	Modified the T-Mobile MBN to solve the problem that IPv4 could not be	R05A07_30
GENERAL	used in T-Mobile network.	.002.30.002
CENEDAL	Solved the problem that executing AT+QISEND ending with character	R05A07_30
GENERAL	"\r\n" would cause the server to receive data abnormally.	.002.30.002
GENERAL	Optimized back off algorithm of Bacara aparatar	R05A07_30
GENERAL	Optimized back-off algorithm of Rogers operator.	.002.30.002
CENEDAL	Updated some time zones to fix the problem that the time queried by	R05A07_30
GENERAL	AT+CCLK? was wrong after AT+CTZU=3 was set.	.002.30.002
OENED A!	Solved the problem of invalid value returned by AT+QCSQ command	R05A07_30
GENERAL	caused by the delay in RSSI reporting.	.002.30.002
OENER AT	Outside LAT OHOD service I	R05A07_30
GENERAL	Optimized AT+CUSD command.	.002.30.002
ALIDIC	Market de la contraction de la	R05A07_30
AUDIO	Modified the value returned by AT+CRSL=? from (0,5) to (0-7).	.001.30.001
DFOTA	Solved the problem that DFOTA upgrade failed when special	R05A07_30



	characters included in the HTTP URL.	.001.30.001
FTP	Solved the problem of timeout error (error code 609 returned) when executing AT+QFTPOPEN to log in to the FTP(S) server.	R05A07_30 .001.30.001
MQTT	Solved the problem that the SFS encrypted certificate failed to establish a two-way authentication connection with the mosquito, FTP or HTTP server.	R05A07_30 .001.30.001
SIMCARD	Solved the problem that the SIM card hot-plug function could not work normally after selecting slot2.	R05A07_30 .001.30.001
TCP SSL	Solved the problem that the SSL server could not be connected normally after setting the SSL version to SSL3.0.	R05A07_30 .001.30.001
TCP SSL	Improved the stability of the module when TCP SSL was multiplexed at the same time.	R05A07_30
GENERAL	Solved the problem that ACDB files on Modem side could not be obtained by AT+QACDBLOAD? .	R05A07_30
GENERAL	Optimized the ubi read-write partition mounting and exception handling mechanism.	R05A07_30
GENERAL	Optimized AT+QPOWD=0 to fast shut down the module.	R05A07_30
GENERAL	Updated the AT&T MBN version to 202105271 to use the MTU size allocated by the network and change ue_usage_setting to DATA Centric.	R05A07_30
GENERAL	Updated SE13 TABLE date to 2020/12/21.	R05A07_30
GENERAL	Solved the problem that the uploaded AT&T APN name of Object 11 instance 0 is null.	R05A07_30
GENERAL	Modified the configuration of the 2nd profile (IMS) for T-Mobile to change the OVRRIDEHOPDP to IPV6.	R05A07_30
GENERAL	Disabled fast dormancy for T-Mobile and updated T-Mobile MBN version to 202106241.	R05A07_30
MQTT	Solved the problem that after setting willmessage with a length of 256 bytes through AT+QMTCFG="WILLEX" , willtopic will also be returned after willmessage in URC.	R05A07_01
NETWORK	Optimized AT+QCFG="fast_dormancy" to support fast dormancy mode 3.	R05A07_01
GENERAL	Modified MultiMBN policy to solve the problem of frequently writing FLASH during MBN activation.	R05A07_01
НТТР	Solved the problem that the module worked improperly after asking an HTTP request with wrong URL.	R05A07_01
GENERAL	Solved the problem that the AT port could not work normally after AT+QRXIIR? exectuion.	R05A07_01
GENERAL	Solved the problem of disconnection after USB suspended and then	R05A07_01



GENERAL	Updated the cefs version to EG91_NA_V00008_202006171.	R05A07_01
		.001.01.001
GENERAL	For non-Chinese operators, turned on AGPS function by default.	R05A07_01
OLIVEINAL	To Horr Chinese operators, turned on Acr Chanculor by default.	.001.01.001
GENERAL	Solved the problem that data sent and received by the module would	R05A07_01
GLINLINAL	lose after the module connected to the DTLS server.	.001.01.001
	Solved the problem that after using AT+QCFG="usbnet" to set the	R05A07_01
GENERAL	usbnet mode to RNDIS, rebooting the module, PC could not connect to	.001.01.001
	the Internet.	.001.01.001
FTP	Solved the problem that there may be no response or 603 error code	R05A07_01
FIF	reported during FTP download and upload.	.001.01.001
ETD	Improved ETDS implicit made compatibility	R05A07_01
FTP	Improved FTPS implicit mode compatibility.	.001.01.001
	Solved the problem that the module may not work normally or error	D05407 04
FTP	codes 603 or 627 returned when data was downloaded discontinuously	R05A07_01
	through FTP.	.001.01.001
ETD	Solved the problem that the AT port could not work normally when the	R05A07_01
FTP	FTPS data were obtained under implicit/explicit encryption mode.	.001.01.001
ETD	Optimized the process of compatibility with various server connections	R05A07_01
FTP	and interactions.	.001.01.001
	Updated the first profile of T-Mobile to support T-Mobile data	R05A07_01
GENERAL	transmission.	.001.01.001
T00///00	Solved the problem that the number of actually connected clients did	R05A07_01
TCP/UDP	not match the set clients when the module was used as a TCP server.	.001.01.001
	Solved the problem that the module could not work normally due to	
	uploading a large number of files (10M) to FTP via UFS after the	R05A07_01
FTP	module established a non-authenticated explicit/implicit connection	.001.01.001
	with the FTP server.	
	Corrected the response format of AT+QMTUNS=? from +QMTSUB to	R05A07_01
MQTT	+QMTUNS.	.001.01.001
	Solved the problem that error code 619 may be returned when PUT file	R05A07_01
FTP	via FTP.	.001.01.001
	Solved the problem that AT+QEEC? could not get echo cancellation	R05A07_01
GENERAL	parameters.	.001.01.001
		R05A07_01
GENERAL	Fixed the deadlock occurred when loading/unloading Mac driver.	.001.01.001
		R05A07_01
SMS	Not saved WAP PUSH SMS in OMA.	.001.01.001
		R05A06_01
GENERAL	Update Verizon MBN version to 201911221.	.001.01.001
	Solved the problem of USB port disconnection due to long time for USB	R05A06_01
GENERAL	resume.	.001.01.001
	Supported reading and writing SMS in the case of no SMS storage	R05A06_01
SMS	area in the SIM card.	.001.01.001
	area in the only outer	.501.01.001



DEOTA		
DFOTA	Updated recovery to fix the problem of log being output during FOTA.	R05A06_01
		.001.01.001
SIMCARD	Enabled invalid SIM card identification.	R05A06_01
		.001.01.001
GENERAL	Updated hVoLTE-Verizon to 0xEE000102.	R05A05_01
	<u>'</u>	.005.01.005
GENERAL	Changed the value of disable_recovery_upon_infinite_null as 1.	R05A05_01
		.005.01.005
GENERAL	Supported to restore configurations of AT+QECCNUM to default value	R05A05_01
	automatically if an error about NV value occurred.	.005.01.005
TCP SSL	Extended the command AT+QSSLCFG="cacertex" to add multiple CA	R05A05_0
	certificates.	.005.01.005
RMNET	Solved the problem that error occurred after executing command	R05A05_01
	AT\$QCRMCALL.	.005.01.00
DFOTA	Opened the serial port for URC output at the baud rate that the	R05A05_0
	customer set during the recovery process.	.005.01.00
DFOTA	Solved the problem that no URC reported about FOTA upgrade.	R05A05_0
	coived the problem that no onco reported about 1 on tapgrade.	.005.01.00
DFOTA	Supported HTTPs protocol download in the process of FOTA upgraded.	R05A05_0
DIOIA	Supported 111 11 3 protocor download in the process of 1 OTA apgraded.	.005.01.00
FTP	Solved the problem that an error would be reported unexpectedly when	R05A05_0
	the FTP transmission was not continuous.	.005.01.00
	Solved the problem of serial port abnormality while returned ERROR	
FTP	directly after returning CONNECT via commands AT+QFTPPUT,	R05A05_0
FIF	AT+QFTPGET, AT+QFTPLIST and AT+QFTPNLST under PORT	
	The state of the s	.005.01.00
	mode.	.005.01.00
GENERAL		
GENERAL	mode.	R05A05_0
	mode. Solved the problem that no URC for manufacturer command when	R05A05_0
GENERAL	mode. Solved the problem that no URC for manufacturer command when executed AT+CMEE=0.	R05A05_0 .005.01.009 R05A05_0
GENERAL	mode. Solved the problem that no URC for manufacturer command when executed AT+CMEE=0. Solved the problem of returned format error when executed AT	R05A05_0 .005.01.009 R05A05_0 .005.01.009
	mode. Solved the problem that no URC for manufacturer command when executed AT+CMEE=0. Solved the problem of returned format error when executed AT command AT+CCLK?.	R05A05_01 .005.01.008 R05A05_01 .005.01.008 R05A05_01
GENERAL	mode. Solved the problem that no URC for manufacturer command when executed AT+CMEE=0. Solved the problem of returned format error when executed AT command AT+CCLK?. Solved the problem that when set the parameter of AT+CTZU to illegal value 2, it would be set and take effect unexpectedly, not fail.	R05A05_0° .005.01.009 R05A05_0° .005.01.009 R05A05_0° .005.01.009
GENERAL	mode. Solved the problem that no URC for manufacturer command when executed AT+CMEE=0. Solved the problem of returned format error when executed AT command AT+CCLK?. Solved the problem that when set the parameter of AT+CTZU to illegal	R05A05_0° .005.01.009 R05A05_0° .005.01.009 R05A05_0° .005.01.009 R05A05_0°
GENERAL GENERAL	mode. Solved the problem that no URC for manufacturer command when executed AT+CMEE=0. Solved the problem of returned format error when executed AT command AT+CCLK?. Solved the problem that when set the parameter of AT+CTZU to illegal value 2, it would be set and take effect unexpectedly, not fail. Optimized RF TX under non-signaling mode.	R05A05_0° .005.01.009 R05A05_0° .005.01.009 R05A05_0° .005.01.009
GENERAL	mode. Solved the problem that no URC for manufacturer command when executed AT+CMEE=0. Solved the problem of returned format error when executed AT command AT+CCLK?. Solved the problem that when set the parameter of AT+CTZU to illegal value 2, it would be set and take effect unexpectedly, not fail.	R05A05_01 .005.01.008 R05A05_01 .005.01.008 R05A05_01 .005.01.008 R05A05_01
GENERAL GENERAL GENERAL	mode. Solved the problem that no URC for manufacturer command when executed AT+CMEE=0. Solved the problem of returned format error when executed AT command AT+CCLK?. Solved the problem that when set the parameter of AT+CTZU to illegal value 2, it would be set and take effect unexpectedly, not fail. Optimized RF TX under non-signaling mode. Updated Telus-Commercial to 0x05800C60.	R05A05_0° .005.01.008 R05A05_0° .005.01.008 R05A05_0° .005.01.008 R05A05_0° .005.01.008
GENERAL GENERAL	Solved the problem that no URC for manufacturer command when executed AT+CMEE=0. Solved the problem of returned format error when executed AT command AT+CCLK?. Solved the problem that when set the parameter of AT+CTZU to illegal value 2, it would be set and take effect unexpectedly, not fail. Optimized RF TX under non-signaling mode. Updated Telus-Commercial to 0x05800C60. Solved the problem that quectel-gps-handle process taken too much	R05A05_07 .005.01.008 R05A05_07 .005.01.008 R05A05_07 .005.01.008 R05A05_07 .005.01.008 R05A05_07
GENERAL GENERAL GENERAL GENERAL	Solved the problem that no URC for manufacturer command when executed AT+CMEE=0. Solved the problem of returned format error when executed AT command AT+CCLK?. Solved the problem that when set the parameter of AT+CTZU to illegal value 2, it would be set and take effect unexpectedly, not fail. Optimized RF TX under non-signaling mode. Updated Telus-Commercial to 0x05800C60. Solved the problem that quectel-gps-handle process taken too much CPU resource and failed to support USB hot plugging.	R05A05_0 .005.01.008 R05A05_0 .005.01.008 R05A05_0 .005.01.008 R05A05_0 .005.01.008 R05A05_0 .005.01.008
GENERAL GENERAL GENERAL	Solved the problem that no URC for manufacturer command when executed AT+CMEE=0. Solved the problem of returned format error when executed AT command AT+CCLK?. Solved the problem that when set the parameter of AT+CTZU to illegal value 2, it would be set and take effect unexpectedly, not fail. Optimized RF TX under non-signaling mode. Updated Telus-Commercial to 0x05800C60. Solved the problem that quectel-gps-handle process taken too much	R05A05_0 .005.01.003 R05A05_0 .005.01.003 R05A05_0 .005.01.003 R05A05_0 .005.01.003 R05A05_0 .005.01.003 R05A05_0
GENERAL GENERAL GENERAL GENERAL GENERAL	Solved the problem that no URC for manufacturer command when executed AT+CMEE=0. Solved the problem of returned format error when executed AT command AT+CCLK?. Solved the problem that when set the parameter of AT+CTZU to illegal value 2, it would be set and take effect unexpectedly, not fail. Optimized RF TX under non-signaling mode. Updated Telus-Commercial to 0x05800C60. Solved the problem that quectel-gps-handle process taken too much CPU resource and failed to support USB hot plugging. Updated Roger-Commercial_VoLTE to 0x05800D80	R05A05_0 .005.01.008 R05A05_0 .005.01.008 R05A05_0 .005.01.008 R05A05_0 .005.01.008 R05A05_0 .005.01.008
GENERAL GENERAL GENERAL GENERAL	Solved the problem that no URC for manufacturer command when executed AT+CMEE=0. Solved the problem of returned format error when executed AT command AT+CCLK?. Solved the problem that when set the parameter of AT+CTZU to illegal value 2, it would be set and take effect unexpectedly, not fail. Optimized RF TX under non-signaling mode. Updated Telus-Commercial to 0x05800C60. Solved the problem that quectel-gps-handle process taken too much CPU resource and failed to support USB hot plugging. Updated Roger-Commercial_VoLTE to 0x05800D80 Modified the default value of command	R05A05_01.005.005
GENERAL GENERAL GENERAL GENERAL GENERAL	Solved the problem that no URC for manufacturer command when executed AT+CMEE=0. Solved the problem of returned format error when executed AT command AT+CCLK?. Solved the problem that when set the parameter of AT+CTZU to illegal value 2, it would be set and take effect unexpectedly, not fail. Optimized RF TX under non-signaling mode. Updated Telus-Commercial to 0x05800C60. Solved the problem that quectel-gps-handle process taken too much CPU resource and failed to support USB hot plugging. Updated Roger-Commercial_VoLTE to 0x05800D80	R05A05_0′ .005.01.005



OENEDA!	Ontinaina d LIC identificana attina a sasa	R05A05_01
GENERAL	Optimized UE identity reporting process.	.005.01.005
CENEDAL	Inches and the INACI be always protection and about	R05A05_01
GENERAL	Improved the IMEI backup protection mechanism.	.005.01.005
CENEDAL	Solved the problem that AT+QGPSSUPLCA testing failed under the	R05A05_01
GENERAL	mode of MT SMS.	.005.01.005
GENERAL	Improved the etability of Madem	R05A05_01
GENERAL	Improved the stability of Modem.	.005.01.005
GENERAL	Demoved the default value of applied for Verizon	R05A05_01
GENERAL	Removed the default value of appid for Verizon.	.005.01.005
MMS	Improved module stability when executing AT+QMMSEDIT=5,1.	R05A05_01
IVIIVIS	improved module stability when executing AT+QMM3EDIT=3,1.	.005.01.005
MMS	Solved the problem that no error report when the parameter of	R05A05_01
IVIIVIS	AT+QMMSCFG="sendparam" was missing.	.005.01.005
MQTT	Solved the problem that the module could not receive more than 1024	R05A05_01
MGTT	bytes of data sent by the MQTT server.	.005.01.005
MQTT	Corrected the MSG_ID that reported when MQTT sending message	R05A05_01
IVIQII	timeout.	.005.01.005
NETWORK	Added cell blacklist function when RRC access failure reached a	R05A05_01
NETWORK	certain condition.	.005.01.005
NETWORK	Solved the problem that there was no LTE result when executing	R05A05_01
NETWORK	AT+QCOPS=7,0 and AT+QCOPS=4,0.	.005.01.005
NETWORK	Changed the maximum band number that allowed to queried by	R05A05_01
NETWORK	command AT+QCOPS.	.005.01.005
NETWORK	Expanded AT command AT+QNETINFO to query system frame	R05A05_01
NETWORK	number and subframe number.	.005.01.005
NETWORK	Improved the stability when executing AT+QNETINFO=2,2 or	R05A05_01
NETWORK	AT+QNETINFO=2,f with unstable network.	.005.01.005
GENERAL	Solved the problem that AT&T OMADM could not connect DM server	R05A05_01
GENERAL	caused by a failure of SSL handshake.	.005.01.005
GENERAL	Disabled URC auto report features for AT&T OMA by default.	R05A05_01
GENERAL	Disabled ONC auto report realtires for AT&T OlviA by default.	.005.01.005
QMI	Optimized QMI process to avoid stuck QMI message rarely.	R05A05_01
QIVII	Optimized Qivii process to avoid stuck Qivii message rarely.	.005.01.005
TCP SSL	Modified the domain name length of AT+QSSLOPEN from 39 bytes to	R05A05_01
TCP 33L	255 bytes.	.005.01.005
НТТР	Solved the problem of returning +CME ERROR: 702 when executing	R05A05_01
r	AT commands AT+QHTTPPOST and AT+QHTTPPUT.	.005.01.005
TCD/UDD	Optimized the module stability when receiving more than 751 bytes	R05A05_01
TCP/UDP	under TCP hex mode.	.005.01.005
TCD/UDD	Optimized the process when sending UDP data on different destination	R05A05_01
TCP/UDP	port.	.005.01.005
TCD/UDD	Solved the problem that if TCP half-closed, error returned when	R05A05_01
TCP/UDP	executing AT+QISEND=0,0.	.005.01.005



TCP/UDP	Solved the problem of URC reporting error when UDP server	R05A05_01
TCF/ODF	connected to multiple clients.	.005.01.005
TCP/UDP	Supported to report the data length within TCPIP URC reported.	R05A05_01
1017001	oupported to report the data length within 101 in Orto reported.	.005.01.005
TCP/UDP	Solved the problem that when multiple TCP connection was	R05A05_01
1017001	established, it was abnormally to loop QIRD quickly.	.005.01.005
GENERAL	Solved the problem that AT side could not enter into Sleep mode after	R05A05_01
OLIVEIVAL	executing AT+QGPSEND to disable GPS.	.005.01.005
NETWORK	Solved the problem that network status light was not working properly.	R05A05_01
THE TWO IN	Colved the presion that hetwork states light was not working properly.	.005.01.005
AUDIO	Solved the issue that audio settings did not take effect.	R05A04_01
	Convocation to the cause continger and not take officer.	.005.01.005
GENERAL	Solved the issue that no URC reported for manufacturer command	R05A04_01
OLIVERAL	when executed AT+CMEE=0.	.005.01.005
AUDIO	Solved the issue of one parameter was missing when queried via AT	R05A04_01
	command AT+QDAI=?.	.005.01.005
NTP	Solved the problem of one more blank space returning when queried	R05A04_01
	default value via AT+QCFG="NTP".	.005.01.005
GENERAL	Disabled AT command AT+QODM="hostdevice",0 for AT&T.	R05A04_01
OLIVEIVAL	Disabled All Command All Facebras Hostacvice 30 for All all.	.005.01.005
MQTT	Fixed stuck issue when sending/receiving MQTT data in weak signal.	R05A04_01
	Tixed stack loads when senaing/reserving wat I data in weak signal.	.004.01.004
NETWORK	Optimized AT+QCOPS to speed up the execution of this command.	R05A04_01
METWORK	optimized All 140010 to opeda up the excedition of this community.	.004.01.004
NETWORK	Added cell blacklist function when RRC access failure reached a	R05A04_01
	certain condition.	.004.01.004
NETWORK	Extended AT command AT+QCOPS to display multiple band points of	R05A04_01
	a single LTE band in the response result.	.004.01.004
GENERAL	Solved the issue that no response returned for manufacturer command	R05A04_01
OLIVEI (7 KL	when executed AT+CMEE=0.	.004.01.004
NETWORK	Fixed stuck issue when APN settings was set for thousands of times	R05A04_01
NETWORK	without stopping.	.004.01.004
	Fixed the following issues that FTM RX value was incorrect for the first	R05A04_01
GENERAL	time and the RX value was always 0 when entered or exited the factory	.004.01.004
	mode.	
TCP SSL	Fixed the issue that qsslsend&qisend still received data when socket	R05A04_01
. 5. 552	was closed which could cause memory run out.	.004.01.004
MQTT	Fixed the issue that the module would be stuck when AT command	R05A04_01
	AT+QMTPUBEX sent data under the weak signal.	.004.01.004
NETWORK	Fixed the issue that when TCP/UDP connected, the module would run	R05A04_01
14211101111	out of memory when under weak signal.	.004.01.004
	Fixed the issue that when MQTT connection was established in the	R05A04_01
MQTT	SSL mode, if the data delivered by the subscribed topic longer than	.004.01.004
	1024 bytes, the module could not report data.	.007.01.004



NETWORK	Fixed the issue when switching AT+COPS=2 to AT+COPS=0 or AT+COPS=1 would cause the module unable to register the network before IMSI was ready.	R05A04_01 .004.01.004
NETWORK	Fixed the problem that no service got from CEREG/CGREG/CREG while module was actually registering network after executing AT+COPS=2 and AT+COPS=1,2,"plmn".	R05A04_01 .004.01.004
TCP SSL	Modified SSL to support TLS_ECDHE_RSA_WITH_AES_256_GCM_SHA384.	R05A04_01 .004.01.004
NETWORK	Optimized AT command AT+QCOPS to restore band capability after executing this command.	R05A04_01 .004.01.004
NETWORK	Optimized AT command AT+QCOPS to show more LTE cells.	R05A04_01 .004.01.004
NETWORK	Optimized AT command AT+QCOPS to solved issue that executing AT+COPS=0 would cause PPP disconnection.	R05A04_01 .004.01.004
GENERAL	Optimized AT command AT+QDSIM that card slot was 1 under boot Initialization when this command set to an illegal value.	R05A04_01 .004.01.004
TCP/UDP	Optimized AT command AT+QISTATE and AT+QIACT? to display IPV6 address.	R05A04_01 .004.01.004
MQTT	Optimized AT command could subscribe to five topics at the same time at most.	R05A04_01 .004.01.004
NTP/MQTT/FT P	Optimized NTP/MQTT/FTP to support IPV6 connection.	R05A04_01 .004.01.004
GENERAL	Optimized USB enumeration logic.	R05A04_01 .004.01.004
НТТР	Optimized AT command AT+QHTTPSTOP to solve blocked issue.	R05A04_01 .004.01.004
TCP/UDP	Solved the issue that AT command AT+QICLOSE returned for long time when the TCP server return (FIN, ACK) at the same time.	R05A04_01 .004.01.004
NETWORK	Solved the issue that scanning flag was not cleared when executing AT+QCOPS returned error.	R05A04_01 .004.01.004
TCP/UDP	Solved the problem that after the TCP connection successfully established, immediately established the connection with the same parameters again would cause a dump.	R05A04_01
TCP/UDP	Solved the problem that when establishing multiple TCP connection, it would abnormally loop QIRD quickly.	R05A04_01 .004.01.004
AUDIO	Supported new codec nauc8810.	R05A04_01 .004.01.004
AUDIO	Fixed the issue AUDIO related command couldn't be executed when rebooting without codec.	R05A04_01
SMS	Fixed the issue that when under the VERIZON network, it would fail to used AT command AT+QCMGS to send the content with the international number.	R05A04_01 .004.01.004
GENERAL	Included Telus MBN.	R05A04_01



GENERAL	
<u> </u>	R05A04_01 .004.01.004
GENERAL Optimized file system protection mechanism.	R05A04_01 .004.01.004
GENERAL	R05A04_01 .004.01.004
GENERAL Changed response format of AT+CEER to +CEER: -ceause .	R05A04
GENERAL Supported to configure numeric and string code by AT+CEER Default is numeric.	R05A04
GENERAL Extended AT+QCOPS command to support display LTE cell id.	R05A04
Fixed bug that module will be stuck when neighbor cell list is too much for AT+QENG="neighbourcell".	R05A04
Fixed bug that URC of HTTP time out is blocked when socket	R05A04
connection could not be established.	
connection could not be established.	R05A04
HTTP connection could not be established. HTTP Changed maximum time out value to 5000ms to close HTTP socket.	R05A04

5. Known Issues

Item/Category	Brief Description	
/		



6. Functions

Basic Function										
SMS	Voice Call	Data Call	USSD	PHB	CMUX	FILE ¹⁾	FAX	STK		
Υ	Υ	Ν	N	Υ	Υ	Υ	Ν	N		
Protocol Function										
QMI	TCP/ UDP	PPP	FTP	NITZ	NTP	HTTP	PING	TCP SSL		
Υ	Υ	Υ	Υ	Υ	Υ	Υ	Υ	Υ		
MQTT	MMS ²⁾	SMTP	SMTPS	HTTPS						
Υ	Υ	Υ	Υ	Υ						
Special Function										
SIM Detection	DFOTA	DTMF ³⁾	Dual UART	TTS	Quec Locator 2.0 ⁴⁾	DSSS	UAC	LowPower		
Υ	Υ	Υ	Υ	Υ	Υ	Y	Υ	Υ		
RMNET	ECM	RNDIS								
Υ	Υ	Υ								

NOTES

- 1. Y means the firmware supports this function.
- 2. N means the firmware does not support this function.
- 3. 1) Supports RAM FILE only.
- 4. 2) Supports MMS sending only.
- 5. 3) Supports DTMF decoding only.
- 6. ⁴⁾ QuecLocator2.0 is an efficient location technology developed by Quectel, while it's not free, you need pay for it if you would like to use it.
- 7. Verification Environment is shown below. For more details, please contact Quectel technical support.

For Windows,

USB Driver: Quectel_Windows_USB_Driver(Q)_NDIS_V2.7.1

Qflash Tool: QFlash_V6.5

For Linux,

QFirehose Tool: QFirehose_Linux_Android_V1.4.15



USB Driver: Quectel_Linux_USB_Serial_Option_Driver_V1.0 Quectel-CM Tool: Quectel_QConnectManager_Linux_V1.6.5

QLog Tool: Quectel_QLog_Linux&Android_V1.5.19

QMI_WWAN Driver: Quectel_Linux&Android_QMI_WWAN_Driver_V1.2.2

GobiNet Driver: Quectel_Linux&Android_GobiNet_Driver_V1.6.5