

### Product change note

Topic Firmware and hardware update for EVK-M8L, EVK-M8U, C93-M8E

UBX-20029902 C1-Public

Author Martin Wallebohr
Date 6 August 2020

Copying, reproduction, modification or disclosure to third parties of this document or any part thereof is only permitted with the express written permission of u-blox. The information contained herein is provided "as is" and u-blox assumes no liability for its use. No warranty, either express or implied, is given, including but not limited, with respect to the accuracy, correctness, reliability and fitness for a particular purpose of the information. This document may be revised by u-blox at any time. For most recent documents, visit www.u-blox.com. Copyright® u-blox AG.

# 1 Affected products

Order code	Old type no.	New type no.	
EVK-M8L-0	EVK-M8L-0-11	EVK-M8L-0-12	
EVK-M8U-0	EVK-M8U-0-00	EVK-M8U-0-12	
C93-M8E-0	C93-M8E-0-00	No change	

2	Τv	pe

	Product status change	$\boxtimes$	Documentation update
$\boxtimes$	Hardware/component change		Certification information
$\boxtimes$	Firmware/software update		Security advisory
	Label change		Other

## 3 Description

The following table describes the updates on firmware and hardware for each evaluation kit:

Order code	Old firmware	New firmware	Hardware change
EVK-M8L-0	ADR 4.21	ADR 4.31	Timepulse pin added
EVK-M8U-0	UDR 1.21	UDR 1.31	Timepulse pin added
C93-M8E-0	UDR 1.21	UDR 1.31	No change

Details on firmware changes are available in the release notes [1], [2]. The timepulse pin is now available on the front pin connector panel. Specific product documentation is updated and available on u-blox website [3], [4], [5].



Updated products can be identified by a type number on the label which is marked in red on the figure below. Please note that an updated C93-M8E cannot be identified by label but only by reading out firmware version via UBX-MON-VER [6].



### 4 Schedule

Updated parts are available as of the middle of September 2020 and have the new type number printed on the label.

### 5 Customer impact and recommended action

- The new firmware includes several improvements compared to the previous firmware. It is highly recommended to evaluate applications with the latest firmware.
- It is possible to upgrade new firmware manually on the existing evaluation kits.

#### 6 Related documentation

- [1] ADR 4.31 release notes, <u>UBX-20009341</u>
- [2] UDR 1.31 release notes, <u>UBX-20013174</u>
- [3] C93-M8E user guide, <u>UBX-15031067</u>
- [4] EVK-M8U user guide, <u>UBX-15023994</u>
- [5] u-blox M8 receiver protocol specification, <u>UBX-13003221</u>
- [6] ADR 4.31 firmware
- [7] UDR 1.31 firmware