

SCHURTER Inc
 447 Aviation Boulevard
 Santa Rosa, CA 95403

TEL 707 636 3000
 FAX 707 636 3033
 www.schurter.com


Dear Customer,

This letter is to inform you of a temporary change of the nut used for SCHURTER part number 4831.2200.

Due to a material shortage, we will need to temporarily supply an alternate nut for part number 4831.2200.

The fit/function of the nut does not change and will allow customers to continue to use this part in their application.

Please note the difference in form in Figures below.

<u>Original nut:</u>	<u>Alternate nut (mm):</u>								
	 <table border="1" data-bbox="667 1201 1477 1333"> <tr> <td></td> <td></td> <td>(s)</td> <td>(m)</td> </tr> <tr> <td>M4</td> <td>0.5</td> <td>7</td> <td>3.2</td> </tr> </table>			(s)	(m)	M4	0.5	7	3.2
		(s)	(m)						
M4	0.5	7	3.2						
Fig. 1	Fig. 2								

We will issue another statement once the original nut is available again.

Thank you for your understanding.

Best regards,

Nikila Kareesan
 Vice President, Engineering

SCHURTER Inc.