

## 1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PGU	Type				
01	002	010	0000000512	See list below	Fuseholder	FAB	

\*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

List of part numbers affected				
<b>FAB complete</b>				
0031.3551	0031.3551.H	0031.3558		
<b>FAB socket</b>				
0031.3553	0031.3557			
<b>FAB carrier</b>				
0031.3555	0031.3555.G	0031.3556	0031.3556.Z	

## 2 Type of change

Material change

## 3 Reason of change

Product improvement to fulfil the enhanced glow wire requirements according to the updated standard IEC 60127-6 and the standard IEC 60335-1 for appliances in unattended use.

## 4 Release date

The change will be rolled-out starting ww 09/2016 and lasts approx. 3 months depending on the variant.

## 5 Impact of change and recommended action

Form:	No	There are no form changes
Fit:	No	There are no dimensional changes
Function:	No	This is a non-functional change
Production Site:	No	There is no change of the production site
Product Label:	No	There is no product label change
Customer action:	No	Notification only

## 6 Reference Documents / Attachments

Kind of document	Document number	Remarks
<a href="#">Data sheet</a>		

Product Change Notification					PCN FAB		
owner	creation date	release date	released by	change order no	rev	page	0118.2274
import	2015-12-05	2015-12-21	zbindeja	2008801	A	1 of 1	