

PRODUCT CHANGE NOTIFICATION

E-Switch Series/ Part No affected: TL1275 series, all PNs. See list below.	Part /Series Description: Tact Switch
--	---------------------------------------

Affected Process

☒ Assembly
 ☐ Molding
 ☐ Stamping
 ☐ Plating

Change on:

☒ Drawing
 ☒ Process
 ☐ Material
 ☐ Specification
☐ Packaging
 ☐ Tooling Modification
 ☐ New Tooling
 ☐ Manufacturing Location
☐ Others

Reason for change:

1. Improve tensile strength of wire to PCB connection. To prevent wires breaking during handling.
- 2.

Proposed change:

1. Add glue to the PCB to wrap the root of the conductor and the plastic outer covering together



BEFORE



AFTER

Proposed Transition/change over:

This will be a running change. Old inventory will be used up first. There may be mixed inventory in distribution.

☐ Customer Notification

Action Item:
Part numbers affected:

TL1275CA2WA500QPR			
TL1275CA2WA500QPG			
TL1275CA2WA500QPB			
TL1275CA2WA500QPRG			
TL1275CB2WA500QPW			
TL1275CA2WA140QPG			