

## PRODUCT CHANGE NOTIFICATION

Product Category	COPPER PATCHCORDS 20240312-1					
Product Group						
ISSUE DATE:	12-Mar-24					
IMPACTED REGIONS:	✓ NA	✓ EMEA	✓ LATAM	✓ AP		
REASON FOR CHANGE:	✓ DISCONTINI	UATION				
	OTHER					
DESCRIPTION OF						
Panduit is discont	inuing its Pro	finet patch cord off	ering as a result	of limited ma	rket demand.	
There are no direct direct replacements available for this offering.						
IMPACTED PART	•		•			
See Below						
DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:						
			Year	Month	Day	
SCHEDULE FOR CHANGE			(YYYY)	(MM)	(DD)	
New product sample availa	bility date					
Old product discontinuation date*			2024	6	10	

IMPACTED PART			Grouping For	Discontinuation
NUMBERS	Compatibility Type	Replacement Part 1	Complex only	Date
IPR54T1GR1M	No Replacement	NO-REPLACEMENT		10-JUN-2024
IPR54T1GR0.5M	No Replacement	NO-REPLACEMENT		10-JUN-2024
IPD11T1NGR10M	No Replacement	NO-REPLACEMENT		10-JUN-2024
IPR54T1GR20M	No Replacement	NO-REPLACEMENT		10-JUN-2024
IPR54T1GR25M	No Replacement	NO-REPLACEMENT		10-JUN-2024
IPR54T1GR3M	No Replacement	NO-REPLACEMENT		10-JUN-2024
IPR54T1GR7.5M	No Replacement	NO-REPLACEMENT		10-JUN-2024
IPD11T1NGR12M	No Replacement	NO-REPLACEMENT		10-JUN-2024

<sup>\*</sup>Important: A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.