



Last Date of Manufacture of Unchanged Product: 08/05/2024

SQ04-0002 Rev 8

SI8235AB-D-IS1R; SI8235AD-D-IS; SI8235AD-D-ISR; SI8235BA-D-IS1; SI8235BA-D-IS1R; SI8235BB-D-IM; SI8235BB-D-IMR; SI8235BB-D-IS1; SI8235BB-D-IS1R; SI8235BB-D-ISR; SI8235BB-D-YM0R; SI8235BD-D-ISR; SI8235BD-D-YSR; SI8237BD-D-ISR; SI8238AB-D-IS1R; SI8238AD-D-IS; SI8238AD-D-ISR; SI8238BB-D-IS1R; SI8238BB-D-YS1R; SI8238BD-D-ISR; SI8422AB-D-IS; SI8422AB-D-ISR; SI8422AD-D-ISR; SI8422BB-D-IS; SI8422BB-D-ISR; SI8423AB-D-IS; SI8423AD-D-IS; SI8423AD-D-YS0R; SI8423BB-D-ISR; SI8220BB-D-IS; SI8220BB-D-ISR; SI8220BD-D-IS; SI8220CB-D-IS; SI8220DB-D-IS; SI8220DB-D-ISR; SI8221CC-D-IS; SI8230AB-D-IS; SI8230AB-D-IS1; SI8230AB-D-IS1R; SI8230AB-D-ISR; SI8230AC-D-IS1; SI8230AD-D-IS; SI8230AD-D-IS3; SI8230AD-D-ISR; SI8230BB-D-IS; SI8230BB-D-IS1; SI8230BB-D-IS1R; SI8230BB-D-ISR; SI8230BB-D-YS1R; SI8230BC-D-IS1; SI8230BD-D-IS; SI8230BD-D-IS3; SI8230BD-D-ISR; SI8231AB-D-IS; SI8231AC-D-IS1; SI8231BB-D-IS; SI8231BB-D-IS1; SI8231BB-D-IS1R; SI8231BB-D-ISR; SI8231BC-D-IS1; SI8231BD-D-IS; SI8231BD-D-ISR; SI8232AB-D-IS1; SI8232AB-D-IS1R; SI8232AC-D-IS1; SI8232BB-D-IS; SI8232BB-D-IS1; SI8232BB-D-IS1R; SI8232BB-D-ISR; SI8232BC-D-IS1; SI8232BD-D-IS; SI8232BD-D-ISR; SI8233AB-D-IM; SI8233AB-D-IM1; SI8233AB-D-IMR; SI8233AB-D-IS; SI8233AB-D-IS1; SI8233AB-D-IS1R; SI8233AC-D-IS1; SI8233AD-D-IS; SI8233AD-D-IS3; SI8233AD-D-ISR; SI8233BB-D-IM; SI8233BB-D-IM1; SI8233BB-D-IMR; SI8233BB-D-IS; SI8233BB-D-IS1; SI8233BB-D-IS1R; SI8233BB-D-ISR; SI8233BB-D-YS1; SI8233BB-D-YS1R; SI8233BC-D-IS1; SI8233BD-D-IS; SI8233BD-D-IS3; SI8233BD-D-IS3R; SI8233BD-D-ISR; SI8233BD-D-YS; SI8233BD-D-YSR; SI8233CB-D-IMR; SI8234AB-D-IS; SI8234AB-D-IS1; SI8234AB-D-IS1R; SI8234AB-D-ISR; SI8234AC-D-IS1; SI8234AD-D-IS; SI8234AD-D-ISR; SI8234BB-D-IM; SI8234BB-D-IM1; SI8234BB-D-IM1R; SI8234BB-D-IMR; SI8234BB-D-IS; SI8234BB-D-IS1; SI8234BB-D-IS1R; SI8234BB-D-ISR; SI8234BC-D-IS1; SI8234BC-D-IS1R; SI8234BD-D-IS; SI8234BD-D-ISR; SI8235AB-D-IM; SI8235AB-D-IM1; SI8235AB-D-IM1R; SI8235AB-D-IMR; SI8235AB-D-IS; SI8235AB-D-IS1; SI8235AB-D-IS1R; SI8235AC-D-IS1; SI8235AD-D-IS; SI8235AD-D-IS3; SI8235AD-D-ISR; SI8235BA-D-IS1; SI8235BA-D-IS1R; SI8235BB-D-IM; SI8235BB-D-IM1; SI8235BB-D-IM1R; SI8235BB-D-IMR; SI8235BB-D-IS; SI8235BB-D-IS1; SI8235BB-D-IS1R; SI8235BB-D-ISR; SI8235BB-D-YM0R; SI8235BC-D-IS1; SI8235BD-D-IS; SI8235BD-D-IS3; SI8235BD-D-IS3R; SI8235BD-D-ISR; SI8235BD-D-YS; SI8235BD-D-YSR; SI8237AB-D-IS1; SI8237AB-D-IS1R; SI8237AC-D-IS1; SI8237AD-D-IS; SI8237BB-D-IS1; SI8237BB-D-IS1R; SI8237BC-D-IS1; SI8237BD-D-IS; SI8237BD-D-ISR; SI8238AB-D-IS1; SI8238AB-D-IS1R; SI8238AC-D-IS1; SI8238AD-D-IS; SI8238AD-D-IS3; SI8238AD-D-ISR; SI8238BB-D-IS1R; SI8238BB-D-YS1; SI8238BB-D-YS1R; SI8238BC-D-IS1; SI8238BD-D-IS; SI8238BD-D-IS3; SI8238BD-D-IS3R; SI8238BD-D-ISR; SI8241BB-D-IS1; SI8244BB-D-IS1; SI8244BB-D-IS1R; SI8244CB-D-IS1; SI8244CB-D-IS1R; SI8410AD-D-IS; SI8420AD-D-IS; SI8420AD-D-ISR; SI8420BD-D-IS; SI8420BD-D-ISR; SI8421AD-D-IS; SI8421AD-D-ISR; SI8421BD-D-IS; SI8421BD-D-ISR; SI8422AB-D-IS; SI8422AB-D-ISR; SI8422AB-D-YS0R; SI8422AD-D-ISR; SI8422BB-D-ISR; SI8422BD-D-IS; SI8422BD-D-ISR; SI8423AB-D-IS; SI8423AB-D-ISR; SI8423AD-D-IS; SI8423AD-D-YS0; SI8423AD-D-YS0R; SI8423BB-D-IS; SI8423BB-D-ISR; SI8SL8AB-D-IS1; SI8SL8AB-D-IS1R

Method for Identifying Changed Product

Full product change traceability is maintained by: different internal part number

Reason for Change

Qualification of VIS Fab 2 leads to Capacity Improvement

Anticipated Impact on Form, Fit Function, Reliability, Durability, Quality or Safety

No customer impact is anticipated with this change; there is no change to form, fit, function, reliability, durability, quality or safety.

Qualification Plan Summary

Qualification (AEC-Q100) for VIS Fab 2 release passed.

Launch Plan

Upon completion of the notification period or customer approval will be implemented

Please contact your Skyworks customer service representative with any questions or comments regarding this change. If you are unsure whom to contact, please email Skyworks Change Management at Skyworks.CCB@Skyworksin.com .

Skyworks Solutions, Inc.

20 Sylvan Road, Woburn, MA 01801

USA: (781) 376-3000 • Asia: 886 2 2735 0399

Europe: 33 (0)1 43548540 • Fax: (781) 376-3300

On the Web: www.skyworksin.com