PRODUCT CHANGE NOTIFICATION

Product Category	COPPER CONNECTORS	**20231219-1**
Product Group	ENTERPRISE CONNECTIVITY	
ISSUE DATE:	19-Dec-23	

IMPACTED REGIONS: ☑ NA ☑ EMEA ☑ LATAM ☑ AP

REASON FOR CHANGE: ☑ DISCONTINUATION
☐ OTHER

DESCRIPTION OF CHANGE: (Required)

The FPE6X88MTG-X ten pack PROFINET Field Terminable Plug is being discontinued due to low volume. Customers should move requirements for the ten-pack to the single-piece pack, FPE6X88MTG instead.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

Reference Page 2 / Linked PDF

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2023	12	19
Old product discontinuation date*	2024	3	18

*Important: A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

Product Groups

CABLE COPPER, FIBER CABLE AND CONNECTORS

CONVERGED INFRASTRUCTURE

COPPER & NETKEY COPPER, FIBER, CABLE

DATA CENTER SOFTWARE

DC CONNECTIVITY

DUCT AND ABRASION

ID, SAFETY AND ACCESSORIES

IMS SMARTZONE HARDWARE

INDUSTRIALNET COPPER

INDUSTRIALNET FIBER

INDUSTRIALNET OUTLETS

IOT SOFTWARE

IOT SOLUTIONS

MISC

OUTLETS, SURFACE RACEWAY, RACKS, ZONE, CABLE MANAGEMENT

POWER CONNECTORS, GROUNDING AND STEEL

PRE-CONFIGURED IA

TIES AND TERMINALS

IMPACTED PART NUMBER(s)	Compatibility Type	Replacement Part 1
FPE6X88MTG-X	Direct	FPE6X88MTG

Replacement Part 2	Grouping (For Complex only)	Discontinuation Date
		18-MAR-2024

Replacement Type Definition

DIRECT REPLACEMENT

Exact same part in a different pa
has any other update that doesn
product itself

COMPATIBLE

The replacement part is differen
allows it to be used for some ap
it is not the same part. The diff
in color, size, material, or perfo
CAT5 to CAT6), etc

COMPLEX

The replacement part(s) are too
assume it can easily replace the
part, however Panduit ca
replacement which may be us
applications. Customer Experie
contacted.

NO REPLACEMENT

No replacement product is

ackage size, or
n't change the

nt in a way that
plications, but
erence can be
ormance (like

o dissimilar to
e discontinued
n offer a
sed in certain
nce should be

available.