PRODUCT CHANGE NOTIFICATION

Product Category	COPPER PATCHCORDS	**20240325-1**
Product Group	ENTERPRISE CONNECTIVITY	
ISSUE DATE:	25-Mar-24	

IMPACTED REGIONS: ☑ NA ☑ EMEA ☑ LATAM ☑ AP

REASON FOR CHANGE: ☑ DISCONTINUATION
☐ OTHER

DESCRIPTION OF CHANGE: (Required)

Panduit is discontinuing the RPDSCN. Responding to our customers' needs, we are pleased to inform that the RapidID application now supports compatibility with select third-party scanners through both Bluetooth and wired connectivity.

For detailed information on compatible third-party scanners, see Third-Party Scanner Guide: https://www.panduit.com/content/dam/panduit/en/website/products/rapidid/documents/scanner-guide-cofl54-ww-eng.pdf

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2024	6	23

*Important: A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

PART NUMBER	Compatibility Type	Replacement Part 1	Replacement Part 2	Grouping (For Complex only)	Discontinuation Date
RPDSCN	No Replacement	NO-REPLACEMENT			23-JUN-2024