



TE Connectivity

Product Change Notification: E-17-009791 PCN Date: 10-JUL-17

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Obsolescence of MIL-LT heat shrink tubing product family.

Description of Changes

The following part numbers are being obsoleted (obsolete status). If there are suggested TE Connectivity substitute part numbers or alternate part numbers, they are shown below with any significant difference described. Please verify that all substitute or alternate part numbers provided below are suitable for your specific application. Replacement parts will be from the VERSAFIT product family. Other attachments:

Superseding of MIL- LT tubing with Versafit tubing

MIL-LT-PCN affected parts.

Reason for Changes:				
Discontinuance. Dear Customer, You are receiving this notice because TE Connectivity has record of you purchasing a part or multiple parts on the list below. Within our continued efforts to manage/ optimize our product portfolio throughout the lifecycle, we've made the decision to obsolete the parts stated thereafter.				
Estimated Dates:				
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):			
07-SEP-2017				
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):			
02-NOV-2017	No Mixed Shipments			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
573577-000	YES			"2-1194553-0", "MIL- LT-3/8-0-FSP"	5515694001		DUPLICATE PART NUMBER ASSIGNED
<u>573577-000</u>	YES			"2-1194553-0", "MIL- LT-3/8-0-FSP"	5515694001		DUPLICATE PART NUMBER ASSIGNED
700613400 3	YES			"600130700A", "1448222-1", "MIL-LT-1/4-0-SP"	5058744001		No Form, Fit, Function change.
700613400 3	YES			"600130700A", "1448222-1", "MIL -I T-1/4-0-SP"	5058744001		No Form, Fit, Function change.
869419400 3	YES			"7-1196767-6", "MIL- LT-3/64-0-SP"	3813914003		No Form, Fit, Function change.
869419400 3	YES			"7-1196767-6", "MIL- LT-3/64-0-SP"	3813914003		No Form, Fit, Function change.

Part Number(s) being Modified:

· artifambel(e) being meaning							
Part	Part Discontinued	Customer	Customer Part	Alias Part Number(s)	Substitute Part	Substitute Alias	Description Of
Number	per PCN	Drawing	Number	Alias Fait Nulliber(s)	Number	Part Number(s)	Difference
573577-000	YES			"2-1194553-0", "MIL-	5515694001		DUPLICATE PART
				LT-3/8-0-FSP"			NUMBER ASSIGNED
7006134003	YES			"600130700A", "1448222-1",	5058744001		No Form, Fit, Function
				"MIL-LT-1/4-0-SP"	3036744001		change.
8694194003	YES	res established		"7-1196767-6", "MIL-	0040044006		No Form, Fit, Function
			LT-3/64-0-SP"	3813914003		change.	

Part Number(s) being Modified:

Part	Part Discontinued	Customer	Customer Part	Alias Part Number(s)	Substitute Part	Substitute Alias	Description Of
Number	per PCN	Drawing	Number	Alias Part Number(s)	Number	Part Number(s)	Difference
573577-000	YES			"2-1194553-0", "MIL-	5515694001		DUPLICATE PART
			LT-3/8-0-FSP"			NUMBER ASSIGNED	
7006134003	YES			"600130700A", "1448222-1",	5058744001		No Form, Fit, Function
				"MIL-LT-1/4-0-SP"			change.
8694194003	YES	YES		"7-1196767-6", "MIL-	0040044006		No Form, Fit, Function
			LT-3/64-0-SP"	3813914003		change.	