

## Product Discontinuity Notice

ISP130301\_BM\_BL\_PDN\_v1.0

Device affected	Package code
ISP130301-BM ISP130301-BL	All versions

Date (YYYY-MM-DD)	PDN reference	Document version
2021-04-01	ISP130301_PDN	1.0

### Reason for discontinuity

Several components and materials required for module manufacturing are discontinued.

### Last order date

2021-10-01

### Last shipping date

2022-04-01

### Alternative solution for customer

Re-design the application with newer module generation which are smaller and compliant for power supply, IOs, integrated antenna design rules and firmware.

### Approvals

Quality Director:  
Chris Barratt

Date:  
2021-04-01

Signature:



Operation Manager:  
Philippe Genin

Date:  
2021-04-01

Signature:

