

## **4M Change Notice**

LBAD0XX1SC/ LBAD0XX1WG/ LBAD0ZZ1SE Series

Dear. Valued Customer

Thank you very much for your great and continued support for business with Murata.  
This is the official notification that some of our products' 4M Change will be proceeded as detailed below.  
Please review this, and approve in writing by Approval Due Date.  
Your understanding and support are highly appreciated.

### **1. Product Type, Changes, and Customer/Murata/Alternative Part Numbers:**

Product Type: LBAD0XX1SC/ LBAD0XX1WG/ LBAD0ZZ1SE Series

Changes: ☐ Man ☐ Machine ☒ Material ☐ Method

	Before	After
TCXO	(Internal IC Fab) : AKM-Miyazaki	(Internal IC Fab) : Renesas-Naka
Flash Memory	Micron : MT25QU128	Micron : MT25QU128 Winbond : W25Q128

Please refer to the attached documents for detailed Part Numbers' information.

### **2. Reasons/Background:**

TCXO : Due to the fire at AKM in Oct/2020, supplier cannot get IC from original fab AKM.

Flash Memory : Due to critical semiconductor supply situation, we additionally certify Winbond.

### **3. Products Before and After the Change:**

There is no spec change on product datasheet.

### **4. Approval Due:**

**Sep., 20, 2021**

Please review this, and reply to Sales for this Notice in writing by Due Date.

### **5. Change Schedule:**

Production Start in New Factory: Oct. 15, 2021~

Last Shipment Date in Current Factory: Oct. 15, 2021

### **6. Contact Window:**

Should you have any questions or concerns,  
please contact Murata Sales, Representative, or Distributor in your area.

Truly Yours. Thank you.

Murata Manufacturing, Co., Ltd.

Date: (MM, DD, YYYY)

Murata  
Part Number

---

LBAD0ZZ1SE-743