



## Product Change Notification / ASER-16TWXJ161

---

**Date:**

16-Aug-2021

**Product Category:**

Wireless Modules

**PCN Type:**

Manufacturing Change

**Notification Subject:**

CCB 4399 Final Notice: Implement MSL 2 for selected Atmel ATA535x and ATA835x device families available in 33L FCBGA (4.5x4.5x1.1mm) package.

**Affected CPNs:**

[ASER-16TWXJ161\\_Affected\\_CPN\\_08162021.pdf](#)  
[ASER-16TWXJ161\\_Affected\\_CPN\\_08162021.csv](#)

**Notification Text:****PCN Status:**

Final notification

**PCN Type:**

Manufacturing Change

**Microchip Parts Affected:**

Please open one of the files found in the Affected CPNs section.

NOTE: For your convenience Microchip includes identical files in two formats (.pdf and .xls).

**Description of Change:**

Implement MSL 2 for selected Atmel ATA535x and ATA835x device families available in 33L FCBGA (4.5x4.5x1.1mm)

package.

**Pre and Post Change Summary:**

|                                     | Pre Change        | Post Change       |
|-------------------------------------|-------------------|-------------------|
| Assembly Site                       | ASE Inc.<br>(ASE) | ASE Inc.<br>(ASE) |
| Moisture Sensitivity Level<br>(MSL) | MSL 3             | MSL 2             |

**Impacts to Data Sheet:**

None

**Change Impact:**

None

**Reason for Change:**

To improve productivity by qualifying assembly at MSL2 classification.

**Change Implementation Status:**

In Progress

**Estimated First Ship Date:**

August 20, 2021 (date code: 2134)

NOTE: Please be advised that after the estimated first ship date customers may receive pre and post change parts.

**Time Table Summary:**

|                               | August 2021 |    |    |    |    |
|-------------------------------|-------------|----|----|----|----|
| Workweek                      | 32          | 33 | 34 | 35 | 36 |
| Qual Report Availability      |             |    | X  |    |    |
| Final PCN Issue Date          |             |    | X  |    |    |
| Estimated Implementation Date |             |    | X  |    |    |

**Method to Identify Change:**

Traceability code

**Qualification Report:**

Please open the attachments included with this PCN labeled as PCN\_#\_Qual\_Report.

**Revision History:**

**August 16, 2021:** Issued final notification.

The change described in this PCN does not alter Microchip's current regulatory compliance regarding the material content of the applicable products.

## **Attachments:**

[PCN\\_ASER-16TWXJ161\\_Qual\\_Report.pdf](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

## **Terms and Conditions:**

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

ATA8350-7MQW

ATA8352-7MQW

ATA5350-7MQW-VAO

ATA5351-7MQW-VAO

ATA5352-7MQW-VAO