

## Product Change Notice

Issue Date: 17-April-2023

**Change Description:**

Introduction of new lead frame source

**Parts Affected:**

ASCB-RTC2-0A207  
ASCB-RTCC-0A207  
ASCB-JTC2-0A208  
ASCB-JTC2-0A308  
ASCB-RTF2-0A207  
ASCB-RTF2-0A307

**Description and Extent of Change:**

Change of new lead frame source with minor change of bottom view appearance and soldering terminal dimension.


**Reasons for Change:**

To ensure continuity of supply.


**Effect of Change on Fit, Form, Function, Quality, or Reliability:**

There is a change of fit and form but no change in function, quality and reliability of the final product. The new and existing appearance as per below:


Part numbers : ASCB-RTC2-xxxxx/ASCB-RTCC-xxxxx



Part numbers : ASCB-RTF2-xxxxx



Part numbers : ASCB-JTC2-xxxxx



**Effective Date of Change:**

Parts with above change will commence 30 days after issuance date above.

**Qualification Data:**

No change in reliability performance. Reliability data will be available upon request.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please acknowledge the receipt of the notice within 30 days of delivery. Lack of acknowledgement within 30 days constitutes acceptance of the change per JEDEC J-STD-046.