

☒ Approved☐ Rejected

Engineering Change Notice

| ECN Number: 2330x | Originator: ZH | Implementation Date: 5/25/2022 | | | | | | |
|--|---|---|----------|-----|-------------|-------------|--------------------|-------------|
| Release Level: <input checked="" type="checkbox"/> Production <input type="checkbox"/> Deviation | Product Number(s): Sharp 4.4"-06, JDI 4.4"-06 | | | | | | | |
| Change Type: <input checked="" type="checkbox"/> BOM <input checked="" type="checkbox"/> Process | <input checked="" type="checkbox"/> Design <input type="checkbox"/> Document | <input type="checkbox"/> Cost Savings <input checked="" type="checkbox"/> Vendor | | | | | | |
| <u>Reason for Change:</u> Improve FLP quality and validate dimensional accuracy of drawings per production product. | | | | | | | | |
| <u>Change Description:</u> The supplier for a component in the FLP has changed. The film component from the new supplier is the same material but is thicker, resulting in a slight increase in overall product thickness. Testing has shown this change to minimally impact FLP environmental and optical performance. Dimensions to the lightbar also changed to more accurately reflect production product. | | | | | | | | |
| <u>Products Affected:</u> <table border="0"><thead><tr><th>Previous</th><th>New</th></tr></thead><tbody><tr><td>12561-06_T3</td><td>12561-06_T4</td></tr><tr><td>12567-06_T3_prelim</td><td>12567-06_T3</td></tr></tbody></table> | | | Previous | New | 12561-06_T3 | 12561-06_T4 | 12567-06_T3_prelim | 12567-06_T3 |
| Previous | New | | | | | | | |
| 12561-06_T3 | 12561-06_T4 | | | | | | | |
| 12567-06_T3_prelim | 12567-06_T3 | | | | | | | |