

## Product Discontinuation Notice

Issue Date  
March, 2023

### Product Discontinuation

Vision sensor



**FQ-M series**



### Recommended Replacement

Vision sensor

**FHV7 series**

#### [ Final order entry date ]

The end of March, 2024

#### [ Date of The Last Shipping ]

The end of April, 2024

#### [ Scheduled date of maintenance close ]

The end of March, 2029

#### [ Caution on recommended replacement ]

Please replace a whole system.

Please contact our sales representative for details of recommended alternatives.

#### [ Difference from discontinued product ]

Recommended replacement Model	Body Color	Dimensions	Wire connection	Mounting Dimensions	Characteristics	Operation ratings	Operation methods
FHV7 series	--	--	--	--	--	--	--

\*\* : Compatible

\* : The change is a little/Almost compatible

-- : Not compatible

- : No corresponding specification


Product discontinuation	Recommended replacement	Product discontinuation	Product discontinuation
FQ-MD30	FHV7 series Please contact our sales representative for details.	FQ-MWD005	FHV7 series Please contact our sales representative for details.
FQ-MD31		FQ-MWD010	
FQ-MS120		FQ-MWDL005	
FQ-MS120-ECT		FQ-MWDL010	
FQ-MS120-M		FQ-MWNE005	
FQ-MS120-M-ECT		FQ-MWNE010	
FQ-MS125		FQ-MWNEL005	
FQ-MS125-ECT		FQ-MWNEL010	
FQ-MS125-M		FQ-MWNL005	
FQ-MS125-M-ECT		FQ-MWNL010	

#### [ Product Discontinuation and recommended replacement ]

# [ System configuration ]

## Product discontinuation FQ-M series


### EtherCAT connections



\*1. Sysmac Studio and Touch Finder can not be used together. When both are connected, Sysmac Studio will have a priority. When you make NJ/NX/NY controller settings with the Sysmac Studio Standard Edition, connect a computer and the controller via a USB connection or an Ethernet network.

\*2. Industrial PC Platform NY-series IPC Machine Controller only.


### No-protocol Ethernet and PLC Link Connections



\* Sysmac Studio and Touch Finder can not be used together. When both are connected, Sysmac Studio will have a priority.

- Note:**
1. EtherCAT and Ethernet (PLC Link) can not be used simultaneously.
  2. It is not possible to configure and adjust the FQ-M via an NJ/NX/NY controller, when they are connected via an EtherCAT network. For configuration and adjustment of FQ-M, connect the FQ-M and a computer or a Touch Finder via an Ethernet network.

Sysmac is a trademark or registered trademark of OMRON Corporation in Japan and other countries for OMRON factory automation products. Windows is registered trademarks of Microsoft Corporation in the USA and other countries. EtherCAT® is registered trademark and patented technology, licensed by Beckhoff Automation GmbH, Germany. Other company names and product names in this document are the trademarks or registered trademarks of their respective companies.



Specifications and prices in this product news are as of the issue date and are subject to change without notice. Only main changes in specifications are described in this document. Please be sure to read the relevant catalogs, datasheets, product specifications, instructions, and manuals for precautions and necessary information when using products.