

PRODUCT CHANGE NOTIFICATION

Product Category LABELING SYSTEMS 20230505-1

Product Group ID AND SAFETY

ISSUE DATE: 5-May-23

IMPACTED REGIONS: ☒ NA ☒ EMEA ☒ LATAM ☒ AP

REASON FOR CHANGE: ☒ DISCONTINUATION
☐ OTHER

DESCRIPTION OF CHANGE: (Required)

Part numbers T100X000VSC-BK and T100X000VSC-WH will be discontinued.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2023	5	5
Old product discontinuation date*	2023	8	3

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)	Compatibility Type	Replacement Part 1	Replacement Part 2
T100X000VSC-BK	Compatible	T100X000VPC-BK	
T100X000VSC-WH	Complex	T100X000BSM-WH	MP300