



Product Name:	HPL 569 - Dsub	
	D-Sub Accessories	
Product Manager:	Renish Baby	
Subject:	Notification of Change with Immediate Effectivity	
Distribution:	Affected customers	
Type of Change:	Documentation Change	
Change Description:	<p>D-Sub Accessories, Lock washer dimension update in customer drawing. No change in actual part.</p> <div style="display: flex; justify-content: space-around;"> <div style="text-align: center;"> <p>Before Change</p>  <p>Lock washer thickness : 1.20 ± 0.10</p> </div> <div style="text-align: center;"> <p>After Change</p>  <p>Lock washer thickness : 1.00 ± 0.10</p> </div> </div>	
Reason for Change:	Documentation error correction. Change to match the thickness of lock washer in drawing with the actual part.	
Affected Parts:	See Affected parts.xls file	
Effective Date of Change:	June,27 2023	
Last Time Buy Date:		
Earliest Disty Return Date:		
Last Time Shipment Date		
Datasheet Attached?	No	
Qual/Test Data Attached?	No	
Samples Availability Date:	27 June ,2023	
Available Alternatives?		
Questions?	<p>Contact your local ACS Representative, or Product Manager</p> <p>Renish Baby / Product Manager</p> <p>Renish.Baby@fci.com</p>	

Note:

Customers should contact Product Line Manager (or their local Amphenol Representative) directly regarding any concern on the PCN.
Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .