

Before Picture

Overview

 Molex management wanted immediate obsolescence as below part can no longer be produced due to "Our supplier has discontinued this product. It is not economical to look for a replacement."

Part Number Impact

- See attached impacted parts list
- Replacement for this part
 - No Replacement
- Please refer to above for LTB and LTS date.

For assets that are customer owned, the owner has 90 days after the last time ship date to claim the tooling."

You may address inquires regarding this PCN by clicking on the below link mailto:pcn_coordinator@molex.com?subject=PCN_Notification:512674 or contact your Local Sales Engineer.

Note: While responding, please retain " PCN Notification : **PCN Notification**: **512674** " in the e-mail Subject line for faster response.

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL (800) 786-6539 www.molex.com

[&]quot;After the last time ship date, Molex will no longer manufacture the products included within this notification and all related tooling will be decommissioned.

PCN No Part List

512674 <u>1731140161</u>