

ı.

1 Products affected

Product hierarchy no. *			chy no. *	Part no.	SBU	Product Type	Customer part no.
SBU	PG	PUG	Type				
02	007	060	0000002302	See list/appendix below	Connectors	4750	-

^{*}SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

List of part number	ers affected for type <4	1750>		
3-135-278	3-135-539	3-135-541	3-128-802	3-135-293
3-135-553	3-135-296			

2 Type of change

• Change of material

3 Detailed description of change

Current product appearance	New product appearance
Color of gray products RAL7040	Color of gray products RAL7035
Color of white products RAL9016	Color of white products RAL9006

4 Reason of change

Due to Material shortage, change to new plastic raw material to secure availability.

5 Release date

The change takes effect in ww 32/2023 (Date code 2332 or higher on label). Parts on stock will be used upon depletion.

6	Impact	of	change	and	recommended	l actior
---	--------	----	--------	-----	-------------	----------

	Form	
\boxtimes	Fit	Slight change of colour
	Function	
	Manufacturing	
	Label	
	Packaging	

7 Reference Documents

Kind of document	Document Title
Data Sheet	Data Sheet 4750

Product Change Notification						PCN 4750 Change of material		
owner	creation date	release date	released by	change order	rev	page	D40 070 404	
mansurva	16.06.2023	22.06.2023	muehlema	2026271	В	1 of 1	D10-070-494	