

Product Name:	HPL - 556 - DIN		
	DIN Solder Eyelet Receptacle		
Product Manager:	Babu Jibu		
Subject:	Notification of Change with Immediate Effectivity		
Distribution:	Affected Customers		
Type of Change:	End-of-Life		
Change Description:	Discontinuation of DIN Solder Eyelet Connector part numbers.		
Reason for Change:	Wornout Tools, High manufacturing cost and Lack of orders does not justify cotinued offering.		
Affected Parts:	As per list attached		
Effective Date of Change:	July,31 2023		
Last Time Buy Date:	July,15 2023		
Earliest Disty Return Date:			
Last Time Shipment Date			
Datasheet Attached?	NA		
Qual/Test Data Attached?	NA		
Samples Availability Date:			
Available Alternatives?			
Questions?	Contact your local ACS Representative, or Product Manager		
	Babu Jibu / Product Manager		
	Jibu.Babu@fci.com		

Note:

Customers should contact Product Line Manager (or their local Amphenol Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .