



Product Change Notification

PCN # 107602

Issued Date: 23-Jun-23

Issued By: Jason Yost

Author: Jason Yost

Change affects whole product family?

No

Part #'s affected (See attached if entire product family is affected)

5130101604 and 5130601604

Description of Change:

Discontinue

Reason for Change:

Vendor of subcomponent increased minimum order quantity requirements beyond what could be justified to maintain the product as active for production

Properties of Old vs. Changed Product:

Obsolete

Disposition of Old Product:

Fill as many backorders as possible with current inventory of raw materials.

Expected Implementation Date: 6/23/2023

Customer Feedback Expected by: N/A

Additional Comments: (Include Potential Risks if Appropriate)

Supporting Qualification Data:

Attached as necessary

Dialight North America

1501 Route 34 South | Farmingdale | New Jersey | 07727 | USA | Tel: 732-919-3119 | www.dialight.com



Dialight North America

1501 Route 34 South | Farmingdale | New Jersey | 07727 | USA | Tel: 732-919-3119 | www.dialight.com