

PRODUCT CHANGE NOTIFICATION

Product Category LOOSE PIECE CABLE TIES **20230620-1**

Product Group PLASTIC CABLE TIES

ISSUE DATE: 20-Jun-23

IMPACTED REGIONS: ☒ NA ☒ EMEA ☒ LATAM ☒ AP

REASON FOR CHANGE: ☒ DISCONTINUATION
☐ OTHER

DESCRIPTION OF CHANGE: (Required)

Discontinuation of Hot Stamp parts.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*			

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBERS	Compatibility Type	Replacement Part	Discontinuation Date
BM4S-P172-C	No Replacement	No Replacement	03-JUL-2023
BT2LH-P398-TL0	No Replacement	No Replacement	03-JUL-2023
BT2S-P123A-M1	No Replacement	No Replacement	03-JUL-2023
BT2S-P123A-M2	No Replacement	No Replacement	03-JUL-2023
BT2S-P123B-M1	No Replacement	No Replacement	03-JUL-2023
BT2S-P123B-M2	No Replacement	No Replacement	03-JUL-2023
BT2S-P123C-M0	No Replacement	No Replacement	03-JUL-2023
BT2S-P123C-M1	No Replacement	No Replacement	03-JUL-2023
BT2S-P123C-M2	No Replacement	No Replacement	03-JUL-2023
BT2S-P123C-M4Y	No Replacement	No Replacement	03-JUL-2023
BT2S-P123C-M6	No Replacement	No Replacement	03-JUL-2023
BT2S-P123D-M1	No Replacement	No Replacement	03-JUL-2023
BT2S-P123D-M2	No Replacement	No Replacement	03-JUL-2023
BT2S-P123E-M1	No Replacement	No Replacement	03-JUL-2023
BT2S-P123E-M2	No Replacement	No Replacement	03-JUL-2023
BT2S-P123F-M1	No Replacement	No Replacement	03-JUL-2023
BT2S-P123F-M2	No Replacement	No Replacement	03-JUL-2023
BT2S-P123G-M1	No Replacement	No Replacement	03-JUL-2023
BT2S-P123G-M2	No Replacement	No Replacement	03-JUL-2023
BT2S-P123H-M1	No Replacement	No Replacement	03-JUL-2023
BT2S-P123H-M2	No Replacement	No Replacement	03-JUL-2023
BT2S-P123I-M1	No Replacement	No Replacement	03-JUL-2023
BT2S-P123I-M2	No Replacement	No Replacement	03-JUL-2023
BT2S-P123J-M0	No Replacement	No Replacement	03-JUL-2023
BT2S-P123J-M1	No Replacement	No Replacement	03-JUL-2023
BT2S-P123J-M2	No Replacement	No Replacement	03-JUL-2023
BT2S-P123J-M4Y	No Replacement	No Replacement	03-JUL-2023
BT2S-P123J-M5	No Replacement	No Replacement	03-JUL-2023
BT2S-P123J-M6	No Replacement	No Replacement	03-JUL-2023
BT2S-P123K-M0	No Replacement	No Replacement	03-JUL-2023
BT2S-P123K-M1	No Replacement	No Replacement	03-JUL-2023
BT2S-P123K-M2	No Replacement	No Replacement	03-JUL-2023
BT2S-P123K-M4Y	No Replacement	No Replacement	03-JUL-2023
BT2S-P123K-M5	No Replacement	No Replacement	03-JUL-2023
BT2S-P123K-M6	No Replacement	No Replacement	03-JUL-2023
BT2S-P123-M0	No Replacement	No Replacement	03-JUL-2023
BT2S-P123-M1	No Replacement	No Replacement	03-JUL-2023
BT2S-P123-M2	No Replacement	No Replacement	03-JUL-2023
BT2S-P123-M4Y	No Replacement	No Replacement	03-JUL-2023
BT2S-P123-M5	No Replacement	No Replacement	03-JUL-2023
BT2S-P123-M6	No Replacement	No Replacement	03-JUL-2023
BT2S-P316-M	No Replacement	No Replacement	03-JUL-2023
BT2S-P392A-M6	No Replacement	No Replacement	03-JUL-2023
BT2S-P392B-M6	No Replacement	No Replacement	03-JUL-2023

BT2S-P392C-M6	No Replacement	No Replacement	03-JUL-2023
BT2S-P392-M6	No Replacement	No Replacement	03-JUL-2023
BT2S-P394A-M0	No Replacement	No Replacement	03-JUL-2023
BT2S-P394B-M0	No Replacement	No Replacement	03-JUL-2023
BT2S-P394B-M4Y	No Replacement	No Replacement	03-JUL-2023
BT2S-P394C-M5	No Replacement	No Replacement	03-JUL-2023
BT2S-P394D-M0	No Replacement	No Replacement	03-JUL-2023
BT2S-P394D-M4Y	No Replacement	No Replacement	03-JUL-2023
BT2S-P394E-M0	No Replacement	No Replacement	03-JUL-2023
BT2S-P394E-M6	No Replacement	No Replacement	03-JUL-2023
BT2S-P394F-M0	No Replacement	No Replacement	03-JUL-2023
BT2S-P394F-M4Y	No Replacement	No Replacement	03-JUL-2023
BT2S-P394G-M0	No Replacement	No Replacement	03-JUL-2023
BT2S-P394H-M4Y	No Replacement	No Replacement	03-JUL-2023
BT2S-P394I-M0	No Replacement	No Replacement	03-JUL-2023
BT2S-P394I-M4Y	No Replacement	No Replacement	03-JUL-2023
BT2S-P71-M3	No Replacement	No Replacement	03-JUL-2023
MP350-P15-M	No Replacement	No Replacement	03-JUL-2023
PL2M2S-P753A-D4Y	No Replacement	No Replacement	03-JUL-2023
PL3M2S-P308-D	No Replacement	No Replacement	03-JUL-2023
PL3M2S-P327-D	No Replacement	No Replacement	03-JUL-2023
PL3M2S-P327-L	No Replacement	No Replacement	03-JUL-2023
PL3M2S-P341-D	No Replacement	No Replacement	03-JUL-2023
PLF1MA-P19-M4Y	No Replacement	No Replacement	03-JUL-2023
PLF1MA-P225-M4Y	No Replacement	No Replacement	03-JUL-2023
PLF1MA-P234-M4Y	No Replacement	No Replacement	03-JUL-2023
PLF1MA-P28-M4Y	No Replacement	No Replacement	03-JUL-2023
PLF1MA-P325-M4Y	No Replacement	No Replacement	03-JUL-2023
PLF1MA-P337A-M6	No Replacement	No Replacement	03-JUL-2023
PLF1MA-P337B-M5	No Replacement	No Replacement	03-JUL-2023
PLF1MA-P45-M2	No Replacement	No Replacement	03-JUL-2023
PLF1M-P378-M3	No Replacement	No Replacement	03-JUL-2023
PLF1M-P46-M0	No Replacement	No Replacement	03-JUL-2023
PLF1M-P4A-M	No Replacement	No Replacement	03-JUL-2023
PLF1M-P4B-M	No Replacement	No Replacement	03-JUL-2023
PLF1M-P939-M6	No Replacement	No Replacement	03-JUL-2023
PLM1M-P198A-C4Y	No Replacement	No Replacement	03-JUL-2023
PLM1M-P198B-C6	No Replacement	No Replacement	03-JUL-2023
PLM1M-P198D-C	No Replacement	No Replacement	03-JUL-2023
PLM1M-P227A-M3	No Replacement	No Replacement	03-JUL-2023
PLM1M-P319A-M6	No Replacement	No Replacement	03-JUL-2023
PLM1M-P319B-M	No Replacement	No Replacement	03-JUL-2023
PLM1M-P319C-M	No Replacement	No Replacement	03-JUL-2023
PLM2M-P157A-M	No Replacement	No Replacement	03-JUL-2023
PLM2M-P157B-C	No Replacement	No Replacement	03-JUL-2023
PLM2M-P157-M	No Replacement	No Replacement	03-JUL-2023
PLM2M-P179A-C4Y	No Replacement	No Replacement	03-JUL-2023

PLM2M-P939A-M6	No Replacement	No Replacement	03-JUL-2023
PLM2S-P107A-D	No Replacement	No Replacement	03-JUL-2023
PLM2S-P107B-D	No Replacement	No Replacement	03-JUL-2023
PLM2S-P107C-D	No Replacement	No Replacement	03-JUL-2023
PLM2S-P107D-D	No Replacement	No Replacement	03-JUL-2023
PLM2S-P107E-D	No Replacement	No Replacement	03-JUL-2023
PLM2S-P107F-D	No Replacement	No Replacement	03-JUL-2023
PLM2S-P107G-D	No Replacement	No Replacement	03-JUL-2023
PLM2S-P107I-D	No Replacement	No Replacement	03-JUL-2023
PLM2S-P235-D0	No Replacement	No Replacement	03-JUL-2023
PLM2S-P298-D4Y	No Replacement	No Replacement	03-JUL-2023
PLM2S-P310-D	No Replacement	No Replacement	03-JUL-2023
PLM2S-P310-D2	No Replacement	No Replacement	03-JUL-2023
PLM2S-P310-D4Y	No Replacement	No Replacement	03-JUL-2023
PLM2S-P310-D6	No Replacement	No Replacement	03-JUL-2023
PLM2S-P340A-D4Y	No Replacement	No Replacement	03-JUL-2023
PLM2S-P340B-D4Y	No Replacement	No Replacement	03-JUL-2023
PLM2S-P340C-D4Y	No Replacement	No Replacement	03-JUL-2023
PLM2S-P340D-D4Y	No Replacement	No Replacement	03-JUL-2023
PLM2S-P340E-D4Y	No Replacement	No Replacement	03-JUL-2023
PLM2S-P358-D	No Replacement	No Replacement	03-JUL-2023
PLM2S-P35-D4Y	No Replacement	No Replacement	03-JUL-2023
PLM2S-P383A-D	No Replacement	No Replacement	03-JUL-2023
PLM2S-P383B-D	No Replacement	No Replacement	03-JUL-2023
PLM2S-P383-D	No Replacement	No Replacement	03-JUL-2023
PLM2S-P388A-D4Y	No Replacement	No Replacement	03-JUL-2023
PLM2S-P388B-D4Y	No Replacement	No Replacement	03-JUL-2023
PLM2S-P388-D4Y	No Replacement	No Replacement	03-JUL-2023
PLM2S-P80A-D2	No Replacement	No Replacement	03-JUL-2023
PLM2S-P80B-D	No Replacement	No Replacement	03-JUL-2023
PLM2S-P80C-D6	No Replacement	No Replacement	03-JUL-2023
PLM2S-P80E-D5	No Replacement	No Replacement	03-JUL-2023
PLM4S-P148-C6	No Replacement	No Replacement	03-JUL-2023
PLM4S-P346D-D	No Replacement	No Replacement	03-JUL-2023
PLM4S-P355-D6	No Replacement	No Replacement	03-JUL-2023
PLM4S-P64-D6	No Replacement	No Replacement	03-JUL-2023
PLT1.5I-P154-M	No Replacement	No Replacement	03-JUL-2023
PLT15I-P81A-M30	No Replacement	No Replacement	03-JUL-2023
PLT15I-P81B-M30	No Replacement	No Replacement	03-JUL-2023
PLT15I-P81C-M30	No Replacement	No Replacement	03-JUL-2023
PLT15I-P81D-M30	No Replacement	No Replacement	03-JUL-2023
PLT15I-P81E-M30	No Replacement	No Replacement	03-JUL-2023
PLT15I-P81F-M30	No Replacement	No Replacement	03-JUL-2023
PLT15I-P81G-M30	No Replacement	No Replacement	03-JUL-2023
PLT15I-P81H-M30	No Replacement	No Replacement	03-JUL-2023
PLT15I-P81J-M30	No Replacement	No Replacement	03-JUL-2023
PLT15I-P81K-M30	No Replacement	No Replacement	03-JUL-2023

PLT2H-P181-TL4Y	No Replacement	No Replacement	03-JUL-2023
PLT2H-P675B-TL6	No Replacement	No Replacement	03-JUL-2023
PLT2H-P675-TL2	No Replacement	No Replacement	03-JUL-2023
PLT2S-P1081A-M2	No Replacement	No Replacement	03-JUL-2023
PLT2S-P156-M55	No Replacement	No Replacement	03-JUL-2023
PLT2S-P180-M6	No Replacement	No Replacement	03-JUL-2023
PLT2S-P238-M	No Replacement	No Replacement	03-JUL-2023
PLT2S-P333A-M3	No Replacement	No Replacement	03-JUL-2023
PLT2S-P333B-M4Y	No Replacement	No Replacement	03-JUL-2023
PLT2S-P333C-M5	No Replacement	No Replacement	03-JUL-2023
PLT2S-P333D-M10	No Replacement	No Replacement	03-JUL-2023
PLT2S-P333E-M6	No Replacement	No Replacement	03-JUL-2023
PLT2S-P95F-M5	No Replacement	No Replacement	03-JUL-2023
PLT2S-P95G-M6	No Replacement	No Replacement	03-JUL-2023
PLT3S-P1081A-M2	No Replacement	No Replacement	03-JUL-2023
PLT3S-P155-M6	No Replacement	No Replacement	03-JUL-2023
PLT3S-P242-M	No Replacement	No Replacement	03-JUL-2023
PLT3S-P25A-M	No Replacement	No Replacement	03-JUL-2023
PLT3S-P348-M100	No Replacement	No Replacement	03-JUL-2023
PLT3S-P352-M6	No Replacement	No Replacement	03-JUL-2023
PLT3S-P91-M0	No Replacement	No Replacement	03-JUL-2023
PLT4H-P223A-TL	No Replacement	No Replacement	03-JUL-2023
PLT4S-P180-M6	No Replacement	No Replacement	03-JUL-2023
PLT4S-P240-C86	No Replacement	No Replacement	03-JUL-2023
PLT4S-P888-M10	No Replacement	No Replacement	03-JUL-2023
PLT5H-P25B-C	No Replacement	No Replacement	03-JUL-2023
PLT6H-P63-C	No Replacement	No Replacement	03-JUL-2023
PLT9LH-P9B-C	No Replacement	No Replacement	03-JUL-2023
PLT9LH-P9E-C3	No Replacement	No Replacement	03-JUL-2023
PLT9LH-P9J-C0	No Replacement	No Replacement	03-JUL-2023
PLT9LH-P9N-C5	No Replacement	No Replacement	03-JUL-2023