



PRODUCT / PROCESS CHANGE NOTIFICATION

PCN NO: PCN IN 230309-17

Issue Date: July 1st, 2023

SUBJECT OF CHANGE:

MSL Level Adjustment for SMD LED Series (Epoxy Encapsulation) Products

PRODUCTS AFFECTED:

All Series. See part series listed below in “PRODUCT Series”.

PRODUCT SPEC NUMBER:

IN-S42DS5G	IN-S42DS5A	IN-S42DS5B	IN-S42DS5UW
IN-S42DS5YG	IN-S42DS5SR	IN-S42DS5B-7835	IN-S42DS5UW-7834
IN-S42DS5Y	IN-S42DS5R		

REASON OF CHANGE:

SMD LED packages were previous designated as MSL 3. Due to their epoxy encapsulation material and their assembly by reflow soldering, Inolux is now designating SMD packages as MSL 2a.

DESCRIPTION OF CHANGE:

Major Change

Minor Change

PRODUCT IDENTIFICATION TO INDICATE CHANGE:

Product packaging bag will reflect change in handling requirement to MSL 2a.

PLEASE NOTE THIS IS A MSL REQUIREMENT ADJUSTMENT ONLY. THE PART REMAINS THE SAME. ALL SPECIFICATIONS, MATERIALS, AND PRODUCT CHARACTERISTICS REMAINS UNCHANGED.

DATECODE OF CHANGE:

Aug. 1st, 2023

DATE TO BEGIN SHIPPING:

Aug. 1st, 2023

ASSESSMENT:

In case of any questions please contact us at:

Issue By	Department	Telephone	Ext.	Fax
William Chang	TM	+1-408-8843871		+1-408-8449618
Holton Lee	GM	+1-408-8449698		+1-408-8449618



**CUSTOMER FEEDBACK FORM
to INOLUX PCN
SMD LED Series MSL Level Adjustment**

Dear Customer,

Your feedback is very much appreciated and will help us to realize this change without problems.
Thank you for your help.

Please tick and comment.

We agree with this change and the schedule.

We have the following objections :

In addition, we need the following information:

We need samples.

Type:

Quantity:

Special requirement:

Purpose of sample order:

Please feedback to: Inolux Corporation

Customer Representative's name:

FAX No.: +1-408-8449618

Phone: +1-408-8843871

Name: Mr. William Chang

.....

Address: 3350 Scott Blvd.

Suite 4102

Santa Clara, CA, USA.

Date/Customer Representative's

Signature