

Product Change Notice

Published Date: 08/09/2023

The change(s) will be applied to the following products. If you need more information or support, please contact PM: Mike Huang

1. Reason for the Change: **BIOS update for Raptor lake-S.**

2. Affected Product: **MIC-770V3.**

3. Impact on Application:

Item	Impact
Impact on Mechanical Design	No
Impact on Software Compatibility	Possible
Impact on Environment Characteristics	No
Impact on Board Certifications ^{Note}	No
Physical Outlook Change	No
Ordering P/N Change	No
Cut-in Implement	New working order

Note: Advantech CE/FCC, UL/CB certifications on this product.

4. Description of the Change(s):

Affected Models	Current Component	New Component	Category	Outlook Difference	Reason
MIC-770V3W-00A1	1420056347 (V1.11)	1420058204 (V2.00)	Firmware	No	1. BIOS update for Raptor lake-S
MIC-770V3H-00A1	1420056348 (V1.11)	1420058205 (V2.00)	Firmware	No	1. BIOS update for Raptor lake-S

5. Implementation & Schedule of the Change(s):

Advantech Southern California
13 Whatney
Irvine, CA 92618
T: 949.420.2500

Advantech Northern California
380 Fairview Way
Milpitas, CA 95305
T: 408.519.3800

Advantech Ohio
11380 Reed Hartman Highway
Cincinnati, OH 45241
T: 513.742.8895

Affected Models	ECOM Number	Estimated Effective Date	Cut-in Implement	Change Description
MIC-770V3W-00A1	ECOM-205291	2023-Sep	New working order	<p>BIOS update.</p> <p>New BIOS compatible with both Alder lake(12th) and Raptor lake(13th) CPUs.</p> <p>Note : <u>The Working order after Sep.</u> will be with the new BIOS phase-in.</p>
MIC-770V3H-00A1	ECOM-205291	2023-Sep	New working order	<p>BIOS update.</p> <p>New BIOS compatible with both Alder lake(12th) and Raptor lake(13th) CPUs.</p> <p>Note : <u>The Working order after Sep.</u> will be with the new BIOS phase-in.</p>

*Note: Cut-in progress depends on the factory production schedule, what is listed in this table is an ESTIMATED time frame

Contact Windows

Contact Windows

PM	Mike Huang / mike.huang@advantech.com / 500-6322
AE	Kent Yang/ kent.yang@advantech.com / 500-6168