

## Discontinuation notice 5.05.10

This letter serves as formal notification that SEGGER Microcontroller GmbH has discontinued the following part number with immediate effect due to manufacturing issues.

5.05.10, Flasher 5 Pro

Please be advised a possible alternative could be 5.17.01, Flasher PRO

We advise the end user to review the web site link below to review as necessary

<https://www.segger.com/products/production/flasher/models/flasher-pro/>

Please accept our apologies for this necessary change.

14th August 2023