



# Product Change Notification

## TE Connectivity

Product Change Notification: PCN-23-183613

PCN Date: 10-AUG-23

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

### General Product Description:

Parts moving to Obsolete

### Description of Changes

The listed part numbers are being discontinued and no longer available. Please consult with your local customer sales representative for further details.

#### Other attachments:

[FOR\\_EMEA\\_023\\_2\\_2019\\_08\\_22 rev.2](#)

### Reason for Changes:

Product Discontinuance

### PCN Attributes:

<b>Product Category:</b>	<b>Kind of Change:</b>
Connectors	Status Change
<b>Change Feature:</b>	<b>Potential Customer Impact:</b>
Discontinuance	No Customer Impact
<b>Remarks:</b>	

### Estimated Dates:

<b>Last Order Date</b> (Obsolete Parts Only):	<b>First Ship Date of Changed Items</b> (Changed Parts Only):
10-AUG-2023	
<b>Last Ship Date of Changed Items</b> (Obsolete Parts Only):	<b>Last Date for Mixed Shipments:</b> (Changed Parts Only):
10-AUG-2023	No Mixed Shipments
<b>Effectivity Date:</b>	<b>Date of First Samples:</b>

### Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">927872-1</a>	YES						

### Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">927872-1</a>	YES						



PCN Description of Eng. Changes

PCN No.  
OEM / CAM informed  
Estimated First Date for samples  
Picture:

PCN-23-183613						
Yes						
Not Applicable						

**TE Part number 1-929450-2, 6-964282-6, 827216-1, 828657-2, 9-699638-6, 963702-2, 1241818-1, 344995-1, 5-962352-1, 826882-5, 827229-4, 827551-5, 828092-3, 828657-5, 927941-2, 962967-1, 967533-1, 1241615-2, 2-927775-1, 344270-3, 699514-1, 828517-1, 926261-1, 927716-1, 1-827520-1, 1-929963-0, 167720-1, 2-962368-1, 349836-1, 5-963215-1, 828657-8, 927659-1, 927864-2, 927872-2, 962945-5, 1-925590-1, 1-927779-1, 344263-2, 348667-8, 5-963291-1, 826008-3, 827212-1, 927872-1, 929966-7, 965739-1, 1-1241026-1, 1-963287-1, 926923-1, 927536-1, 963710-2, 2-967534-1, 216030, 828849-1, 927825-1, 928704-1, 928704-3, 928790-2, 928990-2, 962990-1, 962993-1 are getting obsoleted as there is no sales in the last 10 years and no forecast or customer demand planned**

x	Potential Impact for Customer	x	Product Type	x	Change Type	x	Kind of Change	x	Change Feature	Remark / Free text
		x	CONNECTOR HOUSINGS	x	No Form, Fit, Function	x	Status Change	x	Obsolete	

