

Follow up statement of PCN33-2022

Change in Glass attach epoxy for Line Scanners

14.07.2023

Dear Customer,

please take note of this **Infonote**.

This customer notification is for information only and does not require customer approval.

Objective:	Follow up statement of PCN33-2022 (Change in Glass attach epoxy for Line Scanners)
Affected products:	508080005 4LS10k-5CIA FT SE 508070005 4LS10k-5MIA FT SE 508030006 4LS15k-5CIA FT SE 507830006 4LS15k-5MIA FT SE 507830007 4LS5KM5IA FT SE 301100006 DR16K3.5_INVAR_B&W_V6 FT SE 301740016 DR2K7_INVAR_B&W_BM_V6 FT SE 301110008 DR2X2K7_INVAR_B&W_V6 FT SE 301720008 DR2X2K7_INVAR_RGB_V6 FT SE 301030008 DR2X4K7_INVAR_B&W_V6 FT SE 301040008 DR2X4K7_INVAR_RGB_V6 FT SE 301120005 DR2X8K7_INVAR_B&W_V5 FT SE 301730005 DR2x8K7_Invar_RGB_v5 FT SE 301090010 DR4K3.5_INVAR_B&W_V6 FT SE 301020013 DR4K7_INVAR_B&W_BM_V5 FT SE 301240011 DR6K7_BM_V2 FT SE 301250014 DR8K3.5_INVAR_B&W_BM_V6 FT SE 301750005 DR8K7_Invar_B&W_BM_v6 FT SE
Description:	This is to inform you that full qualification is complete and dual source strategy to be implemented. Samples availability on request according the manufacturing lead times.

If you do have further questions, please do not hesitate to contact us.

Yours sincerely,



Peter Crabbe
ams-OSRAM AG
CIS Operations

Published by ams-OSRAM AG
Tobelbader Strasse 30, 8141 Premstaetten, Austria
Phone +43 3136 500-0
ams-osram.com © All rights reserved