

Product Change Notice

The change(s) will be applied on the affected products, if you need more information or special support, please contact PM: Cindy Huang (TEL: +886-2-2792-7818, ext: 1476; e-Mail:

cindy.huang@advantech.com.tw)

1. Reason for the Change: BMC firmware update.

2. Affected Product: ASMB-805, ASMB-815, ASMB-825, ASMB-925, ASMB-935, ASMB-975, SKY-6100, SKY-6200, SKY-6400 series, and T part numbers that use same BMC firmware as standard products

3. Impact on Application:

Item	Impact
Impact on Mechanical Design	No
Impact on Software Compatibility	No
Impact on Environment Characteristics	No
Impact on Board Certifications	No
Physical Outlook Change	No
Ordering P/N Change	No
Cut-in Implement	Open W/O

4. Description of the Change(s):

Affected Models	Current Component	New Component	Category	Outlook Difference	Reason
ASMB-805	1420055782 (03.04.00.0003)	1420058029 (03.04.00.0006)	FW	No	- Resolved false alarms triggered by a low system fan threshold. - Resolved the issue where the top toolbar in the BMC Web UI would disappear. - Resolved the issue of USB devices occasionally displaying a yellow exclamation mark in Windows Device Manager.
ASMB-815					
ASMB-825					
ASMB-925					
ASMB-935					
ASMB-975					
SKY-6100					
SKY-6200					
SKY-6400					

5. Implementation & Schedule of the Change(s):

Affected Models	ECOM Number	Estimated Effective Date	Cut-in Implement	Change Description
ASMB-805I-00A1	ECOM-204711	Sep 2023	Open W/O	Change BMC firmware 03.04.00.0003 to 03.04.00.0006
ASMB-815I-00A1E				
ASMB-815I-00A1U				
ASMB-815T2-00A1E				
ASMB-815T2-00A1U				
ASMB-825I-00A1E				
ASMB-825T2-00A1E				
ASMB-825T2-00A1U				
ASMB-925I-00A1				
ASMB-925T2-00A1				
ASMB-935I-00A1	ECOM-204711	Sep 2023	Open W/O	Change BMC firmware 03.04.00.0003 to 03.04.00.0006
ASMB-935T2-00A1				
ASMB-935T2-00A1U				
ASMB-975I-00A1				
ASMB-975I-00A1U				
ASMB-975T2-00A1				
ASMB-975T2-00A1U				
SKY-6100-R12B1E				
SKY-6200-R20B1				
SKY-6400-R20B1				

*Note: Cut-in progress depends on factory production schedule, what listed in this table is ESTIMATED time-frame.

Contact Windows

PM	Cindy Huang / cindy.huang@advantech.com.tw / 511-1476
AE	AE.ISG.ACL@advantech.com