



Discontinuation Notice of Some specifications for Mini Power Relay Model MY series, Model G2R series, Ratchet Relay Model G4Q series, Power Relay Model G7J series Model G7X-4BP-JD DC125V, Model MM series, Latching Relay Model G7K series, Model MKK series, Model MMK series, I/O Relay Model G7T series, Model P70A AC110/120, Bi-power Relay Model LY series, Compact power Relay Model MK series, Model MK-S series Socket Model PY(F) series, Model PT(F) series, Model PF series, Model PL15Q, Model P7TF-05-TU, Model PFC series, Model R99 series

Product Discontinuation		Recommended Replacement	
	Mini Power Relay Model MY series Model G2R series		No recommended replacement
	Ratchet Relay Model G4Q series		No recommended replacement
	Power Relay Model G7J series Model G7X-4BP-JD DC125V Model MM series		No recommended replacement
	Latching Relay Model G7K series Model MKK series Model MMK series		No recommended replacement
	I/O Relay Model G7T series Model P70A AC110/120		No recommended replacement
	Bi-power Relay Model LY series		No recommended replacement
	Compact power Relay Model MK series Model MK-S series		No recommended replacement
	Relay circuit unit Model MYA series		No recommended replacement
			

Product Discontinuation**Recommended Replacement**

Socket

Model PY(F) series
Model PT(F) series
Model PF series
Model PL15Q
Model P7TF-05-TU
Model PFC series
Model R99 series

**No recommended replacement****[Final order entry date]**

The end of March, 2023

[Date of The Last Shipping]

The end of June, 2023

[Product Discontinuation and recommended replacement]

Product discontinuation	Recommended replacement
MY2 AC16	No recommended replacement
MY2 DC0.8A	No recommended replacement
MY2-02 AC6	No recommended replacement
MY2-02 DC6	No recommended replacement
MY2-02-AP AC200/220	No recommended replacement
MY2-02-AP DC100/110	No recommended replacement
MY2-02-EU AC100/110	No recommended replacement
MY2-02-TU AC220/240	No recommended replacement
MY2-02-TU DC24	No recommended replacement
MY2-02-US-TS AC240	No recommended replacement
MY2-AP AC100/110	No recommended replacement
MY2-CR AC24	No recommended replacement
MY2-D-Y DC100/110	No recommended replacement
MY2-D-Y DC24	No recommended replacement
MY2-D-Y DC48	No recommended replacement
MY2-G AC100/110	No recommended replacement
MY2-G AC200/220	No recommended replacement
MY2-G AC220/240	No recommended replacement
MY2-G AC24	No recommended replacement
MY2-G DC12	No recommended replacement
MY2-G DC24	No recommended replacement
MY2-G DC6	No recommended replacement
MY2-TU AC100/110	No recommended replacement
MY2-TU AC110/120	No recommended replacement
MY2-TU AC200/220	No recommended replacement
MY2-TU AC220/240	No recommended replacement
MY2-TU AC24	No recommended replacement
MY2-TU DC100/110	No recommended replacement
MY2-TU DC12	No recommended replacement
MY2-TU DC24	No recommended replacement
MY2-Y AC110/120	No recommended replacement

Product discontinuation	Recommended replacement
MY2-Y AC220/240	No recommended replacement
MY2-Y AC24	No recommended replacement
MY2-Y DC100/110	No recommended replacement
MY2-Y DC12	No recommended replacement
MY2-Y DC48	No recommended replacement
MY2-Y DC6	No recommended replacement
MY2E AC100/110	No recommended replacement
MY2E DC125	No recommended replacement
MY2E DC24	No recommended replacement
MY2E-02 AC110/120	No recommended replacement
MY2E-02 DC24	No recommended replacement
MY2F AC6	No recommended replacement
MY2F DC6	No recommended replacement
MY2F-AP AC100/110	No recommended replacement
MY2F-US-SV DC24	No recommended replacement
MY2I AC200/220	No recommended replacement
MY2I DC100/110	No recommended replacement
MY2I DC12	No recommended replacement
MY2IN AC100/110	No recommended replacement
MY2IN AC110/120	No recommended replacement
MY2IN AC200/220	No recommended replacement
MY2IN AC24	No recommended replacement
MY2IN DC24	No recommended replacement
MY2N AC18	No recommended replacement
MY2N DC30	No recommended replacement
MY2N-02 DC48	No recommended replacement
MY2N-CR-TU AC100/110	No recommended replacement
MY2N-CR-TU AC200/220	No recommended replacement
MY2N-TU AC100/110	No recommended replacement
MY2N-TU AC110/120	No recommended replacement
MY2N-TU AC200/220	No recommended replacement
MY2N-TU DC100/110	No recommended replacement
MY2N-TU DC12	No recommended replacement
MY2N-TU DC24	No recommended replacement
MY2N-Y AC110/120	No recommended replacement
MY2N-Y AC12	No recommended replacement
MY2N-Y AC220/240	No recommended replacement
MY2N-Y AC24	No recommended replacement
MY2N-Y DC100/110	No recommended replacement
MY2N-Y DC12	No recommended replacement
MY2N-Y DC48	No recommended replacement
MY2N-Y DC6	No recommended replacement
MY2N-Y-CR AC100/110	No recommended replacement
MY2Z AC50	No recommended replacement
MY2Z DC125	No recommended replacement
MY2Z DC15	No recommended replacement
MY2Z DC6	No recommended replacement
MY2Z-02 AC100/110	No recommended replacement
MY2Z-02 AC110/120.	No recommended replacement

Product discontinuation	Recommended replacement
MY2Z-02 AC200/220	No recommended replacement
MY2Z-02 AC220/240	No recommended replacement
MY2Z-02 AC24.	No recommended replacement
MY2Z-02 DC100/110	No recommended replacement
MY2Z-02 DC12	No recommended replacement
MY2Z-02 DC24	No recommended replacement
MY2Z-02 DC48	No recommended replacement
MY2Z-D DC6	No recommended replacement
MY2Z-G AC100/110	No recommended replacement
MY2Z-G DC24	No recommended replacement
MY2Z-TU AC100/110	No recommended replacement
MY2Z-TU DC24	No recommended replacement
MY2ZF AC100/110	No recommended replacement
MY2ZF AC220/240	No recommended replacement
MY2ZF AC24	No recommended replacement
MY2ZF DC12	No recommended replacement
MY2ZF DC24	No recommended replacement
MY2ZN AC50	No recommended replacement
MY2ZN AC6	No recommended replacement
MY2ZN DC6	No recommended replacement
MY2ZN-TU DC24	No recommended replacement
MY3 AC50	No recommended replacement
MY3 AC6	No recommended replacement
MY3 DC125	No recommended replacement
MY3 DC6	No recommended replacement
MY3-02 DC6	No recommended replacement
MY3-02-EU AC100/110	No recommended replacement
MY3-02-EU AC220/240	No recommended replacement
MY3-02-EU AC24	No recommended replacement
MY3-02-EU DC24	No recommended replacement
MY3-02-PC AC220/240	No recommended replacement
MY3-AP AC100/110	No recommended replacement
MY3-AP DC100/110	No recommended replacement
MY3-CR AC100/110	No recommended replacement
MY3-CR AC220/240	No recommended replacement
MY3-TU AC110/120	No recommended replacement
MY3-TU AC220/240	No recommended replacement
MY3-TU DC100/110	No recommended replacement
MY3-TU DC12	No recommended replacement
MY3-TU DC24	No recommended replacement
MY3-US-SV DC100/110	No recommended replacement
MY3-US-SV DC12	No recommended replacement
MY3F AC110/120	No recommended replacement
MY3F AC220/240	No recommended replacement
MY3F AC24	No recommended replacement
MY3F AC6	No recommended replacement
MY3F DC12	No recommended replacement
MY3F DC27	No recommended replacement
MY3N DC6	No recommended replacement

Product discontinuation	Recommended replacement
MY3N-02 AC100/110	No recommended replacement
MY3N-02 DC24	No recommended replacement
MY3N-CR AC100/110	No recommended replacement
MY3N-CR AC200/220	No recommended replacement
MY3N-D2 DC48	No recommended replacement
MY3N-TU AC100/110	No recommended replacement
MY4-02 AC115	No recommended replacement
MY4-02 AC50	No recommended replacement
MY4-02 AC6	No recommended replacement
MY4-02 DC6	No recommended replacement
MY4-02-BU-AP2 AC100	No recommended replacement
MY4-02-BU-AP2 AC200	No recommended replacement
MY4-02-BU-HT AC100	No recommended replacement
MY4-02-BU-HT AC200	No recommended replacement
MY4-CR AC24	No recommended replacement
MY4-D DC125	No recommended replacement
MY4-G AC100/110	No recommended replacement
MY4-G AC110/120	No recommended replacement
MY4-G AC200/220	No recommended replacement
MY4-G AC24	No recommended replacement
MY4-G DC12	No recommended replacement
MY4-G DC24	No recommended replacement
MY4-G DC48	No recommended replacement
MY4-G DC6	No recommended replacement
MY4-TU AC100/110	No recommended replacement
MY4-TU AC110/120	No recommended replacement
MY4-TU AC200/220	No recommended replacement
MY4-TU AC220/240	No recommended replacement
MY4-TU DC100/110	No recommended replacement
MY4-TU DC12	No recommended replacement
MY4-TU DC125	No recommended replacement
MY4-TU DC24	No recommended replacement
MY4-TU DC48	No recommended replacement
MY4E DC100/110	No recommended replacement
MY4E DC24	No recommended replacement
MY4F-D DC48	No recommended replacement
MY4I AC100/110	No recommended replacement
MY4I AC200/220	No recommended replacement
MY4I AC220/240	No recommended replacement
MY4I AC24	No recommended replacement
MY4I DC100/110	No recommended replacement
MY4I DC12	No recommended replacement
MY4I DC125	No recommended replacement
MY4I DC24	No recommended replacement
MY4I DC48	No recommended replacement
MY4IN AC100/110	No recommended replacement
MY4IN AC110/120	No recommended replacement
MY4IN AC200/220	No recommended replacement
MY4IN AC220/240	No recommended replacement

Product discontinuation	Recommended replacement
MY4IN AC24	No recommended replacement
MY4IN DC100/110	No recommended replacement
MY4IN DC24	No recommended replacement
MY4IN DC48	No recommended replacement
MY4IN-D2 DC24	No recommended replacement
MY4N AC125	No recommended replacement
MY4N AC36	No recommended replacement
MY4N AC42	No recommended replacement
MY4N-02 AC110/120	No recommended replacement
MY4N-02 DC48	No recommended replacement
MY4N-13 DC24	No recommended replacement
MY4N-CR AC115	No recommended replacement
MY4N-CR-TU AC100/110	No recommended replacement
MY4N-CR-TU AC110/120	No recommended replacement
MY4N-CR-TU AC200/220	No recommended replacement
MY4N-D2-TU DC12	No recommended replacement
MY4N-D2-TU DC48	No recommended replacement
MY4N-D2-TU DC6	No recommended replacement
MY4N-G AC100/110	No recommended replacement
MY4N-G AC200/220	No recommended replacement
MY4N-G DC24	No recommended replacement
MY4N-TU AC100/110	No recommended replacement
MY4N-TU AC24	No recommended replacement
MY4N-TU DC100/110	No recommended replacement
MY4N-TU DC12	No recommended replacement
MY4N-TU DC5	No recommended replacement
MY4Z DC6	No recommended replacement
MY4Z-02 AC100/110	No recommended replacement
MY4Z-02 AC200/220	No recommended replacement
MY4Z-02 DC12	No recommended replacement
MY4Z-02-CBG AC200/220	No recommended replacement
MY4Z-02-CBG DC100/110	No recommended replacement
MY4Z-02-CBG DC12	No recommended replacement
MY4Z-02-CBG DC24	No recommended replacement
MY4Z-CBG AC12	No recommended replacement
MY4Z-CBG AC220/240	No recommended replacement
MY4Z-CBG-G DC100/110	No recommended replacement
MY4Z-CBG-G DC125	No recommended replacement
MY4Z-CBG-G DC24	No recommended replacement
MY4Z-CR-AP5 AC200/220	No recommended replacement
MY4Z-D-CBG DC100/110	No recommended replacement
MY4Z-D-CBG DC24	No recommended replacement
MY4Z-D-CBG DC48	No recommended replacement
MY4Z-D-TU DC24	No recommended replacement
MY4Z-G AC100/110	No recommended replacement
MY4Z-G DC24	No recommended replacement
MY4Z-G DC6	No recommended replacement
MY4Z-TU AC100/110	No recommended replacement
MY4Z-TU AC110/120	No recommended replacement

Product discontinuation	Recommended replacement
MY4Z-TU AC200/220	No recommended replacement
MY4Z-TU AC220/240	No recommended replacement
MY4Z-TU DC24	No recommended replacement
MY4ZF-CBG AC200/220	No recommended replacement
MY4ZI AC100/110	No recommended replacement
MY4ZI AC110/120	No recommended replacement
MY4ZI AC12	No recommended replacement
MY4ZI AC200/220	No recommended replacement
MY4ZI DC100/110	No recommended replacement
MY4ZI DC12	No recommended replacement
MY4ZI DC24	No recommended replacement
MY4ZI-CBG AC100/110	No recommended replacement
MY4ZI-CBG DC100/110	No recommended replacement
MY4ZI-CBG DC12	No recommended replacement
MY4ZI-CBG DC24	No recommended replacement
MY4ZI-CBG DC48	No recommended replacement
MY4ZIN AC100/110	No recommended replacement
MY4ZIN AC200/220	No recommended replacement
MY4ZIN DC100/110	No recommended replacement
MY4ZIN DC24	No recommended replacement
MY4ZIN DC48	No recommended replacement
MY4ZIN-D2 DC48	No recommended replacement
MY4ZN DC20	No recommended replacement
MY4ZN DC40	No recommended replacement
MY4ZN-AP5 AC100/110	No recommended replacement
MY4ZN-AP5 AC200/220	No recommended replacement
MY4ZN-AP5 DC100/110	No recommended replacement
MY4ZN-AP5 DC24	No recommended replacement
MY4ZN-AP5 DC48	No recommended replacement
MY4ZN-CBG AC110/120	No recommended replacement
MY4ZN-CBG AC220/240	No recommended replacement
MY4ZN-CBG DC125	No recommended replacement
MY4ZN-CBG DC48	No recommended replacement
MY4ZN-CBG-CR AC100/110	No recommended replacement
MY4ZN-CBG-CR AC200/220	No recommended replacement
MY4ZN-CR-AP5 AC100/110	No recommended replacement
MY4ZN-CR-AP5 AC200/220	No recommended replacement
MY4ZN-CR-TU AC100/110	No recommended replacement
MY4ZN-D2-AP5 DC100/110	No recommended replacement
MY4ZN-D2-AP5 DC12	No recommended replacement
MY4ZN-D2-AP5 DC24	No recommended replacement
MY4ZN-D2-AP5 DC48	No recommended replacement
MY4ZN-D2-CBG DC12	No recommended replacement
MY4ZN-D2-CBG DC48	No recommended replacement
MY4ZN-D2-TU DC125	No recommended replacement
MY4ZN-TU AC100/110	No recommended replacement
MY4ZN-TU AC110/120	No recommended replacement
MY4ZN-TU DC24	No recommended replacement
MY2 AC48/50	No recommended replacement

Product discontinuation	Recommended replacement
MY2 DC125	No recommended replacement
MY2-D DC125	No recommended replacement
MY2-D DC6	No recommended replacement
MY2N AC48/50	No recommended replacement
MY2N DC125	No recommended replacement
MY2N-D2 DC125	No recommended replacement
MY4 AC48/50	No recommended replacement
MY4 AC6	No recommended replacement
MY4 DC125	No recommended replacement
MY4-D DC6	No recommended replacement
MY4N AC48/50	No recommended replacement
MY4Z AC12	No recommended replacement
MY4Z AC48/50	No recommended replacement
MY4Z DC125	No recommended replacement
MY4Z-D DC125	No recommended replacement
MY4Z-D DC6	No recommended replacement
MY4ZN AC12	No recommended replacement
MY4ZN AC48/50	No recommended replacement
MY4ZN AC6	No recommended replacement
MY4ZN DC125	No recommended replacement
MY4ZN DC48	No recommended replacement
MY4ZN DC6	No recommended replacement
MY4ZN-CR AC24	No recommended replacement
MY4ZN-D2 DC125	No recommended replacement
MY4ZN-D2 DC6	No recommended replacement
MY4H-G DC12	No recommended replacement
MY4H-G DC6	No recommended replacement
MY4H-US AC12	No recommended replacement
MY4H-US AC24	No recommended replacement
MY4H-US DC100/110	No recommended replacement
MY4ZH DC125	No recommended replacement
MY4ZH DC5	No recommended replacement
MY4ZH-0 DC12	No recommended replacement
MY4ZH-CBG DC12	No recommended replacement
MY2 AC100/110 (S)	No recommended replacement
MY2 AC200/220 (S)	No recommended replacement
MY2 DC125 (S)	No recommended replacement
MY2 DC220 (S)	No recommended replacement
MY2-D DC12 (S)	No recommended replacement
MY2I DC220 (S)	No recommended replacement
MY2IN DC125 (S)	No recommended replacement
MY2IN-CR AC100/110 (S)	No recommended replacement
MY2IN-CR AC200/220 (S)	No recommended replacement
MY2IN1-D2 DC220(S)	No recommended replacement
MY2N DC125 (S)	No recommended replacement
MY2N-CR AC100/110 (S)	No recommended replacement
MY2N-CR AC200/220 (S)	No recommended replacement
MY2N-D2 DC125 (S)	No recommended replacement
MY4 AC100/110 (S)	No recommended replacement

Product discontinuation	Recommended replacement
MY4 DC220 (S)	No recommended replacement
MY4I DC220 (S)	No recommended replacement
MY4IN DC60 (S)	No recommended replacement
MY4IN-D2 DC100/110 (S)	No recommended replacement
MY4IN1 DC125 (S)	No recommended replacement
MY4IN1-D2 DC125 (S)	No recommended replacement
MY4IN1-D2 DC60 (S)	No recommended replacement
MY4N-D2 DC125 (S)	No recommended replacement
MY4Z AC100/110 (S)	No recommended replacement
MY4Z AC200/220 (S)	No recommended replacement
MY4Z DC125 (S)	No recommended replacement
MY4ZIN DC125 (S)	No recommended replacement
MY4ZIN1-D2 DC100/110 (S)	No recommended replacement
MY4ZIN1-D2 DC12 (S)	No recommended replacement
MY4ZIN1-D2 DC24 (S)	No recommended replacement
MY4ZIN1-D2 DC48 (S)	No recommended replacement
MY4ZIN1-D2 DC6 (S)	No recommended replacement
MY4ZN AC100/110 (S)	No recommended replacement
MY4ZN AC200/220 (S)	No recommended replacement
MY4ZN DC125 (S)	No recommended replacement
MY4ZN-CR AC100/110 (S)	No recommended replacement
MY4ZN-CR AC200/220 (S)	No recommended replacement
MY4ZN-D2 DC125 (S)	No recommended replacement
MYQ2 DC24	No recommended replacement
MYQ2ZN AC100/110	No recommended replacement
MYQ2ZN AC200/220	No recommended replacement
MYQ2ZN DC24	No recommended replacement
MYQ4 AC12	No recommended replacement
MYQ4 AC50	No recommended replacement
MYQ4 DC12	No recommended replacement
MYQ4 DC125	No recommended replacement
MYQ4 DC48	No recommended replacement
MYQ4-02-40 DC48	No recommended replacement
MYQ4N AC48	No recommended replacement
MYQ4N AC6	No recommended replacement
MYQ4N DC125	No recommended replacement
MYQ4Z AC12	No recommended replacement
MYQ4Z DC100/110	No recommended replacement
MYQ4Z DC48	No recommended replacement
MYQ4Z-02 AC110/120	No recommended replacement
MYQ4Z-02 AC200/220	No recommended replacement
MYQ4Z-2 DC24	No recommended replacement
MYQ4ZN AC24	No recommended replacement
MYQ4ZN-D2 DC48	No recommended replacement
MY2K AC115	No recommended replacement
MY2K AC6	No recommended replacement
MY2K DC6	No recommended replacement
MY2K-02 AC120	No recommended replacement
MY2K-G DC24	No recommended replacement

Product discontinuation	Recommended replacement
MY2K-US AC12	No recommended replacement
MY2K-US DC48	No recommended replacement
MY2KZ DC24	No recommended replacement
MY2KZ-02-CBG DC24	No recommended replacement
MY2KZ-CBG DC24	No recommended replacement
MY2KZ-CBG DC48	No recommended replacement
MY2KZ-D DC24	No recommended replacement
MY2-02 AC110/120 BY OMZ	No recommended replacement
MY2-02 AC48 BY OMZ	No recommended replacement
MY2-02 DC100/110 BY OMZ	No recommended replacement
MY2-02 DC6 BY OMZ	No recommended replacement
MY2-02-E AC220/240 BY OMZ	No recommended replacement
MY2-02-EU AC200/220 BY OMZ	No recommended replacement
MY2-02-EU AC220/240 BY OMZ	No recommended replacement
MY2-02-EU DC100/110 BY OMZ	No recommended replacement
MY2-02-EU DC12 BY OMZ	No recommended replacement
MY2-02-EU DC24 BY OMZ	No recommended replacement
MY2-02-SL AC220/240 BY OMZ	No recommended replacement
MY2-02-US-SV AC110/120 BY OMZ	No recommended replacement
MY2-02-US-SV AC12 BY OMZ	No recommended replacement
MY2-02-US-SV AC24 BY OMZ	No recommended replacement
MY2-02-US-SV AC48 BY OMZ	No recommended replacement
MY2-02-US-SV DC12 BY OMZ	No recommended replacement
MY2-02-US-SV DC6 BY OMZ	No recommended replacement
MY2-02-US-SV-EU AC110/120 OMZ	No recommended replacement
MY2-02-US-SV-EU AC12 BY OMZ	No recommended replacement
MY2-02-US-SV-EU AC24 BY OMZ	No recommended replacement
MY2-02-US-SV-EU AC48 BY OMZ	No recommended replacement
MY2-02-US-SV-EU DC12 BY OMZ	No recommended replacement
MY2-02-US-SV-EU DC6 BY OMZ	No recommended replacement
MY2-US-SV AC110/120 BY OMZ	No recommended replacement
MY2-US-SV AC24 BY OMZ	No recommended replacement
MY2-US-SV DC12 BY OMZ	No recommended replacement
MY2-US-SV DC24 BY OMZ	No recommended replacement
MY2E-02 AC220/240 BY OMZ	No recommended replacement
MY2F AC110/120 BY OMZ	No recommended replacement
MY2F AC200/220 BY OMZ	No recommended replacement
MY2F AC24 BY OMZ	No recommended replacement
MY2F DC100/110 BY OMZ	No recommended replacement
MY2F DC12 BY OMZ	No recommended replacement
MY2F DC24 BY OMZ	No recommended replacement
MY2F DC6 BY OMZ	No recommended replacement
MY2F-EU AC24 BY OMZ	No recommended replacement
MY2F-EU DC24 BY OMZ	No recommended replacement
MY2F-US-SV AC110/120 BY OMZ	No recommended replacement
MY2F-US-SV-EU AC110/120 BY OMZ	No recommended replacement
MY2F-V0 AC110/120 BY OMZ	No recommended replacement
MY4-02 AC100/110 BY OMZ	No recommended replacement
MY4-02 AC200/220 BY OMZ	No recommended replacement

Product discontinuation	Recommended replacement
MY4-02 AC48 BY OMZ	No recommended replacement
MY4-02 AP10 DC12 BY OMZ	No recommended replacement
MY4-02 AP10-EU DC12 BY OMZ	No recommended replacement
MY4-02 DC100/110 BY OMZ	No recommended replacement
MY4-02 DC48 BY OMZ	No recommended replacement
MY4-02 DC6 BY OMZ	No recommended replacement
MY4-02 DC9 BY OMZ	No recommended replacement
MY4-02-1 DC24 BY OMZ	No recommended replacement
MY4-02-EU AC110/120 BY OMZ	No recommended replacement
MY4-02-EU AC200/220 BY OMZ	No recommended replacement
MY4-02-EU AC24 BY OMZ	No recommended replacement
MY4-02-EU AC48 BY OMZ	No recommended replacement
MY4-02-EU DC100/110 BY OMZ	No recommended replacement
MY4-02-EU DC12 BY OMZ	No recommended replacement
MY4-02-EU DC48 BY OMZ	No recommended replacement
MY4-02-LS DC42 BY OMZ	No recommended replacement
MY4E-02 AC110/120 BY OMZ	No recommended replacement
MY4E-02 AC24 BY OMZ	No recommended replacement
MY4E-02 DC100/110 BY OMZ	No recommended replacement
MY4E-02 DC24 BY OMZ	No recommended replacement
MY4F AC110/120 BY OMZ	No recommended replacement
MY4F AC200/220 BY OMZ	No recommended replacement
MY4F AC220/240 BY OMZ	No recommended replacement
MY4F DC12 BY OMZ	No recommended replacement
MY4F DC24 BY OMZ	No recommended replacement
MY4F-EU AC220/240 BY OMZ	No recommended replacement
MY4F-EU DC12 BY OMZ	No recommended replacement
G2R-1-S AC120(N) BY OMB	No recommended replacement
G2R-1-S AC230(N) BY OMB	No recommended replacement
G2R-1-S AC240(N) BY OMB	No recommended replacement
G2R-1-S AC48(N) BY OMB	No recommended replacement
G2R-1-S DC110(N) BY OMB	No recommended replacement
G2R-1-S DC9(N) BY OMB	No recommended replacement
G2R-1-SN AC120(N) BY OMB	No recommended replacement
G2R-1-SN AC230(N) BY OMB	No recommended replacement
G2R-1-SN AC240(N) BY OMB	No recommended replacement
G2R-1-SN AC50(N) BY OMB	No recommended replacement
G2R-1-SN DC110(N) BY OMB	No recommended replacement
G2R-2-S AC120(N) BY OMB	No recommended replacement
G2R-2-S AC230(N) BY OMB	No recommended replacement
G2R-2-S AC240(N) BY OMB	No recommended replacement
G2R-2-S AC48(N) BY OMB	No recommended replacement
G2R-2-S AC50(N) BY OMB	No recommended replacement
G2R-2-S DC110(N) BY OMB	No recommended replacement
G2R-2-SD DC110(N) BY OMB	No recommended replacement
G2R-2-SN AC120(N) BY OMB	No recommended replacement
G2R-2-SN AC230(N) BY OMB	No recommended replacement
G2R-2-SN AC240(N) BY OMB	No recommended replacement
G2R-2-SN AC48(N) BY OMB	No recommended replacement

Product discontinuation	Recommended replacement
G2R-2-SN AC50(N) BY OMB	No recommended replacement
G2R-2-SN DC110(N) BY OMB	No recommended replacement
G2R-2-SN DC60(N) BY OMB	No recommended replacement
G2R-2-SND-AP3 DC110(N) BY OMB	No recommended replacement
G2R-1-S AC12(S) BY OMB	No recommended replacement
G2R-1-S DC100(S) BY OMB	No recommended replacement
G2R-1-S DC110(S) BY OMB	No recommended replacement
G2R-1-S DC5(S) BY OMB	No recommended replacement
G2R-1-S-AP3 AC24(S) BY OMB	No recommended replacement
G2R-1-S-AP3 DC12(S) BY OMB	No recommended replacement
G2R-1-SD DC100(S) BY OMB	No recommended replacement
G2R-1-SD DC5(S) BY OMB	No recommended replacement
G2R-1-SN AC12(S) BY OMB	No recommended replacement
G2R-1-SN AC200/(220)BY OMB(SOD	No recommended replacement
G2R-1-SN AC50(S) BY OMB	No recommended replacement
G2R-1-SN DC100(S) BY OMB	No recommended replacement
G2R-1-SN DC110(S) BY OMB	No recommended replacement
G2R-1-SN DC5(S) BY OMB	No recommended replacement
G2R-1-SN-AP3 AC24(S) BY OMB	No recommended replacement
G2R-1-SND DC100 (S) BY OMB	No recommended replacement
G2R-1-SND DC24 BY OMB (SOD)	No recommended replacement
G2R-1-SND DC5(S) BY OMB	No recommended replacement
G2R-1-SNDI DC110(S) BY OMB	No recommended replacement
G2R-1-SNDI DC12 BY OMB (SJ)	No recommended replacement
G2R-1-SNDI DC24 BY OMB (SJ)	No recommended replacement
G2R-1-SNI AC100/(110)BYOMB(SJ)	No recommended replacement
G2R-1-SNI AC200/(220)BYOMB(SJ)	No recommended replacement
G2R-1-SNI DC12 BY OMB (SJ)	No recommended replacement
G2R-1-SNI DC24 BY OMB (SJ)	No recommended replacement
G2R-1-SNI-AP3 DC12 (S) BY OMB	No recommended replacement
G2R-2-S AC12(S) BY OMB	No recommended replacement
G2R-2-S AC50(S) BY OMB	No recommended replacement
G2R-2-S DC100(S) BY OMB	No recommended replacement
G2R-2-S DC110(S) BY OMB	No recommended replacement
G2R-2-S DC5(S) BY OMB	No recommended replacement
G2R-2-S-AP3 AC24(S) BY OMB	No recommended replacement
G2R-2-S-AP3 DC12(S) BY OMB	No recommended replacement
G2R-2-SD DC100(S) BY OMB	No recommended replacement
G2R-2-SD DC110(S) BY OMB	No recommended replacement
G2R-2-SD DC5(S) BY OMB	No recommended replacement
G2R-2-SN AC12(S) BY OMB	No recommended replacement
G2R-2-SN AC200/(220) BYOMB(SOD	No recommended replacement
G2R-2-SN AC50(S) BY OMB	No recommended replacement
G2R-2-SN DC100(S) BY OMB	No recommended replacement
G2R-2-SN DC24 BY OMB (SOD)	No recommended replacement
G2R-2-SN DC5(S) BY OMB	No recommended replacement
G2R-2-SN DC60(S) BY OMB	No recommended replacement
G2R-2-SN-AP3 AC24(S) BY OMB	No recommended replacement
G2R-2-SND DC100(S) BY OMB	No recommended replacement

Product discontinuation	Recommended replacement
G2R-2-SND DC110(S) BY OMB	No recommended replacement
G2R-2-SND DC5(S) BY OMB	No recommended replacement
G2R-2-SNDI DC12 BY OMB (SJ)	No recommended replacement
G2R-2-SNDI DC24 BY OMB (SJ)	No recommended replacement
G2R-2-SNI AC100/(110)BYOMB(SJ)	No recommended replacement
G2R-2-SNI AC200/(220)BYOMB(SJ)	No recommended replacement
G2R-2-SNI AC230 BY OMB (SJ)	No recommended replacement
G2R-2-SNI DC12 BY OMB (SJ)	No recommended replacement
G2R-2-SNI DC24 BY OMB (SJ)	No recommended replacement
G2R-1-T DC110 BY OMB	No recommended replacement
G2R-1A-T AC230 BY OMB	No recommended replacement
G2R-1A-T-AP3 AC120 BY OMB	No recommended replacement
G2R-1A-T-AP3 AC230 BY OMB	No recommended replacement
G4Q-211A AC50 CHN	No recommended replacement
G4Q-211A DC6	No recommended replacement
G4Q-212S AC115	No recommended replacement
G4Q-212S AC120	No recommended replacement
G4Q-212S AC230	No recommended replacement
G4Q-212S AC48	No recommended replacement
G4Q-212S DC220	No recommended replacement
G4Q-212S DC6	No recommended replacement
G7J-2A2B-B DC6	No recommended replacement
G7J-2A2B-B-W1 AC24	No recommended replacement
G7J-2A2B-B-W1 DC12V	No recommended replacement
G7J-2A2B-BZ-2B AC100/120	No recommended replacement
G7J-2A2B-BZ-2B AC200/240	No recommended replacement
G7J-2A2B-BZ-2B DC24	No recommended replacement
G7J-2A2B-P DC6	No recommended replacement
G7J-2A2B-PZ-2B AC100/120	No recommended replacement
G7J-2A2B-PZ-2B AC200/240	No recommended replacement
G7J-2A2B-PZ-2B-OEE DC24	No recommended replacement
G7J-2A2B-T DC6	No recommended replacement
G7J-2A2B-T-W1 AC200/240	No recommended replacement
G7J-2A2B-T-W1 AC24	No recommended replacement
G7J-2A2B-T-W1 DC12	No recommended replacement
G7J-2A2B-T-W1 DC24	No recommended replacement
G7J-2A2B-TZ-2B AC100/120	No recommended replacement
G7J-2A2B-TZ-2B AC200/240	No recommended replacement
G7J-2A2B-TZ-2B DC24	No recommended replacement
G7J-3A1B-B DC6	No recommended replacement
G7J-3A1B-B-W1 AC200/240	No recommended replacement
G7J-3A1B-B-W1 AC24	No recommended replacement
G7J-3A1B-B-W1 DC12	No recommended replacement
G7J-3A1B-B-W1 DC48	No recommended replacement
G7J-3A1B-BZ AC100/120	No recommended replacement
G7J-3A1B-BZ DC110	No recommended replacement
G7J-3A1B-BZ DC6	No recommended replacement
G7J-3A1B-P DC6	No recommended replacement
G7J-3A1B-PZ AC100/120	No recommended replacement

Product discontinuation	Recommended replacement
G7J-3A1B-T DC6	No recommended replacement
G7J-3A1B-T-W1 AC24	No recommended replacement
G7J-3A1B-T-W1 DC12	No recommended replacement
G7J-3A1B-TZ AC200/240	No recommended replacement
G7J-4A-B DC110	No recommended replacement
G7J-4A-B DC6	No recommended replacement
G7J-4A-B-KM-W1 AC200/240	No recommended replacement
G7J-4A-B-W1 AC24	No recommended replacement
G7J-4A-B-W1 DC12	No recommended replacement
G7J-4A-BZ AC100/120	No recommended replacement
G7J-4A-P DC6	No recommended replacement
G7J-4A-P-CB-IN DC24V	No recommended replacement
G7J-4A-P-PH DC24	No recommended replacement
G7J-4A-T DC6	No recommended replacement
G7J-4A-T-W1 AC100/120	No recommended replacement
G7J-4A-T-W1 AC200/240	No recommended replacement
G7J-4A-T-W1 DC12	No recommended replacement
G7J-4A-T-W1 DC24	No recommended replacement
G7J-4A-TZ DC12	No recommended replacement
G7J-4A-TZ DC24	No recommended replacement
G7X-4BP-JD DC125	No recommended replacement
MM2 AC110	No recommended replacement
MM2 AC115	No recommended replacement
MM2 AC220	No recommended replacement
MM2 AC230	No recommended replacement
MM2 AC48	No recommended replacement
MM2 DC200/220	No recommended replacement
MM2 DC42	No recommended replacement
MM2B AC115	No recommended replacement
MM2B DC3A	No recommended replacement
MM2B DC6	No recommended replacement
MM2P AC115	No recommended replacement
MM2P AC120	No recommended replacement
MM2P AC230	No recommended replacement
MM2P AC240	No recommended replacement
MM2P AC400	No recommended replacement
MM2P AC63.5	No recommended replacement
MM2P DC1A	No recommended replacement
MM2P DC230	No recommended replacement
MM2P-TC AC120	No recommended replacement
MM2P-TC DC200/220	No recommended replacement
MM2P-V AC100/(110)	No recommended replacement
MM2PN-D DC100/110	No recommended replacement
MM2PN-D DC24	No recommended replacement
MM2PN-D DC6	No recommended replacement
MM2X DC200/220	No recommended replacement
MM2XB DC125V	No recommended replacement
MM2XB DC200/220.	No recommended replacement
MM2XP AC115	No recommended replacement

Product discontinuation	Recommended replacement
MM2XP AC120	No recommended replacement
MM2XP AC125	No recommended replacement
MM2XP AC210	No recommended replacement
MM2XP AC230	No recommended replacement
MM2XP AC240	No recommended replacement
MM2XP AC400	No recommended replacement
MM2XP AC50	No recommended replacement
MM2XP AC63.5	No recommended replacement
MM2XP DC120	No recommended replacement
MM2XP DC1A	No recommended replacement
MM2XP DC250	No recommended replacement
MM2XP DC30	No recommended replacement
MM2XP DC36	No recommended replacement
MM2XP-D DC6	No recommended replacement
MM2XP-D DC80	No recommended replacement
MM2XP-TC AC100/(110)	No recommended replacement
MM2XP-TC AC220	No recommended replacement
MM2XP-TC DC100/110	No recommended replacement
MM2XP-TC DC125	No recommended replacement
MM2XP-TC DC24	No recommended replacement
MM2XP-TC DC48	No recommended replacement
MM2XP-V AC200/(220)	No recommended replacement
MM2XPN-D DC125	No recommended replacement
MM2XPN-D DC200/220	No recommended replacement
MM2XPN-D DC48	No recommended replacement
MM2XPN-V AC100/(110)	No recommended replacement
MM2XPN-V AC200/(220)	No recommended replacement
MM3 AC115	No recommended replacement
MM3 AC220	No recommended replacement
MM3 DC200/220	No recommended replacement
MM3P AC115	No recommended replacement
MM3P AC120	No recommended replacement
MM3P AC230	No recommended replacement
MM3P AC240	No recommended replacement
MM3P AC63.5	No recommended replacement
MM3PN AC110	No recommended replacement
MM3PN DC6	No recommended replacement
MM3PN-D DC200/220	No recommended replacement
MM3XB AC230	No recommended replacement
MM3XB DC125	No recommended replacement
MM3XB DC200/220	No recommended replacement
MM3XP AC240	No recommended replacement
MM3XP DC125	No recommended replacement
MM3XP DC21	No recommended replacement
MM3XPN-D DC100/110	No recommended replacement
MM3XPN-D DC24	No recommended replacement
MM4 AC115	No recommended replacement
MM4 AC120	No recommended replacement
MM4 DC200/220	No recommended replacement

Product discontinuation	Recommended replacement
MM4B AC110	No recommended replacement
MM4P AC115	No recommended replacement
MM4P AC12	No recommended replacement
MM4P AC120	No recommended replacement
MM4P AC230	No recommended replacement
MM4P AC240	No recommended replacement
MM4P DC6	No recommended replacement
MM4P-JD AC115	No recommended replacement
MM4P-JD AC63.5	No recommended replacement
MM4P-TC DC100/110	No recommended replacement
MM4PN DC12	No recommended replacement
MM4PN-D DC100/110	No recommended replacement
MM4PN-D DC24	No recommended replacement
MM4XB AC115	No recommended replacement
MM4XB AC12	No recommended replacement
MM4XB AC120	No recommended replacement
MM4XB AC240	No recommended replacement
MM4XB DC125	No recommended replacement
MM4XP AC120	No recommended replacement
MM4XP AC125	No recommended replacement
MM4XP AC210	No recommended replacement
MM4XP AC230	No recommended replacement
MM4XP AC240	No recommended replacement
MM4XP AC63.5	No recommended replacement
MM4XP DC1A	No recommended replacement
MM4XP DC250	No recommended replacement
MM4XP DC36	No recommended replacement
MM4XP-D DC60V	No recommended replacement
MM4XP-JD AC115	No recommended replacement
MM4XP-TC AC220	No recommended replacement
MM4XP-TC AC230	No recommended replacement
MM4XP-TC DC100/110	No recommended replacement
MM4XP-TC DC125	No recommended replacement
MM4XP-TC DC200/220	No recommended replacement
MM4XP-TC DC24	No recommended replacement
MM4XP-V AC100/(110)	No recommended replacement
MM4XP-V AC200/(220)	No recommended replacement
MM4XPN AC50	No recommended replacement
MM4XPN-D DC200/220	No recommended replacement
MM4XPN-D DC48	No recommended replacement
MM2K AC110	No recommended replacement
MM2K AC220	No recommended replacement
MM2K DC80 AC100/(110)	No recommended replacement
MM2KB AC110	No recommended replacement
MM2KB DC48	No recommended replacement
MM2KB DC6 AC200/(220)	No recommended replacement
MM2KP AC115	No recommended replacement
MM2KP AC120.	No recommended replacement
MM2KP AC240	No recommended replacement

Product discontinuation	Recommended replacement
MM2KP DC100/110 AC100/(110)	No recommended replacement
MM2KP DC1A AC100/(110)	No recommended replacement
MM2KP DC50	No recommended replacement
MM2KPD DC24	No recommended replacement
MM2XK AC100/(110)	No recommended replacement
MM2XKP AC100/(110) DC100/110	No recommended replacement
MM2XKP AC230.	No recommended replacement
MM2XKP DC0.75 DC125	No recommended replacement
MM2XKP DC0.75A AC220	No recommended replacement
MM2XKP DC0.75A DC100/110	No recommended replacement
MM2XKP DC100/110 AC100/(110)	No recommended replacement
MM2XKP DC12 DC24.	No recommended replacement
MM2XKP DC1A AC100/(110)	No recommended replacement
MM2XKP DC1A DC100/110	No recommended replacement
MM2XKP DC6	No recommended replacement
MM2XKP-D DC200/220	No recommended replacement
MM3K AC110	No recommended replacement
MM3KP AC115	No recommended replacement
MM3KP AC120.	No recommended replacement
MM3KP DC1A AC100/(110)	No recommended replacement
MM3KP DC1A DC100/110	No recommended replacement
MM3XKP AC110	No recommended replacement
MM3XKP AC3A AC100/(110)	No recommended replacement
MM3XKP DC100/110 AC100/(110)	No recommended replacement
MM3XKP DC1A AC100/(110)	No recommended replacement
MM3XKP DC1A DC100/110	No recommended replacement
MM3XKP DC200/220	No recommended replacement
MM3XKP DC24 AC100/(110)	No recommended replacement
MM3XKP DC2A AC100/(110)	No recommended replacement
MM3XKP DC2A DC100/110	No recommended replacement
MM3XKP DC3A AC100/(110)	No recommended replacement
MM4K AC110 AC50.	No recommended replacement
MM4K DC100/110 DC48	No recommended replacement
MM4KB AC220	No recommended replacement
MM4KB AC230.	No recommended replacement
MM4KP AC100/(110) DC100/110	No recommended replacement
MM4KP AC115	No recommended replacement
MM4KP AC120.	No recommended replacement
MM4KP AC230	No recommended replacement
MM4KP AC240	No recommended replacement
MM4KP DC1.2A AC200/(220)	No recommended replacement
MM4KP DC1A AC100/(110)	No recommended replacement
MM4KP DC1A DC100/110	No recommended replacement
MM4KP-D DC100/110	No recommended replacement
MM4KP-JD AC115	No recommended replacement
MM4KP-JD AC120	No recommended replacement
MM4KP-JK AC115	No recommended replacement
MM4KP-JK DC125	No recommended replacement
MM4KP-JK DC48	No recommended replacement

Product discontinuation	Recommended replacement
MM4KP-NZ17 AC100/(110)	No recommended replacement
MM4KP-NZ17 AC200/(220)	No recommended replacement
MM4KP-NZ17 DC100/110	No recommended replacement
MM4KP-NZ17 DC24	No recommended replacement
MM4KP-NZ17 DC48	No recommended replacement
MM4KP-TC AC200/(220)	No recommended replacement
MM4KP-TC DC100/110	No recommended replacement
MM4XKB AC200/(220) DC24	No recommended replacement
MM4XKB AC220.	No recommended replacement
MM4XKB DC125	No recommended replacement
MM4XKP AC0.75A AC110	No recommended replacement
MM4XKP AC0.75A AC220	No recommended replacement
MM4XKP AC100/(110) DC100/110	No recommended replacement
MM4XKP AC120	No recommended replacement
MM4XKP AC125	No recommended replacement
MM4XKP AC230.	No recommended replacement
MM4XKP DC0.75A AC100/(110)	No recommended replacement
MM4XKP DC0.75A AC200/(220)	No recommended replacement
MM4XKP DC1.2A AC100/(110)	No recommended replacement
MM4XKP DC1.2A DC100/110	No recommended replacement
MM4XKP DC100/110 AC100/(110)	No recommended replacement
MM4XKP DC100/110 AC220	No recommended replacement
MM4XKP DC120	No recommended replacement
MM4XKP DC1A AC100/(110)	No recommended replacement
MM4XKP DC1A AC110	No recommended replacement
MM4XKP DC1A AC200/(220)	No recommended replacement
MM4XKP DC1A DC100/110	No recommended replacement
MM4XKP DC200/220 AC200/(220)	No recommended replacement
MM4XKP DC24 AC220	No recommended replacement
MM4XKP DC2A AC100/(110)	No recommended replacement
MM4XKP DC2A DC100/110	No recommended replacement
MM4XKP DC36	No recommended replacement
MM4XKP DC3A DC100/110	No recommended replacement
MM4XKP-D DC125	No recommended replacement
MM4XKP-D DC200/220	No recommended replacement
MM4XKP-D DC24	No recommended replacement
MM4XKP-D DC48	No recommended replacement
MM4XKP-JD AC110	No recommended replacement
MM4XKP-JK AC100/(110)	No recommended replacement
MM4XKP-JK AC200/(220)	No recommended replacement
MM4XKP-JK DC125	No recommended replacement
MM4XKP-TC DC100/110	No recommended replacement
MM4XKP-TC DC125	No recommended replacement
MM4XKP-TC DC50	No recommended replacement
G7K-412S AC115	No recommended replacement
G7K-412S AC240V	No recommended replacement
G7K-412S-D DC48	No recommended replacement
G7K-422S AC100	No recommended replacement
G7K-422S DC100	No recommended replacement

Product discontinuation	Recommended replacement
G7K-422S DC110	No recommended replacement
MK2P AC0.15A	No recommended replacement
MK2P AC0.4A	No recommended replacement
MK2P AC0.6A	No recommended replacement
MK2P AC0.9A	No recommended replacement
MK2P AC1.1A	No recommended replacement
MK2P AC1.1A 2AB-12	No recommended replacement
MK2P AC1.85A 2AB-15	No recommended replacement
MK2P AC100 100W	No recommended replacement
MK2P AC100 10W	No recommended replacement
MK2P AC100 20W	No recommended replacement
MK2P AC115	No recommended replacement
MK2P AC115 20W	No recommended replacement
MK2P AC115 40W	No recommended replacement
MK2P AC115 60W	No recommended replacement
MK2P AC120	No recommended replacement
MK2P AC1A	No recommended replacement
MK2P AC2.5A	No recommended replacement
MK2P AC200/220 40W	No recommended replacement
MK2P AC200/220 60W	No recommended replacement
MK2P AC230	No recommended replacement
MK2P AC24 40W	No recommended replacement
MK2P AC240	No recommended replacement
MK2P AC2A	No recommended replacement
MK2P AC3.5A	No recommended replacement
MK2P AC48	No recommended replacement
MK2P AC4A	No recommended replacement
MK2P AC5A	No recommended replacement
MK2P DC1.5A	No recommended replacement
MK2P DC1A	No recommended replacement
MK2P DC200	No recommended replacement
MK2P DC220	No recommended replacement
MK2P DC24 20W	No recommended replacement
MK2P DC250MA	No recommended replacement
MK2P DC30	No recommended replacement
MK2P DC350MA	No recommended replacement
MK2P DC380MA	No recommended replacement
MK2P DC500MA	No recommended replacement
MK2P DC60	No recommended replacement
MK2P DC700MA	No recommended replacement
MK2P DC75	No recommended replacement
MK2P DC9	No recommended replacement
MK2P-2 AC/DC100 20W	No recommended replacement
MK2P-2 AC/DC100 40W	No recommended replacement
MK2P-2 AC/DC24 20W	No recommended replacement
MK2P-2 AC/DC24 40W	No recommended replacement
MK2P-2 AC/DC24 60W	No recommended replacement
MK2P-2 AC100 20W	No recommended replacement
MK2P-2 AC100 40W	No recommended replacement

Product discontinuation	Recommended replacement
MK2P-2 AC115	No recommended replacement
MK2P-2 AC12	No recommended replacement
MK2P-2 AC220 65W	No recommended replacement
MK2P-2 DC110	No recommended replacement
MK2P-2 DC125	No recommended replacement
MK2P-2 DC24 20W	No recommended replacement
MK2P-2 DC24 40W	No recommended replacement
MK2P-2-36 DC12	No recommended replacement
MK2P-2-40 AC115	No recommended replacement
MK2P-3 DC12	No recommended replacement
MK2P-50 DC48	No recommended replacement
MK2P-JN AC100	No recommended replacement
MK2P-JN DC24	No recommended replacement
MK2P-TC DC24	No recommended replacement
MK2P-US AC120	No recommended replacement
MK2P-US AC230	No recommended replacement
MK2P2-36 DC24	No recommended replacement
MK2P2-40 DC24	No recommended replacement
MK2PA AC200	No recommended replacement
MK2PA AC220	No recommended replacement
MK2PA DC110	No recommended replacement
MK2PA-2 DC24	No recommended replacement
MK2PN AC115	No recommended replacement
MK2PN DC125	No recommended replacement
MK2PN DC200	No recommended replacement
MK2PN-2 AC100	No recommended replacement
MK2PN-2 AC200	No recommended replacement
MK2PN-2 AC24	No recommended replacement
MK2PN-2 DC100	No recommended replacement
MK2PN-2 DC12	No recommended replacement
MK2PN-2 DC24	No recommended replacement
MK2PN-2 DC48	No recommended replacement
MK2PN-2 DC6	No recommended replacement
MK2PN-DO DC100	No recommended replacement
MK2PN-DO DC24	No recommended replacement
MK2PN-DO DC48	No recommended replacement
MK2ZP AC115	No recommended replacement
MK2ZP DC125	No recommended replacement
MK2ZP-2 DC100	No recommended replacement
MK2ZP-2 DC12	No recommended replacement
MK2ZP-DO AC220	No recommended replacement
MK2ZP-DO DC24	No recommended replacement
MK2ZP-US AC115	No recommended replacement
MK2ZPN AC100	No recommended replacement
MK2ZPN AC12	No recommended replacement
MK2ZPN AC200	No recommended replacement
MK2ZPN AC200/220	No recommended replacement
MK2ZPN AC24	No recommended replacement
MK2ZPN DC24	No recommended replacement

Product discontinuation	Recommended replacement
MK2ZPN DC48	No recommended replacement
MK2ZPN-2 AC100/110	No recommended replacement
MK2ZPN-2 DC24	No recommended replacement
MK2ZPN-DO AC100/110	No recommended replacement
MK2ZPN-DO DC110	No recommended replacement
MK2ZPN-DO DC24	No recommended replacement
MK2ZPN-DO DC48	No recommended replacement
MK3LP AC100	No recommended replacement
MK3LP AC200	No recommended replacement
MK3LP DC110	No recommended replacement
MK3LP-2 DC12	No recommended replacement
MK3LP-2 DC24	No recommended replacement
MK3LP-5 AC24	No recommended replacement
MK3LP-5 DC10	No recommended replacement
MK3LPN AC100	No recommended replacement
MK3LPN AC200	No recommended replacement
MK3LPN DC100	No recommended replacement
MK3LPN DC24	No recommended replacement
MK3LPN-2 AC100/(110)	No recommended replacement
MK3LPN-SQ AC100/110	No recommended replacement
MK3LPN-SQ AC200/220	No recommended replacement
MK3LPN-SQ DC110	No recommended replacement
MK3P AC100 40W	No recommended replacement
MK3P AC100 60W	No recommended replacement
MK3P AC115	No recommended replacement
MK3P AC115 40W	No recommended replacement
MK3P AC120	No recommended replacement
MK3P AC17	No recommended replacement
MK3P AC230	No recommended replacement
MK3P AC240	No recommended replacement
MK3P AC48	No recommended replacement
MK3P DC24 20W	No recommended replacement
MK3P DC24 40W	No recommended replacement
MK3P DC24 60W	No recommended replacement
MK3P DC60	No recommended replacement
MK3P-13 DC100	No recommended replacement
MK3P-13 DC24	No recommended replacement
MK3P-2 AC110	No recommended replacement
MK3P-2 AC115	No recommended replacement
MK3P-2 AC48	No recommended replacement
MK3P-2 DC125	No recommended replacement
MK3P-4 AC24	No recommended replacement
MK3P-4 DC24	No recommended replacement
MK3P-5 AC220	No recommended replacement
MK3P-5 AC240	No recommended replacement
MK3P-5 AC36	No recommended replacement
MK3P-AP DC100	No recommended replacement
MK3P-DO AC100/110	No recommended replacement
MK3P-TC AC100	No recommended replacement

Product discontinuation	Recommended replacement
MK3P-TC DC24	No recommended replacement
MK3P-US AC100	No recommended replacement
MK3P-US AC115	No recommended replacement
MK3P-US AC120	No recommended replacement
MK3P-US DC110	No recommended replacement
MK3P5-US AC100/(110)	No recommended replacement
MK3P5-US DC12	No recommended replacement
MK3PA AC100	No recommended replacement
MK3PA AC110	No recommended replacement
MK3PA AC200	No recommended replacement
MK3PA DC110	No recommended replacement
MK3PA-2 DC24	No recommended replacement
MK3PA-D DC24	No recommended replacement
MK3PAD DC100	No recommended replacement
MK3PAD DC12	No recommended replacement
MK3PAD-40 DC110	No recommended replacement
MK3PAD-40 DC24	No recommended replacement
MK3PN AC115	No recommended replacement
MK3PN AC240	No recommended replacement
MK3PN AC36	No recommended replacement
MK3PN DC125	No recommended replacement
MK3PN DC200	No recommended replacement
MK3PN-2 AC100	No recommended replacement
MK3PN-2 AC200	No recommended replacement
MK3PN-2 AC200/(220)	No recommended replacement
MK3PN-2 DC48	No recommended replacement
MK3PN-2 DC6	No recommended replacement
MK3PN-5 AC100	No recommended replacement
MK3PN-5 AC200	No recommended replacement
MK3PN-5 AC24	No recommended replacement
MK3PN-5 AC42	No recommended replacement
MK3PN-5 DC24	No recommended replacement
MK3PN-AP DC110	No recommended replacement
MK3PN-AP DC24	No recommended replacement
MK3PN-DO AC100/110	No recommended replacement
MK3PN-DO AC200/(220)	No recommended replacement
MK3PN-DO DC100	No recommended replacement
MK3PN-DO DC110	No recommended replacement
MK3PN-DO DC48	No recommended replacement
MK3PN-SQ AC100/110	No recommended replacement
MK3PN-TC AC100/110	No recommended replacement
MK3PN-TC AC200/(220)	No recommended replacement
MK3PN-TC AC220	No recommended replacement
MK3PN-TC DC24	No recommended replacement
MK3ZP AC115	No recommended replacement
MK3ZP AC115 60W	No recommended replacement
MK3ZP AC120	No recommended replacement
MK3ZP AC200	No recommended replacement
MK3ZP AC240	No recommended replacement

Product discontinuation	Recommended replacement
MK3ZP DC110	No recommended replacement
MK3ZP DC125	No recommended replacement
MK3ZP-2 AC100	No recommended replacement
MK3ZP-2 AC12	No recommended replacement
MK3ZP-2 AC200	No recommended replacement
MK3ZP-2 DC110	No recommended replacement
MK3ZP-2-US DC24	No recommended replacement
MK3ZP-5 DC110	No recommended replacement
MK3ZP-AP AC100/110	No recommended replacement
MK3ZP-AP DC24	No recommended replacement
MK3ZP-DO DC100	No recommended replacement
MK3ZP-DO DC24	No recommended replacement
MK3ZP-PG AC100	No recommended replacement
MK3ZP-TC AC100/(110)	No recommended replacement
MK3ZP-TC DC100	No recommended replacement
MK3ZP-TC DC110	No recommended replacement
MK3ZP-TC DC24	No recommended replacement
MK3ZP2-TC AC100/(110)	No recommended replacement
MK3ZPA AC100/(110)	No recommended replacement
MK3ZPN AC200	No recommended replacement
MK3ZPN DC100/110	No recommended replacement
MK3ZPN DC12	No recommended replacement
MK3ZPN DC48	No recommended replacement
MK3ZPN-2 AC200	No recommended replacement
MK3ZPN-2 AC24	No recommended replacement
MK3ZPN-2 DC100	No recommended replacement
MK3ZPN-2 DC110	No recommended replacement
MK3ZPN-2 DC24	No recommended replacement
MK3ZPN-2 DC48	No recommended replacement
MK3ZPN-AP AC100	No recommended replacement
MK3ZPN-AP AC200	No recommended replacement
MK3ZPN-DO AC100/110	No recommended replacement
MK3ZPN-DO DC24	No recommended replacement
MK3ZPN-SQ AC200/220	No recommended replacement
MK3ZPN2-SQ AC100/110	No recommended replacement
MK3ZPN2-TB AC100	No recommended replacement
MK3ZPN2-TB AC200	No recommended replacement
MK3ZPN2-TB DC24	No recommended replacement
MK2KP AC100 DC100	No recommended replacement
MK2KP AC100 DC24	No recommended replacement
MK2KP AC100 DC6	No recommended replacement
MK2KP AC115	No recommended replacement
MK2KP AC120	No recommended replacement
MK2KP-40 AC100/(110)	No recommended replacement
MK2KP-41 DC48	No recommended replacement
MK2KP-AP DC110	No recommended replacement
MK2KP-DO DC24	No recommended replacement
MK2KP-TC AC110	No recommended replacement
MK2KP-TC AC120	No recommended replacement

Product discontinuation	Recommended replacement
MK2KP-TC AC200/(220)	No recommended replacement
MK2KP-TC AC220	No recommended replacement
MK2KPD AC100	No recommended replacement
MK2KPD AC100 RL786	No recommended replacement
MK2KPD DC24	No recommended replacement
G7T-1012S AC100/110 BY OMZ	No recommended replacement
G7T-1012S AC200/220 BY OMZ	No recommended replacement
G7T-1012S DC100/110 BY OMZ	No recommended replacement
G7T-1012S DC48 BY OMZ	No recommended replacement
G7T-1022S AC100/110 BY OMZ	No recommended replacement
G7T-1022S AC200/220 BY OMZ	No recommended replacement
G7T-1022S DC24 BY OMZ	No recommended replacement
G7T-1112S AC110/120 BY OMZ	No recommended replacement
G7T-1112S AC200/220 BY OMZ	No recommended replacement
G7T-1112S DC100/110 BY OMZ	No recommended replacement
G7T-1112S DC48 BY OMZ	No recommended replacement
G7T-1122S AC110/120 BY OMZ	No recommended replacement
G7T-1122S AC220/240 BY OMZ	No recommended replacement
G7T-1122S AC24 BY OMZ	No recommended replacement
G7T-1122S DC125 BY OMZ	No recommended replacement
G7T-112S AC100/110 BY OMZ	No recommended replacement
G7T-112S AC200/220 BY OMZ	No recommended replacement
G7T-112S DC100/110 BY OMZ	No recommended replacement
G7T-112S DC48 BY OMZ	No recommended replacement
P70A AC110/120	No recommended replacement
LY1 DC6	No recommended replacement
LY1-0 AC220/240	No recommended replacement
LY1-0 AC6	No recommended replacement
LY1-0 DC100/110	No recommended replacement
LY1-0-VD AC220	No recommended replacement
LY1-0-VD AC220/240	No recommended replacement
LY1-0-VD-US AC220	No recommended replacement
LY1-C DC24	No recommended replacement
LY1-CR AC100/110	No recommended replacement
LY1-CR AC200/220	No recommended replacement
LY1-D-TU DC12	No recommended replacement
LY1-FD AC100/110	No recommended replacement
LY1-FD AC200/220	No recommended replacement
LY1-VD DC12	No recommended replacement
LY1-VD-US DC24	No recommended replacement
LY1F AC12	No recommended replacement
LY1F AC50	No recommended replacement
LY1F-FD AC100/110	No recommended replacement
LY1F-FD AC200/220	No recommended replacement
LY1F-T2 AC200/220	No recommended replacement
LY1F-T2 AC24	No recommended replacement
LY1F-VD-US AC110	No recommended replacement
LY1N AC6	No recommended replacement
LY1N-CR AC100/110	No recommended replacement

Product discontinuation	Recommended replacement
LY1N-CR AC200/220	No recommended replacement
LY1S AC110/120	No recommended replacement
LY1S AC220/240	No recommended replacement
LY2 AC0.35A	No recommended replacement
LY2 AC6	No recommended replacement
LY2 DC36	No recommended replacement
LY2 DC90	No recommended replacement
LY2-0 DC6	No recommended replacement
LY2-0-C DC12	No recommended replacement
LY2-0-C DC24	No recommended replacement
LY2-0-VD-US AC220	No recommended replacement
LY2-0-VD-US AC24	No recommended replacement
LY2-0-VD-US DC24	No recommended replacement
LY2-C DC6	No recommended replacement
LY2-CR AC110/120	No recommended replacement
LY2-CR AC220/240	No recommended replacement
LY2-D DC32	No recommended replacement
LY2-FD AC100/110	No recommended replacement
LY2-FD AC200/220	No recommended replacement
LY2-FD DC24	No recommended replacement
LY2-FD DC6	No recommended replacement
LY2-MT AC100	No recommended replacement
LY2-MT DC12	No recommended replacement
LY2-MT DC24	No recommended replacement
LY2-TU DC100/110	No recommended replacement
LY2-TU DC24	No recommended replacement
LY2-US-006530 DC24	No recommended replacement
LY2-VD AC220	No recommended replacement
LY2-VD DC24	No recommended replacement
LY2-VD-US AC24	No recommended replacement
LY2F AC6	No recommended replacement
LY2F DC6	No recommended replacement
LY2F-D DC48	No recommended replacement
LY2F-DI2 AC220/240	No recommended replacement
LY2F-T2 AC110/120	No recommended replacement
LY2F-T2 AC24	No recommended replacement
LY2F-T2 DC12	No recommended replacement
LY2F-VD-US AC110	No recommended replacement
LY2F-Y90 AC200/220	No recommended replacement
LY2IN AC100/110	No recommended replacement
LY2IN AC200/220	No recommended replacement
LY2IN AC220/240	No recommended replacement
LY2IN DC100/110	No recommended replacement
LY2IN DC125	No recommended replacement
LY2IN DC24	No recommended replacement
LY2IN-D2 DC125	No recommended replacement
LY2N AC6	No recommended replacement
LY2N DC125	No recommended replacement
LY2N DC6	No recommended replacement

Product discontinuation	Recommended replacement
LY2N-CR-TU AC100/110	No recommended replacement
LY2N-D2 DC125	No recommended replacement
LY2N-D2-TU DC24	No recommended replacement
LY2N-FD AC24	No recommended replacement
LY2N-TU AC100/110	No recommended replacement
LY2N-TU AC200/220	No recommended replacement
LY2N-TU DC24	No recommended replacement
LY2S AC100/110	No recommended replacement
LY2S AC200/220	No recommended replacement
LY2S AC220/240	No recommended replacement
LY2S AC24	No recommended replacement
LY2Z AC110/120	No recommended replacement
LY2Z AC12	No recommended replacement
LY2Z AC220/240	No recommended replacement
LY2Z AC24	No recommended replacement
LY2Z DC125	No recommended replacement
LY2Z DC6	No recommended replacement
LY2Z-D DC100/110	No recommended replacement
LY2ZF AC220/240	No recommended replacement
LY2ZF-D DC12	No recommended replacement
LY2ZF-D DC24	No recommended replacement
LY2ZI AC110/120	No recommended replacement
LY3 AC115	No recommended replacement
LY3 AC6	No recommended replacement
LY3 DC30	No recommended replacement
LY3 DC6	No recommended replacement
LY3-0 DC6	No recommended replacement
LY3-0-US-SV DC12	No recommended replacement
LY3-C DC24	No recommended replacement
LY3-D DC6	No recommended replacement
LY3F DC6	No recommended replacement
LY3F-Y90 AC200/220	No recommended replacement
LY3N AC120	No recommended replacement
LY3N AC50	No recommended replacement
LY3S AC24	No recommended replacement
LY4 AC120	No recommended replacement
LY4 AC240	No recommended replacement
LY4 AC42	No recommended replacement
LY4 AC6	No recommended replacement
LY4 DC125	No recommended replacement
LY4 DC30	No recommended replacement
LY4 DC6	No recommended replacement
LY4 DC60	No recommended replacement
LY4-0 AC12	No recommended replacement
LY4-0 AC6	No recommended replacement
LY4-D DC6	No recommended replacement
LY4-MT DC12	No recommended replacement
LY4F AC230	No recommended replacement
LY4F-Y90 AC200/220	No recommended replacement

Product discontinuation	Recommended replacement
LY4N AC115	No recommended replacement
LY4N AC50	No recommended replacement
LY4N AC6	No recommended replacement
LY4N DC125	No recommended replacement
LY4N DC6	No recommended replacement
LY1 AC220/240 BY OMI	No recommended replacement
LY1 AC32 BY OMI	No recommended replacement
LY1 AC48 BY OMI	No recommended replacement
LY1 AC50 BY OMI	No recommended replacement
LY1 AC6 BY OMI	No recommended replacement
LY1 DC6 BY OMI	No recommended replacement
LY1-0 AC12 BY OMI	No recommended replacement
LY1-0 AC220/240 BY OMI	No recommended replacement
LY1-0 AC48 BY OMI	No recommended replacement
LY1-0 AC50 BY OMI	No recommended replacement
LY1-0 AC6 BY OMI	No recommended replacement
LY1-0 DC100/110 BY OMI	No recommended replacement
LY1-0 DC48 BY OMI	No recommended replacement
LY1-0 DC6 BY OMI	No recommended replacement
LY1-0-EU AC110/120 BY OMI	No recommended replacement
LY1-0-EU AC220/240 BY OMI	No recommended replacement
LY1-0-EU AC24 BY OMI	No recommended replacement
LY1-0-EU DC12 BY OMI	No recommended replacement
LY1-0-EU DC24 BY OMI	No recommended replacement
LY1-0-T130 DC24 BY OMI	No recommended replacement
LY1F AC12 BY OMI	No recommended replacement
LY1F AC220/240-PL BY OMI	No recommended replacement
LY1F AC220/240-WCI BY OMI	No recommended replacement
LY1F AC48 BY OMI	No recommended replacement
LY1F AC50 BY OMI	No recommended replacement
LY1F AC6 BY OMI	No recommended replacement
LY1F DC48 BY OMI	No recommended replacement
LY1F-ADB AC220 BY OMI	No recommended replacement
LY1F-EU AC110/120 BY OMI	No recommended replacement
LY1F-EU AC200/220 BY OMI	No recommended replacement
LY1F-EU AC220/240 BY OMI	No recommended replacement
LY1F-EU AC24 BY OMI	No recommended replacement
LY1F-EU DC12 BY OMI	No recommended replacement
LY1F-EU DC24 BY OMI	No recommended replacement
LY1F-MAQ AC110/120 BY OMI	No recommended replacement
LY1F-MAQ AC220/240 BY OMI	No recommended replacement
LY1F-MAQ1 AC115 BY OMI	No recommended replacement
LY1F-MAQ1 AC208/230 BY OMI	No recommended replacement
LY1F-MAQ1 AC220/240 BY OMI	No recommended replacement
LY1F-T105 AC220/240 BY OMI	No recommended replacement
LY1F-WCI2 AC220/240 BY OMI	No recommended replacement
LY1I4 AC100/110 BY OMI	No recommended replacement
LY1I4 AC110/120 BY OMI	No recommended replacement
LY1I4 AC12 BY OMI	No recommended replacement

Product discontinuation	Recommended replacement
LY1I4 AC200/220 BY OMI	No recommended replacement
LY1I4 AC220/240 BY OMI	No recommended replacement
LY1I4 AC24 BY OMI	No recommended replacement
LY1I4 AC50 BY OMI	No recommended replacement
LY1I4 AC6 BY OMI	No recommended replacement
LY1I4 DC100/110 BY OMI	No recommended replacement
LY1I4 DC12 BY OMI	No recommended replacement
LY1I4 DC24 BY OMI	No recommended replacement
LY1I4 DC48 BY OMI	No recommended replacement
LY1I4 DC6 BY OMI	No recommended replacement
LY1N AC220/240 BY OMI	No recommended replacement
LY1N AC6 BY OMI	No recommended replacement
LY1N DC6 BY OMI	No recommended replacement
LY2 AC110/120-PL BY OMI	No recommended replacement
LY2 AC12-PL BY OMI	No recommended replacement
LY2 AC138 BY OMI	No recommended replacement
LY2 AC220/240-PL BY OMI	No recommended replacement
LY2 AC24-PL BY OMI	No recommended replacement
LY2 AC32 BY OMI	No recommended replacement
LY2 AC42 BY OMI	No recommended replacement
LY2 AC48 BY OMI	No recommended replacement
LY2 AC48-PL BY OMI	No recommended replacement
LY2 AC50 BY OMI	No recommended replacement
LY2 AC6 BY OMI	No recommended replacement
LY2 AC6-PL BY OMI	No recommended replacement
LY2 AC60 BY OMI	No recommended replacement
LY2 DC100/110-PL BY OMI	No recommended replacement
LY2 DC12-PL BY OMI	No recommended replacement
LY2 DC120 BY OMI	No recommended replacement
LY2 DC14 BY OMI	No recommended replacement
LY2 DC15 BY OMI	No recommended replacement
LY2 DC24-PL BY OMI	No recommended replacement
LY2 DC32 BY OMI	No recommended replacement
LY2 DC48-PL BY OMI	No recommended replacement
LY2 DC6 BY OMI	No recommended replacement
LY2 DC6-PL BY OMI	No recommended replacement
LY2 DC60 BY OMI	No recommended replacement
LY2 DC9 BY OMI	No recommended replacement
LY2-0 AC48 BY OMI	No recommended replacement
LY2-0 AC50 BY OMI	No recommended replacement
LY2-0 AC6 BY OMI	No recommended replacement
LY2-0 DC12-PL BY OMI	No recommended replacement
LY2-0 DC24-PL BY OMI	No recommended replacement
LY2-0 DC6 BY OMI	No recommended replacement
LY2-0 DC9 BY OMI	No recommended replacement
LY2-0-20 AC24 BY OMI	No recommended replacement
LY2-0-ABB AC220/240 BY OMI	No recommended replacement
LY2-0-AP DC12 BY OMI	No recommended replacement
LY2-0-AP10 DC12 BY OMI	No recommended replacement

Product discontinuation	Recommended replacement
LY2-0-AP3 DC12 BY OMI	No recommended replacement
LY2-0-EU AC100/110 BY OMI	No recommended replacement
LY2-0-EU AC110/120 BY OMI	No recommended replacement
LY2-0-EU AC200/220 BY OMI	No recommended replacement
LY2-0-EU AC220/240 BY OMI	No recommended replacement
LY2-0-EU AC24 BY OMI	No recommended replacement
LY2-0-EU DC100/110 BY OMI	No recommended replacement
LY2-0-EU DC12 BY OMI	No recommended replacement
LY2-0-EU DC24 BY OMI	No recommended replacement
LY2-0-EU DC48 BY OMI	No recommended replacement
LY2-0-EU DC6 BY OMI	No recommended replacement
LY2-0-FD DC24 BY OMI	No recommended replacement
LY2-0-MAQ AC220/240 BY OMI	No recommended replacement
LY2-0-T130 DC12 BY OMI	No recommended replacement
LY2-0-T130 DC24 BY OMI	No recommended replacement
LY2-0-TV3 DC12 BY OMI	No recommended replacement
LY2-AP DC24 BY OMI	No recommended replacement
LY2-AP10 AC220 BY OMI	No recommended replacement
LY2-AP10 DC12 BY OMI	No recommended replacement
LY2-JF BY OMI	No recommended replacement
LY2-SEV AC220 BY OMI	No recommended replacement
LY2-T130 DC24 BY OMI	No recommended replacement
LY2-US-G-SV AC200/220 BY OMI	No recommended replacement
LY2F AC208/230 BY OMI	No recommended replacement
LY2F AC220/240-PL BY OMI	No recommended replacement
LY2F AC24 FOR OCB-MY BY OMI(OY	No recommended replacement
LY2F AC48 BY OMI	No recommended replacement
LY2F AC50 BY OMI	No recommended replacement
LY2F AC6 BY OMI	No recommended replacement
LY2F DC12-PL BY OMI	No recommended replacement
LY2F DC6 BY OMI	No recommended replacement
LY2F-1 AC100 BY OMI	No recommended replacement
LY2F-AP3 AC110/120 BY OMI	No recommended replacement
LY2F-AP3 AC24 BY OMI	No recommended replacement
LY2F-DI2 AC220/240 BY OMI	No recommended replacement
LY2F-EU AC110/120 BY OMI	No recommended replacement
LY2F-EU AC12 BY OMI	No recommended replacement
LY2F-EU AC200/220 BY OMI	No recommended replacement
LY2F-EU AC220/240 BY OMI	No recommended replacement
LY2F-EU AC24 BY OMI	No recommended replacement
LY2F-EU DC12 BY OMI	No recommended replacement
LY2F-EU DC24 BY OMI	No recommended replacement
LY2F-EU DC48 BY OMI	No recommended replacement
LY2F-FD AC110/120 BY OMI	No recommended replacement
LY2F-FD AC24 BY OMI	No recommended replacement
LY2F-FD DC24 BY OMI	No recommended replacement
LY2F-MAQ AC110/120 BY OMI	No recommended replacement
LY2F-MAQ1 AC110/120 BY OMI	No recommended replacement
LY2I4 AC100/110 BY OMI	No recommended replacement

Product discontinuation	Recommended replacement
LY2I4 AC110/120 BY OMI	No recommended replacement
LY2I4 AC12 BY OMI	No recommended replacement
LY2I4 AC200/220 BY OMI	No recommended replacement
LY2I4 AC220/240 BY OMI	No recommended replacement
LY2I4 AC24 BY OMI	No recommended replacement
LY2I4 AC50 BY OMI	No recommended replacement
LY2I4 AC6 BY OMI	No recommended replacement
LY2I4 DC100/110 BY OMI	No recommended replacement
LY2I4 DC12 BY OMI	No recommended replacement
LY2I4 DC24 BY OMI	No recommended replacement
LY2I4 DC48 BY OMI	No recommended replacement
LY2I4 DC6 BY OMI	No recommended replacement
LY2I4-0 DC24 BY OMI	No recommended replacement
LY2I4N AC100/110 BY OMI	No recommended replacement
LY2I4N AC110/120 BY OMI	No recommended replacement
LY2I4N AC12 BY OMI	No recommended replacement
LY2I4N AC200/220 BY OMI	No recommended replacement
LY2I4N AC50 BY OMI	No recommended replacement
LY2I4N AC6 BY OMI	No recommended replacement
LY2I4N DC100/110 BY OMI	No recommended replacement
LY2I4N DC12 BY OMI	No recommended replacement
LY2I4N DC48 BY OMI	No recommended replacement
LY2I4N DC6 BY OMI	No recommended replacement
LY2I4N-D2 DC24 BY OMI	No recommended replacement
LY2N AC220/240-PL BY OMI	No recommended replacement
LY2N AC24-PL BY OMI	No recommended replacement
LY2N AC32 BY OMI	No recommended replacement
LY2N AC48 BY OMI	No recommended replacement
LY2N AC50 BY OMI	No recommended replacement
LY2N AC6 BY OMI	No recommended replacement
LY2N DC24-PL BY OMI	No recommended replacement
LY2N DC32 BY OMI	No recommended replacement
LY2N DC6 BY OMI	No recommended replacement
LY3 AC100/110-PL BY OMI	No recommended replacement
LY3 AC110/120 BY OMI	No recommended replacement
LY3 AC200/220-PL BY OMI	No recommended replacement
LY3 AC220/240 BY OMI	No recommended replacement
LY3 AC230 BY OMI	No recommended replacement
LY3 AC240 BY OMI	No recommended replacement
LY3 AC32 BY OMI	No recommended replacement
LY3 AC48 BY OMI	No recommended replacement
LY3 AC50 BY OMI	No recommended replacement
LY3 AC6 BY OMI.	No recommended replacement
LY3 DC125 BY OMI	No recommended replacement
LY3 DC24-PL BY OMI	No recommended replacement
LY3 DC5 BY OMI	No recommended replacement
LY3 DC6 BY OMI	No recommended replacement
LY3 DC60 BY OMI	No recommended replacement
LY3-0 AC12 BY OMI	No recommended replacement

Product discontinuation	Recommended replacement
LY3-0 AC120 BY OMI	No recommended replacement
LY3-0 AC230 BY OMI	No recommended replacement
LY3-0 AC240 BY OMI	No recommended replacement
LY3-0 AC48 BY OMI	No recommended replacement
LY3-0 AC50 BY OMI	No recommended replacement
LY3-0 AC6 BY OMI	No recommended replacement
LY3-0 DC6 BY OMI	No recommended replacement
LY3-0-AP AC12 BY OMI	No recommended replacement
LY3-0-EU AC120 BY OMI	No recommended replacement
LY3-0-EU AC200/220 BY OMI	No recommended replacement
LY3-0-EU AC24 BY OMI	No recommended replacement
LY3-0-EU AC240 BY OMI	No recommended replacement
LY3-0-EU DC100/110 BY OMI	No recommended replacement
LY3-0-EU DC12 BY OMI	No recommended replacement
LY3-0-EU DC24 BY OMI	No recommended replacement
LY3-0-EU DC48 BY OMI	No recommended replacement
LY3-0-EU DC6 BY OMI	No recommended replacement
LY3-AP10 AC200/220 BY OMI	No recommended replacement
LY3F AC120 BY OMI	No recommended replacement
LY3F AC220/240 BY OMI	No recommended replacement
LY3F AC48 BY OMI	No recommended replacement
LY3F AC50 BY OMI	No recommended replacement
LY3F AC6 BY OMI	No recommended replacement
LY3F DC48 BY OMI	No recommended replacement
LY3F DC5 BY OMI	No recommended replacement
LY3F DC6 BY OMI	No recommended replacement
LY3F DC60 BY OMI	No recommended replacement
LY3F-EU AC120 BY OMI	No recommended replacement
LY3F-EU AC24 BY OMI	No recommended replacement
LY3F-EU AC240 BY OMI	No recommended replacement
LY3F-EU DC12 BY OMI	No recommended replacement
LY3F-EU DC24 BY OMI	No recommended replacement
LY3F-FD AC24 BY OMI	No recommended replacement
LY3I4 AC100/110 BY OMI	No recommended replacement
LY3I4 AC110/120 BY OMI	No recommended replacement
LY3I4 AC12 BY OMI	No recommended replacement
LY3I4 AC200/220 BY OMI	No recommended replacement
LY3I4 AC230 BY OMI	No recommended replacement
LY3I4 AC24 BY OMI	No recommended replacement
LY3I4 AC240 BY OMI	No recommended replacement
LY3I4 AC50 BY OMI	No recommended replacement
LY3I4 AC6 BY OMI	No recommended replacement
LY3I4 DC100/110 BY OMI	No recommended replacement
LY3I4 DC12 BY OMI	No recommended replacement
LY3I4 DC24 BY OMI	No recommended replacement
LY3I4 DC48 BY OMI	No recommended replacement
LY3I4 DC6 BY OMI	No recommended replacement
LY3I4N AC110/120 BY OMI	No recommended replacement
LY3I4N AC12 BY OMI	No recommended replacement

Product discontinuation	Recommended replacement
LY3I4N AC24 BY OMI	No recommended replacement
LY3I4N AC240 BY OMI	No recommended replacement
LY3I4N AC6 BY OMI	No recommended replacement
LY3I4N DC100/110 BY OMI	No recommended replacement
LY3I4N DC12 BY OMI	No recommended replacement
LY3I4N DC24 BY OMI	No recommended replacement
LY3I4N DC48 BY OMI	No recommended replacement
LY3I4N DC6 BY OMI	No recommended replacement
LY3N AC120 BY OMI	No recommended replacement
LY3N AC220/240 BY OMI	No recommended replacement
LY3N AC230 BY OMI	No recommended replacement
LY3N AC240 BY OMI	No recommended replacement
LY3N AC50 BY OMI	No recommended replacement
LY3N AC6 BY OMI	No recommended replacement
LY3N DC16 BY OMI	No recommended replacement
LY3N DC6 BY OMI	No recommended replacement
LY4 AC100/110-PL BY OMI	No recommended replacement
LY4 AC110/120 BY OMI	No recommended replacement
LY4 AC200/220-PL BY OMI	No recommended replacement
LY4 AC220/240 BY OMI	No recommended replacement
LY4 AC24-PL BY OMI	No recommended replacement
LY4 AC32 BY OMI	No recommended replacement
LY4 AC42 BY OMI	No recommended replacement
LY4 AC48 BY OMI	No recommended replacement
LY4 AC48-PL BY OMI	No recommended replacement
LY4 AC50 BY OMI	No recommended replacement
LY4 AC6 BY OMI	No recommended replacement
LY4 DC100/110-PL BY OMI	No recommended replacement
LY4 DC12-PL BY OMI	No recommended replacement
LY4 DC120 BY OMI	No recommended replacement
LY4 DC125 BY OMI	No recommended replacement
LY4 DC24-PL BY OMI	No recommended replacement
LY4 DC32 BY OMI	No recommended replacement
LY4 DC36 BY OMI	No recommended replacement
LY4 DC48-PL BY OMI	No recommended replacement
LY4 DC5 BY OMI	No recommended replacement
LY4 DC6 BY OMI	No recommended replacement
LY4 DC60 BY OMI	No recommended replacement
LY4-0 AC110/120 BY OMI	No recommended replacement
LY4-0 AC12 BY OMI	No recommended replacement
LY4-0 AC120 BY OMI	No recommended replacement
LY4-0 AC220/240 BY OMI	No recommended replacement
LY4-0 AC230 BY OMI	No recommended replacement
LY4-0 AC240 BY OMI	No recommended replacement
LY4-0 AC42 BY OMI	No recommended replacement
LY4-0 AC48 BY OMI	No recommended replacement
LY4-0 AC50 BY OMI	No recommended replacement
LY4-0 AC6 BY OMI	No recommended replacement
LY4-0 DC125 BY OMI	No recommended replacement

Product discontinuation	Recommended replacement
LY4-0 DC24-PL BY OMI	No recommended replacement
LY4-0 DC36 BY OMI	No recommended replacement
LY4-0 DC6 BY OMI	No recommended replacement
LY4-0-AP AC12 BY OMI	No recommended replacement
LY4-0-EU AC120 BY OMI	No recommended replacement
LY4-0-EU AC200/220 BY OMI	No recommended replacement
LY4-0-EU AC230 BY OMI	No recommended replacement
LY4-0-EU AC24 BY OMI	No recommended replacement
LY4-0-EU AC240 BY OMI	No recommended replacement
LY4-0-EU DC100/110 BY OMI	No recommended replacement
LY4-0-EU DC12 BY OMI	No recommended replacement
LY4-0-EU DC24 BY OMI	No recommended replacement
LY4-0-EU DC48 BY OMI	No recommended replacement
LY4-1 AC100/110 BY OMI	No recommended replacement
LY4-1 AC12 BY OMI	No recommended replacement
LY4-1 AC120 BY OMI	No recommended replacement
LY4-1 AC200/220 BY OMI	No recommended replacement
LY4-1 AC24 BY OMI	No recommended replacement
LY4-1 AC240 BY OMI	No recommended replacement
LY4-1 AC32 BY OMI	No recommended replacement
LY4-1 AC50 BY OMI	No recommended replacement
LY4-1 AC6 BY OMI	No recommended replacement
LY4-1 DC100/110 BY OMI	No recommended replacement
LY4-1 DC12 BY OMI	No recommended replacement
LY4-1 DC24 BY OMI	No recommended replacement
LY4-1 DC32 BY OMI	No recommended replacement
LY4-1 DC48 BY OMI	No recommended replacement
LY4-1 DC6 BY OMI	No recommended replacement
LY4-JF BY OMI	No recommended replacement
LY4F AC100/110 BY OMI	No recommended replacement
LY4F AC12 BY OMI	No recommended replacement
LY4F AC120 BY OMI	No recommended replacement
LY4F AC200/220 BY OMI	No recommended replacement
LY4F AC24 BY OMI	No recommended replacement
LY4F AC240 BY OMI	No recommended replacement
LY4F AC48 BY OMI	No recommended replacement
LY4F AC50 BY OMI	No recommended replacement
LY4F AC6 BY OMI	No recommended replacement
LY4F DC100/110 BY OMI	No recommended replacement
LY4F DC12 BY OMI	No recommended replacement
LY4F DC24 BY OMI	No recommended replacement
LY4F DC48 BY OMI	No recommended replacement
LY4F DC6 BY OMI	No recommended replacement
LY4F-EU AC120 BY OMI	No recommended replacement
LY4F-EU AC24 BY OMI	No recommended replacement
LY4F-EU AC240 BY OMI	No recommended replacement
LY4F-EU DC12 BY OMI	No recommended replacement
LY4F-EU DC24 BY OMI	No recommended replacement
LY4F-EU DC48 BY OMI	No recommended replacement

Product discontinuation	Recommended replacement
LY4I4 AC100/110 BY OMI	No recommended replacement
LY4I4 AC110/120 BY OMI	No recommended replacement
LY4I4 AC12 BY OMI	No recommended replacement
LY4I4 AC200/220 BY OMI	No recommended replacement
LY4I4 AC230 BY OMI	No recommended replacement
LY4I4 AC24 BY OMI	No recommended replacement
LY4I4 AC240 BY OMI	No recommended replacement
LY4I4 AC50 BY OMI	No recommended replacement
LY4I4 AC6 BY OMI	No recommended replacement
LY4I4 DC100/110 BY OMI	No recommended replacement
LY4I4 DC12 BY OMI	No recommended replacement
LY4I4 DC24 BY OMI	No recommended replacement
LY4I4 DC48 BY OMI	No recommended replacement
LY4I4 DC6 BY OMI	No recommended replacement
LY4I4N AC100/110 BY OMI	No recommended replacement
LY4I4N AC110/120 BY OMI	No recommended replacement
LY4I4N AC12 BY OMI	No recommended replacement
LY4I4N AC200/220 BY OMI	No recommended replacement
LY4I4N AC230 BY OMI	No recommended replacement
LY4I4N AC24 BY OMI	No recommended replacement
LY4I4N AC240 BY OMI	No recommended replacement
LY4I4N AC48 BY OMI	No recommended replacement
LY4I4N AC50 BY OMI	No recommended replacement
LY4I4N AC6 BY OMI	No recommended replacement
LY4I4N DC100/110 BY OMI	No recommended replacement
LY4I4N DC12 BY OMI	No recommended replacement
LY4I4N DC48 BY OMI	No recommended replacement
LY4I4N DC6 BY OMI	No recommended replacement
LY4N AC230 BY OMI	No recommended replacement
LY4N AC32 BY OMI	No recommended replacement
LY4N AC48 BY OMI	No recommended replacement
LY4N AC50 BY OMI	No recommended replacement
LY4N AC6 BY OMI	No recommended replacement
LY4N DC32 BY OMI	No recommended replacement
LY4N DC36 BY OMI	No recommended replacement
LY4N DC6 BY OMI	No recommended replacement
LY4W-O AC120 BY OMI	No recommended replacement
LY4W-O AC24 BY OMI	No recommended replacement
LY4W-O DC12 BY OMI	No recommended replacement
LY4W-O DC24 BY OMI	No recommended replacement
LY1-J DC12 BY OMI	No recommended replacement
LY1-J DC24 BY OMI	No recommended replacement
LY2-0-J AC100/110 BY OMI	No recommended replacement
LY2-0-J AC110/120 BY OMI	No recommended replacement
LY2-0-J AC200/220 BY OMI	No recommended replacement
LY2-0-J AC220/240 BY OMI	No recommended replacement
LY2-0-J DC12 BY OMI	No recommended replacement
LY2-J AC110/120 BY OMI	No recommended replacement
LY2-J AC24 BY OMI	No recommended replacement

Product discontinuation	Recommended replacement
LY2-J AC6 BY OMI	No recommended replacement
LY2-J DC48 BY OMI	No recommended replacement
LY2-J DC6 BY OMI	No recommended replacement
LY2N-J DC6 BY OMI	No recommended replacement
LY2N-J-SXE DC24 BY OMI	No recommended replacement
LY3-J AC100/110 BY OMI	No recommended replacement
LY3-J AC200/220 BY OMI	No recommended replacement
LY3-J DC24 BY OMI	No recommended replacement
LY3N-J AC100/110 BY OMI	No recommended replacement
LY3N-J AC110/120 BY OMI	No recommended replacement
LY3N-J AC200/220 BY OMI	No recommended replacement
LY3N-J DC100/110 BY OMI	No recommended replacement
LY4-J AC100/110 BY OMI	No recommended replacement
LY4-J AC110/120 BY OMI	No recommended replacement
LY4-J AC12 BY OMI	No recommended replacement
LY4-J AC220/240 BY OMI	No recommended replacement
LY4-J AC24 BY OMI	No recommended replacement
LY4-J DC100/110 BY OMI	No recommended replacement
LY4-J DC6 BY OMI	No recommended replacement
LYQ2 AC200/220	No recommended replacement
LYQ2 DC6	No recommended replacement
MKS2P AC48 BY OMZ	No recommended replacement
MKS2P AC50 BY OMZ	No recommended replacement
MKS2P DC32 BY OMZ	No recommended replacement
MKS2P-2 AC120 BY OMZ	No recommended replacement
MKS2P-2 AC230 BY OMZ	No recommended replacement
MKS2P-2 AC50 BY OMZ	No recommended replacement
MKS2P-D DC100 BY OMZ	No recommended replacement
MKS2P-D DC110 BY OMZ	No recommended replacement
MKS2P-D DC12 BY OMZ	No recommended replacement
MKS2P-D DC125 BY OMZ	No recommended replacement
MKS2P-D DC24 BY OMZ	No recommended replacement
MKS2P-D DC48 BY OMZ	No recommended replacement
MKS2P-D DC6 BY OMZ	No recommended replacement
MKS2P-D-2 DC100 BY OMZ	No recommended replacement
MKS2P-D-2 DC110 BY OMZ	No recommended replacement
MKS2P-D-2 DC12 BY OMZ	No recommended replacement
MKS2P-D-2 DC24 BY OMZ	No recommended replacement
MKS2P-D-2 DC48 BY OMZ	No recommended replacement
MKS2P-D-2 DC6 BY OMZ	No recommended replacement
MKS2P-V AC100 BY OMZ	No recommended replacement
MKS2P-V AC110 BY OMZ	No recommended replacement
MKS2P-V AC12 BY OMZ	No recommended replacement
MKS2P-V AC120 BY OMZ	No recommended replacement
MKS2P-V AC200 BY OMZ	No recommended replacement
MKS2P-V AC220 BY OMZ	No recommended replacement
MKS2P-V AC230 BY OMZ	No recommended replacement
MKS2P-V AC24 BY OMZ	No recommended replacement
MKS2P-V AC240 BY OMZ	No recommended replacement

Product discontinuation	Recommended replacement
MKS2P-V AC50 BY OMZ	No recommended replacement
MKS2P-V AC6 BY OMZ	No recommended replacement
MKS2P-V-2 AC100 BY OMZ	No recommended replacement
MKS2P-V-2 AC110 BY OMZ	No recommended replacement
MKS2P-V-2 AC12 BY OMZ	No recommended replacement
MKS2P-V-2 AC120 BY OMZ	No recommended replacement
MKS2P-V-2 AC200 BY OMZ	No recommended replacement
MKS2P-V-2 AC220 BY OMZ	No recommended replacement
MKS2P-V-2 AC230 BY OMZ	No recommended replacement
MKS2P-V-2 AC24 BY OMZ	No recommended replacement
MKS2P-V-2 AC240 BY OMZ	No recommended replacement
MKS2P-V-2 AC50 BY OMZ	No recommended replacement
MKS2P-V-2 AC6 BY OMZ	No recommended replacement
MKS2P1-D DC100 BY OMZ	No recommended replacement
MKS2P1-D DC110 BY OMZ	No recommended replacement
MKS2P1-D DC12 BY OMZ	No recommended replacement
MKS2P1-D DC125 BY OMZ	No recommended replacement
MKS2P1-D DC24 BY OMZ	No recommended replacement
MKS2P1-D DC48 BY OMZ	No recommended replacement
MKS2P1-D DC6 BY OMZ	No recommended replacement
MKS2P1-D-2 DC100 BY OMZ	No recommended replacement
MKS2P1-D-2 DC110 BY OMZ	No recommended replacement
MKS2P1-D-2 DC12 BY OMZ	No recommended replacement
MKS2P1-D-2 DC24 BY OMZ	No recommended replacement
MKS2P1-D-2 DC48 BY OMZ	No recommended replacement
MKS2P1-D-2 DC6 BY OMZ	No recommended replacement
MKS2PI AC48 BY OMZ	No recommended replacement
MKS2PI AC50 BY OMZ	No recommended replacement
MKS2PI DC60 BY OMZ	No recommended replacement
MKS2PI-2 AC120 BY OMZ	No recommended replacement
MKS2PI-2 AC230 BY OMZ	No recommended replacement
MKS2PI-2 AC50 BY OMZ	No recommended replacement
MKS2PI-2 AC6 BY OMZ	No recommended replacement
MKS2PI-D DC100 BY OMZ	No recommended replacement
MKS2PI-D DC110 BY OMZ	No recommended replacement
MKS2PI-D DC12 BY OMZ	No recommended replacement
MKS2PI-D DC48 BY OMZ	No recommended replacement
MKS2PI-D DC6 BY OMZ	No recommended replacement
MKS2PI-D-2 DC100 BY OMZ	No recommended replacement
MKS2PI-D-2 DC110 BY OMZ	No recommended replacement
MKS2PI-D-2 DC12 BY OMZ	No recommended replacement
MKS2PI-D-2 DC24 BY OMZ	No recommended replacement
MKS2PI-D-2 DC48 BY OMZ	No recommended replacement
MKS2PI-D-2 DC6 BY OMZ	No recommended replacement
MKS2PI-V AC100 BY OMZ	No recommended replacement
MKS2PI-V AC110 BY OMZ	No recommended replacement
MKS2PI-V AC12 BY OMZ	No recommended replacement
MKS2PI-V AC120 BY OMZ	No recommended replacement
MKS2PI-V AC200 BY OMZ	No recommended replacement

Product discontinuation	Recommended replacement
MKS2PI-V AC220 BY OMZ	No recommended replacement
MKS2PI-V AC230 BY OMZ	No recommended replacement
MKS2PI-V AC24 BY OMZ	No recommended replacement
MKS2PI-V AC240 BY OMZ	No recommended replacement
MKS2PI-V AC50 BY OMZ	No recommended replacement
MKS2PI-V AC6 BY OMZ	No recommended replacement
MKS2PI-V-2 AC100 BY OMZ	No recommended replacement
MKS2PI-V-2 AC110 BY OMZ	No recommended replacement
MKS2PI-V-2 AC12 BY OMZ	No recommended replacement
MKS2PI-V-2 AC120 BY OMZ	No recommended replacement
MKS2PI-V-2 AC200 BY OMZ	No recommended replacement
MKS2PI-V-2 AC220 BY OMZ	No recommended replacement
MKS2PI-V-2 AC230 BY OMZ	No recommended replacement
MKS2PI-V-2 AC24 BY OMZ	No recommended replacement
MKS2PI-V-2 AC240 BY OMZ	No recommended replacement
MKS2PI-V-2 AC50 BY OMZ	No recommended replacement
MKS2PI-V-2 AC6 BY OMZ	No recommended replacement
MKS2PI1-D DC100 BY OMZ	No recommended replacement
MKS2PI1-D DC110 BY OMZ	No recommended replacement
MKS2PI1-D DC12 BY OMZ	No recommended replacement
MKS2PI1-D DC24 BY OMZ	No recommended replacement
MKS2PI1-D DC48 BY OMZ	No recommended replacement
MKS2PI1-D DC6 BY OMZ	No recommended replacement
MKS2PI1-D-2 DC100 BY OMZ	No recommended replacement
MKS2PI1-D-2 DC110 BY OMZ	No recommended replacement
MKS2PI1-D-2 DC12 BY OMZ	No recommended replacement
MKS2PI1-D-2 DC24 BY OMZ	No recommended replacement
MKS2PI1-D-2 DC48 BY OMZ	No recommended replacement
MKS2PI1-D-2 DC6 BY OMZ	No recommended replacement
MKS2PIN AC50 BY OMZ	No recommended replacement
MKS2PIN AC6 BY OMZ	No recommended replacement
MKS2PIN-2 AC100 BY OMZ	No recommended replacement
MKS2PIN-2 AC12 BY OMZ	No recommended replacement
MKS2PIN-2 AC120 BY OMZ	No recommended replacement
MKS2PIN-2 AC200 BY OMZ	No recommended replacement
MKS2PIN-2 AC230 BY OMZ	No recommended replacement
MKS2PIN-2 AC24 BY OMZ	No recommended replacement
MKS2PIN-2 AC240 BY OMZ	No recommended replacement
MKS2PIN-2 AC50 BY OMZ	No recommended replacement
MKS2PIN-2 AC6 BY OMZ	No recommended replacement
MKS2PIN-2 DC100 BY OMZ	No recommended replacement
MKS2PIN-2 DC110 BY OMZ	No recommended replacement
MKS2PIN-2 DC12 BY OMZ	No recommended replacement
MKS2PIN-2 DC24 BY OMZ	No recommended replacement
MKS2PIN-2 DC48 BY OMZ	No recommended replacement
MKS2PIN-2 DC6 BY OMZ	No recommended replacement
MKS2PIN-D DC100 BY OMZ	No recommended replacement
MKS2PIN-D DC110 BY OMZ	No recommended replacement
MKS2PIN-D DC12 BY OMZ	No recommended replacement

Product discontinuation	Recommended replacement
MKS2PIN-D DC24 BY OMZ	No recommended replacement
MKS2PIN-D DC48 BY OMZ	No recommended replacement
MKS2PIN-D DC6 BY OMZ	No recommended replacement
MKS2PIN-D-2 DC100 BY OMZ	No recommended replacement
MKS2PIN-D-2 DC110 BY OMZ	No recommended replacement
MKS2PIN-D-2 DC12 BY OMZ	No recommended replacement
MKS2PIN-D-2 DC24 BY OMZ	No recommended replacement
MKS2PIN-D-2 DC48 BY OMZ	No recommended replacement
MKS2PIN-D-2 DC6 BY OMZ	No recommended replacement
MKS2PIN-V AC100 BY OMZ	No recommended replacement
MKS2PIN-V AC110 BY OMZ	No recommended replacement
MKS2PIN-V AC12 BY OMZ	No recommended replacement
MKS2PIN-V AC120 BY OMZ	No recommended replacement
MKS2PIN-V AC200 BY OMZ	No recommended replacement
MKS2PIN-V AC220 BY OMZ	No recommended replacement
MKS2PIN-V AC230 BY OMZ	No recommended replacement
MKS2PIN-V AC24 BY OMZ	No recommended replacement
MKS2PIN-V AC240 BY OMZ	No recommended replacement
MKS2PIN-V AC50 BY OMZ	No recommended replacement
MKS2PIN-V AC6 BY OMZ	No recommended replacement
MKS2PIN-V-2 AC100 BY OMZ	No recommended replacement
MKS2PIN-V-2 AC110 BY OMZ	No recommended replacement
MKS2PIN-V-2 AC12 BY OMZ	No recommended replacement
MKS2PIN-V-2 AC120 BY OMZ	No recommended replacement
MKS2PIN-V-2 AC200 BY OMZ	No recommended replacement
MKS2PIN-V-2 AC220 BY OMZ	No recommended replacement
MKS2PIN-V-2 AC230 BY OMZ	No recommended replacement
MKS2PIN-V-2 AC24 BY OMZ	No recommended replacement
MKS2PIN-V-2 AC240 BY OMZ	No recommended replacement
MKS2PIN-V-2 AC50 BY OMZ	No recommended replacement
MKS2PIN-V-2 AC6 BY OMZ	No recommended replacement
MKS2PIN1 DC100 BY OMZ	No recommended replacement
MKS2PIN1 DC110 BY OMZ	No recommended replacement
MKS2PIN1 DC12 BY OMZ	No recommended replacement
MKS2PIN1 DC24 BY OMZ	No recommended replacement
MKS2PIN1 DC48 BY OMZ	No recommended replacement
MKS2PIN1 DC6 BY OMZ	No recommended replacement
MKS2PIN1-2 DC100 BY OMZ	No recommended replacement
MKS2PIN1-2 DC110 BY OMZ	No recommended replacement
MKS2PIN1-2 DC12 BY OMZ	No recommended replacement
MKS2PIN1-2 DC24 BY OMZ	No recommended replacement
MKS2PIN1-2 DC48 BY OMZ	No recommended replacement
MKS2PIN1-2 DC6 BY OMZ	No recommended replacement
MKS2PN AC230 BY OMZ	No recommended replacement
MKS2PN AC50 BY OMZ	No recommended replacement
MKS2PN-2 AC100 BY OMZ	No recommended replacement
MKS2PN-2 AC110 BY OMZ	No recommended replacement
MKS2PN-2 AC12 BY OMZ	No recommended replacement
MKS2PN-2 AC120 BY OMZ	No recommended replacement

Product discontinuation	Recommended replacement
MKS2PN-2 AC200 BY OMZ	No recommended replacement
MKS2PN-2 AC230 BY OMZ	No recommended replacement
MKS2PN-2 AC24 BY OMZ	No recommended replacement
MKS2PN-2 AC240 BY OMZ	No recommended replacement
MKS2PN-2 AC50 BY OMZ	No recommended replacement
MKS2PN-2 AC6 BY OMZ	No recommended replacement
MKS2PN-2 DC100 BY OMZ	No recommended replacement
MKS2PN-2 DC110 BY OMZ	No recommended replacement
MKS2PN-2 DC12 BY OMZ	No recommended replacement
MKS2PN-2 DC24 BY OMZ	No recommended replacement
MKS2PN-2 DC48 BY OMZ	No recommended replacement
MKS2PN-2 DC6 BY OMZ	No recommended replacement
MKS2PN-D DC100 BY OMZ	No recommended replacement
MKS2PN-D DC110 BY OMZ	No recommended replacement
MKS2PN-D DC12 BY OMZ	No recommended replacement
MKS2PN-D DC24 BY OMZ	No recommended replacement
MKS2PN-D DC48 BY OMZ	No recommended replacement
MKS2PN-D DC6 BY OMZ	No recommended replacement
MKS2PN-D-2 DC100 BY OMZ	No recommended replacement
MKS2PN-D-2 DC110 BY OMZ	No recommended replacement
MKS2PN-D-2 DC12 BY OMZ	No recommended replacement
MKS2PN-D-2 DC24 BY OMZ	No recommended replacement
MKS2PN-D-2 DC48 BY OMZ	No recommended replacement
MKS2PN-D-2 DC6 BY OMZ	No recommended replacement
MKS2PN-V AC100 BY OMZ	No recommended replacement
MKS2PN-V AC110 BY OMZ	No recommended replacement
MKS2PN-V AC12 BY OMZ	No recommended replacement
MKS2PN-V AC120 BY OMZ	No recommended replacement
MKS2PN-V AC200 BY OMZ	No recommended replacement
MKS2PN-V AC220 BY OMZ	No recommended replacement
MKS2PN-V AC230 BY OMZ	No recommended replacement
MKS2PN-V AC24 BY OMZ	No recommended replacement
MKS2PN-V AC240 BY OMZ	No recommended replacement
MKS2PN-V AC50 BY OMZ	No recommended replacement
MKS2PN-V AC6 BY OMZ	No recommended replacement
MKS2PN-V-2 AC100 BY OMZ	No recommended replacement
MKS2PN-V-2 AC110 BY OMZ	No recommended replacement
MKS2PN-V-2 AC12 BY OMZ	No recommended replacement
MKS2PN-V-2 AC120 BY OMZ	No recommended replacement
MKS2PN-V-2 AC200 BY OMZ	No recommended replacement
MKS2PN-V-2 AC220 BY OMZ	No recommended replacement
MKS2PN-V-2 AC230 BY OMZ	No recommended replacement
MKS2PN-V-2 AC24 BY OMZ	No recommended replacement
MKS2PN-V-2 AC240 BY OMZ	No recommended replacement
MKS2PN-V-2 AC50 BY OMZ	No recommended replacement
MKS2PN-V-2 AC6 BY OMZ	No recommended replacement
MKS2PN1-2 DC100 BY OMZ	No recommended replacement
MKS2PN1-2 DC110 BY OMZ	No recommended replacement
MKS2PN1-2 DC12 BY OMZ	No recommended replacement

Product discontinuation	Recommended replacement
MKS2PN1-2 DC24 BY OMZ	No recommended replacement
MKS2PN1-2 DC48 BY OMZ	No recommended replacement
MKS2PN1-2 DC6 BY OMZ	No recommended replacement
MKS3P AC120 BY OMZ	No recommended replacement
MKS3P AC48 BY OMZ	No recommended replacement
MKS3P AC50 BY OMZ	No recommended replacement
MKS3P DC32 BY OMZ	No recommended replacement
MKS3P-2 AC120 BY OMZ	No recommended replacement
MKS3P-2 AC230 BY OMZ	No recommended replacement
MKS3P-2 AC50 BY OMZ	No recommended replacement
MKS3P-5 AC100 BY OMZ	No recommended replacement
MKS3P-5 AC12 BY OMZ	No recommended replacement
MKS3P-5 AC200 BY OMZ	No recommended replacement
MKS3P-5 AC240 BY OMZ	No recommended replacement
MKS3P-5 AC48 BY OMZ	No recommended replacement
MKS3P-5 AC50 BY OMZ	No recommended replacement
MKS3P-5 AC6 BY OMZ	No recommended replacement
MKS3P-5 DC100 BY OMZ	No recommended replacement
MKS3P-5 DC110 BY OMZ	No recommended replacement
MKS3P-5 DC12 BY OMZ	No recommended replacement
MKS3P-5 DC125 BY OMZ	No recommended replacement
MKS3P-5 DC48 BY OMZ	No recommended replacement
MKS3P-5 DC6 BY OMZ	No recommended replacement
MKS3P-5 DC60 BY OMZ	No recommended replacement
MKS3P-D DC100 BY OMZ	No recommended replacement
MKS3P-D DC110 BY OMZ	No recommended replacement
MKS3P-D DC12 BY OMZ	No recommended replacement
MKS3P-D DC24 BY OMZ	No recommended replacement
MKS3P-D DC48 BY OMZ	No recommended replacement
MKS3P-D DC6 BY OMZ	No recommended replacement
MKS3P-D-2 DC100 BY OMZ	No recommended replacement
MKS3P-D-2 DC110 BY OMZ	No recommended replacement
MKS3P-D-2 DC12 BY OMZ	No recommended replacement
MKS3P-D-2 DC24 BY OMZ	No recommended replacement
MKS3P-D-2 DC48 BY OMZ	No recommended replacement
MKS3P-D-2 DC6 BY OMZ	No recommended replacement
MKS3P-D-5 DC100 BY OMZ	No recommended replacement
MKS3P-D-5 DC110 BY OMZ	No recommended replacement
MKS3P-D-5 DC12 BY OMZ	No recommended replacement
MKS3P-D-5 DC24 BY OMZ	No recommended replacement
MKS3P-D-5 DC48 BY OMZ	No recommended replacement
MKS3P-D-5 DC6 BY OMZ	No recommended replacement
MKS3P-V AC100 BY OMZ	No recommended replacement
MKS3P-V AC110 BY OMZ	No recommended replacement
MKS3P-V AC12 BY OMZ	No recommended replacement
MKS3P-V AC120 BY OMZ	No recommended replacement
MKS3P-V AC200 BY OMZ	No recommended replacement
MKS3P-V AC220 BY OMZ	No recommended replacement
MKS3P-V AC230 BY OMZ	No recommended replacement

Product discontinuation	Recommended replacement
MKS3P-V AC24 BY OMZ	No recommended replacement
MKS3P-V AC240 BY OMZ	No recommended replacement
MKS3P-V AC50 BY OMZ	No recommended replacement
MKS3P-V AC6 BY OMZ	No recommended replacement
MKS3P-V-2 AC100 BY OMZ	No recommended replacement
MKS3P-V-2 AC110 BY OMZ	No recommended replacement
MKS3P-V-2 AC12 BY OMZ	No recommended replacement
MKS3P-V-2 AC120 BY OMZ	No recommended replacement
MKS3P-V-2 AC200 BY OMZ	No recommended replacement
MKS3P-V-2 AC220 BY OMZ	No recommended replacement
MKS3P-V-2 AC230 BY OMZ	No recommended replacement
MKS3P-V-2 AC24 BY OMZ	No recommended replacement
MKS3P-V-2 AC240 BY OMZ	No recommended replacement
MKS3P-V-2 AC50 BY OMZ	No recommended replacement
MKS3P-V-2 AC6 BY OMZ	No recommended replacement
MKS3P-V-5 AC100 BY OMZ	No recommended replacement
MKS3P-V-5 AC110 BY OMZ	No recommended replacement
MKS3P-V-5 AC12 BY OMZ	No recommended replacement
MKS3P-V-5 AC120 BY OMZ	No recommended replacement
MKS3P-V-5 AC200 BY OMZ	No recommended replacement
MKS3P-V-5 AC220 BY OMZ	No recommended replacement
MKS3P-V-5 AC230 BY OMZ	No recommended replacement
MKS3P-V-5 AC24 BY OMZ	No recommended replacement
MKS3P-V-5 AC240 BY OMZ	No recommended replacement
MKS3P-V-5 AC50 BY OMZ	No recommended replacement
MKS3P-V-5 AC6 BY OMZ	No recommended replacement
MKS3P1-D DC100 BY OMZ	No recommended replacement
MKS3P1-D DC110 BY OMZ	No recommended replacement
MKS3P1-D DC12 BY OMZ	No recommended replacement
MKS3P1-D DC24 BY OMZ	No recommended replacement
MKS3P1-D DC48 BY OMZ	No recommended replacement
MKS3P1-D DC6 BY OMZ	No recommended replacement
MKS3P1-D-2 DC100 BY OMZ	No recommended replacement
MKS3P1-D-2 DC110 BY OMZ	No recommended replacement
MKS3P1-D-2 DC12 BY OMZ	No recommended replacement
MKS3P1-D-2 DC24 BY OMZ	No recommended replacement
MKS3P1-D-2 DC48 BY OMZ	No recommended replacement
MKS3P1-D-2 DC6 BY OMZ	No recommended replacement
MKS3P1-D-5 DC100 BY OMZ	No recommended replacement
MKS3P1-D-5 DC110 BY OMZ	No recommended replacement
MKS3P1-D-5 DC12 BY OMZ	No recommended replacement
MKS3P1-D-5 DC125 BY OMZ	No recommended replacement
MKS3P1-D-5 DC24 BY OMZ	No recommended replacement
MKS3P1-D-5 DC48 BY OMZ	No recommended replacement
MKS3P1-D-5 DC6 BY OMZ	No recommended replacement
MKS3PI AC120 BY OMZ	No recommended replacement
MKS3PI AC230 BY OMZ	No recommended replacement
MKS3PI AC50 BY OMZ	No recommended replacement
MKS3PI-2 AC120 BY OMZ	No recommended replacement

Product discontinuation	Recommended replacement
MKS3PI-2 AC230 BY OMZ	No recommended replacement
MKS3PI-2 AC50 BY OMZ	No recommended replacement
MKS3PI-5 AC100 BY OMZ	No recommended replacement
MKS3PI-5 AC12 BY OMZ	No recommended replacement
MKS3PI-5 AC200 BY OMZ	No recommended replacement
MKS3PI-5 AC48 BY OMZ	No recommended replacement
MKS3PI-5 AC50 BY OMZ	No recommended replacement
MKS3PI-5 AC6 BY OMZ	No recommended replacement
MKS3PI-5 DC100 BY OMZ	No recommended replacement
MKS3PI-5 DC125 BY OMZ	No recommended replacement
MKS3PI-5 DC6 BY OMZ	No recommended replacement
MKS3PI-5 DC60 BY OMZ	No recommended replacement
MKS3PI-D DC100 BY OMZ	No recommended replacement
MKS3PI-D DC110 BY OMZ	No recommended replacement
MKS3PI-D DC12 BY OMZ	No recommended replacement
MKS3PI-D DC24 BY OMZ	No recommended replacement
MKS3PI-D DC48 BY OMZ	No recommended replacement
MKS3PI-D DC6 BY OMZ	No recommended replacement
MKS3PI-D-2 DC100 BY OMZ	No recommended replacement
MKS3PI-D-2 DC110 BY OMZ	No recommended replacement
MKS3PI-D-2 DC12 BY OMZ	No recommended replacement
MKS3PI-D-2 DC24 BY OMZ	No recommended replacement
MKS3PI-D-2 DC48 BY OMZ	No recommended replacement
MKS3PI-D-2 DC6 BY OMZ	No recommended replacement
MKS3PI-D-5 DC100 BY OMZ	No recommended replacement
MKS3PI-D-5 DC110 BY OMZ	No recommended replacement
MKS3PI-D-5 DC12 BY OMZ	No recommended replacement
MKS3PI-D-5 DC24 BY OMZ	No recommended replacement
MKS3PI-D-5 DC48 BY OMZ	No recommended replacement
MKS3PI-D-5 DC6 BY OMZ	No recommended replacement
MKS3PI-V AC100 BY OMZ	No recommended replacement
MKS3PI-V AC110 BY OMZ	No recommended replacement
MKS3PI-V AC12 BY OMZ	No recommended replacement
MKS3PI-V AC120 BY OMZ	No recommended replacement
MKS3PI-V AC200 BY OMZ	No recommended replacement
MKS3PI-V AC220 BY OMZ	No recommended replacement
MKS3PI-V AC230 BY OMZ	No recommended replacement
MKS3PI-V AC24 BY OMZ	No recommended replacement
MKS3PI-V AC240 BY OMZ	No recommended replacement
MKS3PI-V AC50 BY OMZ	No recommended replacement
MKS3PI-V AC6 BY OMZ	No recommended replacement
MKS3PI-V-2 AC100 BY OMZ	No recommended replacement
MKS3PI-V-2 AC110 BY OMZ	No recommended replacement
MKS3PI-V-2 AC12 BY OMZ	No recommended replacement
MKS3PI-V-2 AC120 BY OMZ	No recommended replacement
MKS3PI-V-2 AC200 BY OMZ	No recommended replacement
MKS3PI-V-2 AC220 BY OMZ	No recommended replacement
MKS3PI-V-2 AC230 BY OMZ	No recommended replacement
MKS3PI-V-2 AC24 BY OMZ	No recommended replacement

Product discontinuation	Recommended replacement
MKS3PI-V-2 AC240 BY OMZ	No recommended replacement
MKS3PI-V-2 AC50 BY OMZ	No recommended replacement
MKS3PI-V-2 AC6 BY OMZ	No recommended replacement
MKS3PI-V-5 AC100 BY OMZ	No recommended replacement
MKS3PI-V-5 AC110 BY OMZ	No recommended replacement
MKS3PI-V-5 AC12 BY OMZ	No recommended replacement
MKS3PI-V-5 AC120 BY OMZ	No recommended replacement
MKS3PI-V-5 AC200 BY OMZ	No recommended replacement
MKS3PI-V-5 AC220 BY OMZ	No recommended replacement
MKS3PI-V-5 AC230 BY OMZ	No recommended replacement
MKS3PI-V-5 AC24 BY OMZ	No recommended replacement
MKS3PI-V-5 AC240 BY OMZ	No recommended replacement
MKS3PI-V-5 AC50 BY OMZ	No recommended replacement
MKS3PI-V-5 AC6 BY OMZ	No recommended replacement
MKS3PI1-D DC100 BY OMZ	No recommended replacement
MKS3PI1-D DC110 BY OMZ	No recommended replacement
MKS3PI1-D DC12 BY OMZ	No recommended replacement
MKS3PI1-D DC24 BY OMZ	No recommended replacement
MKS3PI1-D DC48 BY OMZ	No recommended replacement
MKS3PI1-D DC6 BY OMZ	No recommended replacement
MKS3PI1-D-2 DC100 BY OMZ	No recommended replacement
MKS3PI1-D-2 DC110 BY OMZ	No recommended replacement
MKS3PI1-D-2 DC12 BY OMZ	No recommended replacement
MKS3PI1-D-2 DC24 BY OMZ	No recommended replacement
MKS3PI1-D-2 DC48 BY OMZ	No recommended replacement
MKS3PI1-D-2 DC6 BY OMZ	No recommended replacement
MKS3PI1-D-5 DC100 BY OMZ	No recommended replacement
MKS3PI1-D-5 DC110 BY OMZ	No recommended replacement
MKS3PI1-D-5 DC12 BY OMZ	No recommended replacement
MKS3PI1-D-5 DC24 BY OMZ	No recommended replacement
MKS3PI1-D-5 DC48 BY OMZ	No recommended replacement
MKS3PI1-D-5 DC6 BY OMZ	No recommended replacement
MKS3PIN AC120 BY OMZ	No recommended replacement
MKS3PIN AC230 BY OMZ	No recommended replacement
MKS3PIN AC50 BY OMZ	No recommended replacement
MKS3PIN-2 AC120 BY OMZ	No recommended replacement
MKS3PIN-2 AC230 BY OMZ	No recommended replacement
MKS3PIN-2 AC50 BY OMZ	No recommended replacement
MKS3PIN-5 AC100 BY OMZ	No recommended replacement
MKS3PIN-5 AC12 BY OMZ	No recommended replacement
MKS3PIN-5 AC200 BY OMZ	No recommended replacement
MKS3PIN-5 AC240 BY OMZ	No recommended replacement
MKS3PIN-5 AC48 BY OMZ	No recommended replacement
MKS3PIN-5 AC50 BY OMZ	No recommended replacement
MKS3PIN-5 AC6 BY OMZ	No recommended replacement
MKS3PIN-5 DC100 BY OMZ	No recommended replacement
MKS3PIN-5 DC110 BY OMZ	No recommended replacement
MKS3PIN-5 DC12 BY OMZ	No recommended replacement
MKS3PIN-5 DC48 BY OMZ	No recommended replacement

Product discontinuation	Recommended replacement
MKS3PIN-5 DC6 BY OMZ	No recommended replacement
MKS3PIN-D DC100 BY OMZ	No recommended replacement
MKS3PIN-D DC110 BY OMZ	No recommended replacement
MKS3PIN-D DC12 BY OMZ	No recommended replacement
MKS3PIN-D DC24 BY OMZ	No recommended replacement
MKS3PIN-D DC48 BY OMZ	No recommended replacement
MKS3PIN-D DC6 BY OMZ	No recommended replacement
MKS3PIN-D-2 DC100 BY OMZ	No recommended replacement
MKS3PIN-D-2 DC110 BY OMZ	No recommended replacement
MKS3PIN-D-2 DC12 BY OMZ	No recommended replacement
MKS3PIN-D-2 DC24 BY OMZ	No recommended replacement
MKS3PIN-D-2 DC48 BY OMZ	No recommended replacement
MKS3PIN-D-2 DC6 BY OMZ	No recommended replacement
MKS3PIN-D-5 DC100 BY OMZ	No recommended replacement
MKS3PIN-D-5 DC110 BY OMZ	No recommended replacement
MKS3PIN-D-5 DC12 BY OMZ	No recommended replacement
MKS3PIN-D-5 DC125 BY OMZ	No recommended replacement
MKS3PIN-D-5 DC48 BY OMZ	No recommended replacement
MKS3PIN-D-5 DC6 BY OMZ	No recommended replacement
MKS3PIN-V AC100 BY OMZ	No recommended replacement
MKS3PIN-V AC110 BY OMZ	No recommended replacement
MKS3PIN-V AC12 BY OMZ	No recommended replacement
MKS3PIN-V AC120 BY OMZ	No recommended replacement
MKS3PIN-V AC200 BY OMZ	No recommended replacement
MKS3PIN-V AC220 BY OMZ	No recommended replacement
MKS3PIN-V AC230 BY OMZ	No recommended replacement
MKS3PIN-V AC24 BY OMZ	No recommended replacement
MKS3PIN-V AC240 BY OMZ	No recommended replacement
MKS3PIN-V AC50 BY OMZ	No recommended replacement
MKS3PIN-V AC6 BY OMZ	No recommended replacement
MKS3PIN-V-2 AC100 BY OMZ	No recommended replacement
MKS3PIN-V-2 AC110 BY OMZ	No recommended replacement
MKS3PIN-V-2 AC12 BY OMZ	No recommended replacement
MKS3PIN-V-2 AC120 BY OMZ	No recommended replacement
MKS3PIN-V-2 AC200 BY OMZ	No recommended replacement
MKS3PIN-V-2 AC220 BY OMZ	No recommended replacement
MKS3PIN-V-2 AC230 BY OMZ	No recommended replacement
MKS3PIN-V-2 AC24 BY OMZ	No recommended replacement
MKS3PIN-V-2 AC240 BY OMZ	No recommended replacement
MKS3PIN-V-2 AC50 BY OMZ	No recommended replacement
MKS3PIN-V-2 AC6 BY OMZ	No recommended replacement
MKS3PIN-V-5 AC100 BY OMZ	No recommended replacement
MKS3PIN-V-5 AC110 BY OMZ	No recommended replacement
MKS3PIN-V-5 AC12 BY OMZ	No recommended replacement
MKS3PIN-V-5 AC120 BY OMZ	No recommended replacement
MKS3PIN-V-5 AC200 BY OMZ	No recommended replacement
MKS3PIN-V-5 AC220 BY OMZ	No recommended replacement
MKS3PIN-V-5 AC230 BY OMZ	No recommended replacement
MKS3PIN-V-5 AC24 BY OMZ	No recommended replacement

Product discontinuation	Recommended replacement
MKS3PIN-V-5 AC240 BY OMZ	No recommended replacement
MKS3PIN-V-5 AC50 BY OMZ	No recommended replacement
MKS3PIN-V-5 AC6 BY OMZ	No recommended replacement
MKS3PIN1-2 DC100 BY OMZ	No recommended replacement
MKS3PIN1-2 DC110 BY OMZ	No recommended replacement
MKS3PIN1-2 DC12 BY OMZ	No recommended replacement
MKS3PIN1-2 DC24 BY OMZ	No recommended replacement
MKS3PIN1-2 DC48 BY OMZ	No recommended replacement
MKS3PIN1-2 DC6 BY OMZ	No recommended replacement
MKS3PIN1-5 DC100 BY OMZ	No recommended replacement
MKS3PIN1-5 DC110 BY OMZ	No recommended replacement
MKS3PIN1-5 DC12 BY OMZ	No recommended replacement
MKS3PIN1-5 DC24 BY OMZ	No recommended replacement
MKS3PIN1-5 DC48 BY OMZ	No recommended replacement
MKS3PIN1-5 DC6 BY OMZ	No recommended replacement
MKS3PN AC100 BY OMZ	No recommended replacement
MKS3PN AC230 BY OMZ	No recommended replacement
MKS3PN AC50 BY OMZ	No recommended replacement
MKS3PN-2 AC100 BY OMZ	No recommended replacement
MKS3PN-2 AC12 BY OMZ	No recommended replacement
MKS3PN-2 AC120 BY OMZ	No recommended replacement
MKS3PN-2 AC200 BY OMZ	No recommended replacement
MKS3PN-2 AC230 BY OMZ	No recommended replacement
MKS3PN-2 AC24 BY OMZ	No recommended replacement
MKS3PN-2 AC240 BY OMZ	No recommended replacement
MKS3PN-2 AC50 BY OMZ	No recommended replacement
MKS3PN-2 AC6 BY OMZ	No recommended replacement
MKS3PN-2 DC100 BY OMZ	No recommended replacement
MKS3PN-2 DC110 BY OMZ	No recommended replacement
MKS3PN-2 DC12 BY OMZ	No recommended replacement
MKS3PN-2 DC24 BY OMZ	No recommended replacement
MKS3PN-2 DC48 BY OMZ	No recommended replacement
MKS3PN-2 DC6 BY OMZ	No recommended replacement
MKS3PN-5 AC100 BY OMZ	No recommended replacement
MKS3PN-5 AC12 BY OMZ	No recommended replacement
MKS3PN-5 AC120 BY OMZ	No recommended replacement
MKS3PN-5 AC200 BY OMZ	No recommended replacement
MKS3PN-5 AC230 BY OMZ	No recommended replacement
MKS3PN-5 AC24 BY OMZ	No recommended replacement
MKS3PN-5 AC240 BY OMZ	No recommended replacement
MKS3PN-5 AC50 BY OMZ	No recommended replacement
MKS3PN-5 AC6 BY OMZ	No recommended replacement
MKS3PN-5 DC100 BY OMZ	No recommended replacement
MKS3PN-5 DC110 BY OMZ	No recommended replacement
MKS3PN-5 DC12 BY OMZ	No recommended replacement
MKS3PN-5 DC24 BY OMZ	No recommended replacement
MKS3PN-5 DC32 BY OMZ	No recommended replacement
MKS3PN-5 DC48 BY OMZ	No recommended replacement
MKS3PN-5 DC6 BY OMZ	No recommended replacement

Product discontinuation	Recommended replacement
MKS3PN-D DC100 BY OMZ	No recommended replacement
MKS3PN-D DC110 BY OMZ	No recommended replacement
MKS3PN-D DC12 BY OMZ	No recommended replacement
MKS3PN-D DC24 BY OMZ	No recommended replacement
MKS3PN-D DC48 BY OMZ	No recommended replacement
MKS3PN-D DC6 BY OMZ	No recommended replacement
MKS3PN-D-2 DC100 BY OMZ	No recommended replacement
MKS3PN-D-2 DC110 BY OMZ	No recommended replacement
MKS3PN-D-2 DC12 BY OMZ	No recommended replacement
MKS3PN-D-2 DC24 BY OMZ	No recommended replacement
MKS3PN-D-2 DC48 BY OMZ	No recommended replacement
MKS3PN-D-2 DC6 BY OMZ	No recommended replacement
MKS3PN-D-5 DC100 BY OMZ	No recommended replacement
MKS3PN-D-5 DC110 BY OMZ	No recommended replacement
MKS3PN-D-5 DC12 BY OMZ	No recommended replacement
MKS3PN-D-5 DC24 BY OMZ	No recommended replacement
MKS3PN-D-5 DC48 BY OMZ	No recommended replacement
MKS3PN-D-5 DC6 BY OMZ	No recommended replacement
MKS3PN-V AC100 BY OMZ	No recommended replacement
MKS3PN-V AC110 BY OMZ	No recommended replacement
MKS3PN-V AC12 BY OMZ	No recommended replacement
MKS3PN-V AC120 BY OMZ	No recommended replacement
MKS3PN-V AC200 BY OMZ	No recommended replacement
MKS3PN-V AC220 BY OMZ	No recommended replacement
MKS3PN-V AC230 BY OMZ	No recommended replacement
MKS3PN-V AC24 BY OMZ	No recommended replacement
MKS3PN-V AC240 BY OMZ	No recommended replacement
MKS3PN-V AC50 BY OMZ	No recommended replacement
MKS3PN-V AC6 BY OMZ	No recommended replacement
MKS3PN-V-2 AC100 BY OMZ	No recommended replacement
MKS3PN-V-2 AC110 BY OMZ	No recommended replacement
MKS3PN-V-2 AC12 BY OMZ	No recommended replacement
MKS3PN-V-2 AC120 BY OMZ	No recommended replacement
MKS3PN-V-2 AC200 BY OMZ	No recommended replacement
MKS3PN-V-2 AC220 BY OMZ	No recommended replacement
MKS3PN-V-2 AC230 BY OMZ	No recommended replacement
MKS3PN-V-2 AC24 BY OMZ	No recommended replacement
MKS3PN-V-2 AC240 BY OMZ	No recommended replacement
MKS3PN-V-2 AC50 BY OMZ	No recommended replacement
MKS3PN-V-2 AC6 BY OMZ	No recommended replacement
MKS3PN-V-5 AC100 BY OMZ	No recommended replacement
MKS3PN-V-5 AC110 BY OMZ	No recommended replacement
MKS3PN-V-5 AC12 BY OMZ	No recommended replacement
MKS3PN-V-5 AC120 BY OMZ	No recommended replacement
MKS3PN-V-5 AC200 BY OMZ	No recommended replacement
MKS3PN-V-5 AC220 BY OMZ	No recommended replacement
MKS3PN-V-5 AC230 BY OMZ	No recommended replacement
MKS3PN-V-5 AC24 BY OMZ	No recommended replacement
MKS3PN-V-5 AC240 BY OMZ	No recommended replacement

Product discontinuation	Recommended replacement
MKS3PN-V-5 AC50 BY OMZ	No recommended replacement
MKS3PN-V-5 AC6 BY OMZ	No recommended replacement
MKS3PN1-2 DC100 BY OMZ	No recommended replacement
MKS3PN1-2 DC110 BY OMZ	No recommended replacement
MKS3PN1-2 DC12 BY OMZ	No recommended replacement
MKS3PN1-2 DC24 BY OMZ	No recommended replacement
MKS3PN1-2 DC48 BY OMZ	No recommended replacement
MKS3PN1-2 DC6 BY OMZ	No recommended replacement
MKS3PN1-5 DC100 BY OMZ	No recommended replacement
MKS3PN1-5 DC110 BY OMZ	No recommended replacement
MKS3PN1-5 DC12 BY OMZ	No recommended replacement
MKS3PN1-5 DC24 BY OMZ	No recommended replacement
MKS3PN1-5 DC48 BY OMZ	No recommended replacement
MKS3PN1-5 DC6 BY OMZ	No recommended replacement
MY4-TF AC100/110 40W	No recommended replacement
MY4-TF AC100/110 60W	No recommended replacement
MY4-TF AC115 60W	No recommended replacement
MY4-TF AC200/220 40W	No recommended replacement
MY4-TF AC200/220 60W	No recommended replacement
MY4-TF DC24 40W	No recommended replacement
MYA-B135 AC100/110	No recommended replacement
MYA-B135 DC100/110	No recommended replacement
MYA-B145 DC24	No recommended replacement
MYA-HLA12 AC100	No recommended replacement
MYA-HLA12 DC100	No recommended replacement
MYA-HLA12 DC24	No recommended replacement
MYA-LA12 AC110/120	No recommended replacement
MYA-LA12-D1 DC24	No recommended replacement
MYA-LA12-TU DC24	No recommended replacement
MYA-LA2 AC110/120	No recommended replacement
MYA-LA2 AC220/240	No recommended replacement
MYA-LA2-D1 DC24	No recommended replacement
MYA-LA2-U DC100/110	No recommended replacement
MYA-LB1 AC110/120	No recommended replacement
MYA-LB12 AC110/120	No recommended replacement
MYA-LB2 AC115	No recommended replacement
MYA-NA1 DC12	No recommended replacement
MYA-NA2 AC110/120	No recommended replacement
MYA-NA2 AC220/240	No recommended replacement
MYA-NA2 DC12	No recommended replacement
MYA-NA2-D1 DC24	No recommended replacement
MYA-NA2-TU DC100/110	No recommended replacement
MYA-NB2 AC115	No recommended replacement
MYA-NB2-TU AC200/220	No recommended replacement
P7TF-05-TU BY OMZ	No recommended replacement
8PFA-SA	No recommended replacement
8PFA1-SA	No recommended replacement
PF113A-SA	No recommended replacement
PL15Q	No recommended replacement

Product discontinuation	Recommended replacement
PT08-0-EU	No recommended replacement
PT08-AR	No recommended replacement
PT08-Y1 FOR LY	No recommended replacement
PT08QN-Y1 FOR LY	No recommended replacement
PT11-0-EU	No recommended replacement
PT14-0-EU	No recommended replacement
PTF11A-TU FOR LY	No recommended replacement
PTF11A-W	No recommended replacement
PTF14A-TU FOR LY	No recommended replacement
PY08-0-EU	No recommended replacement
PY08-02-EU	No recommended replacement
PY08QN-Y2 FOR MY	No recommended replacement
PY11-0 FOR MY	No recommended replacement
PY11-0-EU	No recommended replacement
PY11-02-EU	No recommended replacement
PY14-0-EU	No recommended replacement
PY14-02-EU	No recommended replacement
PYF11A-TU FOR MY	No recommended replacement
PYF11A-W	No recommended replacement
PYF14A-V (200VAC)	No recommended replacement
PYF14A-V-TU	No recommended replacement
PYF14T-IB	No recommended replacement
PYF14T-S	No recommended replacement
PYF14T-TU	No recommended replacement
PYF14T-W	No recommended replacement
PFC-1 FOR MK	No recommended replacement
PFC-7 FOR MYA.LJA	No recommended replacement
R99-03MK FOR MK	No recommended replacement
R99-22 FOR G2RS(NAME PLATE)	No recommended replacement

Specifications and prices in this product news are as of the issue date and are subject to change without notice. Only main changes in specifications are described in this document. Please be sure to read the relevant catalogs, datasheets, product specifications, instructions, and manuals for precautions and necessary information when using products.