

PRODUCT CHANGE NOTIFICATION

E-Switch Series/ Part No affected: TL3253 series (all P/Ns)

Part /Series Description:

Affected Process

☐

Assembly

☐

Molding

☐

Stamping

☐

Plating

Change on:

☐

Drawing

☐

Process

☐

Material

☐

Specification

☒

Packaging

☐

Tooling Modification

☐

New Tooling

☐

Manufacturing Location

☐

Others

Reason for change:


1. Improve packaging to prevent switch terminals from damage during shipping.
2. Package 1 piece per cavity instead of 2. New quantity per tray is 126.

Proposed change:

BEFORE



AFTER



Proposed Transition/change over: Immediate

