

Dear Sir or Madam,

HellermannTyton is committed to offering the right part for the right solution. In a recent product analysis, it was determined to obsolete some parts due to low turnover and production efficiency.

We have provided an equivalent replacement for the following product(s) no longer available, effective immediately:

<i>Current Part Number</i>	<i>Description</i>	<i>Replacement Part Number</i>	<i>Description</i>
T50R2C2UL	T50R RED TIE 7.9" - 100/BAG 5,000/CTN	T50R2C2	T50R RED TIE 7.9" - 100/BAG 5,000/CTN

All our standard parts have the UL-listing, which is why the specific UL-designation is no longer needed.

If you have any questions, please contact your local salesperson or Jamison Soya, Product Manager.

Thank you for your continued business.

Kilian Oelrich
Project Associate
Product Management
HellermannTyton

[7930 N. Faulkner Road, Milwaukee, WI 53224, USA](mailto:7930.N.Faulkner.Road,Milwaukee,WI.53224,USA)
www.hellermann.tyton.com

HELLERMANN TYTON EMAIL NOTICE: The information contained in this email and any attachments is confidential and may be subject to copyright or other intellectual property protection. If you are not the intended recipient, you are not authorized to use or disclose this information, and we request that you notify us by reply mail or telephone and delete the original message from your mail system.