

April 2023

Product Discontinuation Announcement

CO2 Laser Marker **LP-400** series

Dear valued customers,

This letter is to notify you that the CO2 Laser Marker **LP-400** series will be discontinued.


As it became difficult to continue production due to the end of OS support and the end of production of many parts, we decided to discontinue the sale of this product.

We apologize for any inconvenience caused and appreciate your kind understanding.

■End of order acceptance: September 29, 2023 (JST)

■Maintenance period: September 29, 2028 (JST)

■Discontinued product and recommended substitutes

Discontinued product	Recommended substitutes
<p>CO2 Laser Marker LP-400 series</p> 	<p>We plan to release a recommended substitute model.</p> <p>For more information, please contact our sales office.</p>

*Special ordered products and accessories / options are included.

*Please note that due to changes in market conditions, it may be difficult to obtain parts and the order end date may be pushed forward. If the order end date is moved forward, we will inform you as soon as we know.

Thank you for your continued support of Industrial Device Business Division, Panasonic Industry Co., Ltd.

Sincerely,

■Discontinued models on September 29, 2023 (JST)

Discontinued products		Discontinued products	
Model No.	Part No.	Model No.	Part No.
LP-410TU	ULP410TU	LP-425S9TU-A	ULP425S9TUA
LP-410TU-A	ULP410TUA	LP-425S9TU-C	ULP425S9TUC
LP-410TU-C	ULP410TUC	LP-425S9TU-CHN	ULP425S9TUCHN
LP-410TU-CHN	ULP410TUCHN	LP-425S9U	ULP425S9U
LP-410U	ULP410U	LP-425S9U-A	ULP425S9UA
LP-410U-A	ULP410UA	LP-425S9U-C	ULP425S9UC
LP-410U-C	ULP410UC	LP-425S9U-CHN	ULP425S9UCHN
LP-410U-CHN	ULP410UCHN	LP-430TU	ULP430TU
LP-411TU	ULP411TU	LP-430TU-A	ULP430TUA
LP-411TU-A	ULP411TUA	LP-430TU-C	ULP430TUC
LP-411TU-C	ULP411TUC	LP-430TU-CHN	ULP430TUCHN
LP-411TU-CHN	ULP411TUCHN	LP-430U	ULP430U
LP-411U	ULP411U	LP-430U-A	ULP430UA
LP-411U-A	ULP411UA	LP-430U-C	ULP430UC
LP-411U-C	ULP411UC	LP-430U-CHN	ULP430UCHN
LP-411U-CHN	ULP411UCHN	LP-431TU	ULP431TU
LP-420S9TU	ULP420S9TU	LP-431TU-A	ULP431TUA
LP-420S9TU-A	ULP420S9TUA	LP-431TU-C	ULP431TUC
LP-420S9TU-C	ULP420S9TUC	LP-431TU-CHN	ULP431TUCHN
LP-420S9TU-CHN	ULP420S9TUCHN	LP-431U	ULP431U
LP-420S9U	ULP420S9U	LP-431U-A	ULP431UA
LP-420S9U-A	ULP420S9UA	LP-431U-C	ULP431UC
LP-420S9U-C	ULP420S9UC	LP-431U-CHN	ULP431UCHN
LP-420S9U-CHN	ULP420S9UCHN	LP-435TU	ULP435TU
LP-421S9TU	ULP421S9TU	LP-435TU-A	ULP435TUA
LP-421S9TU-A	ULP421S9TUA	LP-435TU-C	ULP435TUC
LP-421S9TU-C	ULP421S9TUC	LP-435TU-CHN	ULP435TUCHN
LP-421S9TU-CHN	ULP421S9TUCHN	LP-435U	ULP435U
LP-421S9U	ULP421S9U	LP-435U-A	ULP435UA
LP-421S9U-A	ULP421S9UA	LP-435U-C	ULP435UC
LP-421S9U-C	ULP421S9UC	LP-435U-CHN	ULP435UCHN
LP-421S9U-CHN	ULP421S9UCHN		
LP-425S9TU	ULP425S9TU		

*In addition, the special-order models based on the above models will be discontinued.

■Discontinued options on June 30, 2028 (JST)

Product name	Discontinued products		Recommended substitutes	
	Model No.	Part No.	Model No.	Part No.
Air filter for replacement	LP-AFT20	ULPAFT20	Not available	

*Orders for optional products will end in June 2028.

■Regarding maintenance

- We accept repair requests up to the maintenance end date and repair items that arrive at our company within one month of receiving the request. If it is not shipped in time, it will be cancelled.
- The number of replacements is limited, so we may not be able to meet your needs.
- Please note that if it becomes difficult to obtain maintenance parts before the maintenance end date, we may terminate maintenance or refuse repair at that time.
- As for the repair, after we receive your request, we will check the condition of the product and provide you with a repair estimate (Price, delivery date). In that case, if we determine that it is difficult to guarantee the repair quality due to the condition of the product, we may not be able to handle the repair.