

Product Discontinuation

ODU MAC 8 mm LAMTAC insulator replacement.

The following part numbers are to be discontinued and replaced for use with insulator 611.161.102.923.000.

Contact (old)	Contact (new)
181.874.100.200.000	181.874.100.200.001
178.874.100.201.000	178.874.100.201.001
181.875.100.200.000	181.875.100.200.001
178.875.100.201.000	178.875.100.201.001


OLD REVISION

Isolierkörper insulator	Kontakt-Ø: 8 contact-Ø: 8		Maß dim. "A"	mm ²
Part no.: 611.161.102.923.000 Part-ID: 50084726 Polzahl / number of contacts: 2 Einheiten / units: 6	S	Part no.: 181.874.100.200.000 Part-ID: 50055165	6.8	25
	B	Part no.: 178.874.100.201.000 Part-ID: 50052378		
	S	Part no.: 181.875.100.200.000 Part-ID: 50055168	5.5	16
	B	Part no.: 178.875.100.201.000 Part-ID: 50052383		

Product Discontinuation

NEW REVISION

Isolierkoerper <i>insulator</i>	Kontakt-Ø: 8 <i>contact-Ø: 8</i>		Maß <i>dim.</i> "A"	mm ²
Part-no.: 611.161.102.923.000 Part-ID: 50084726 Polzahl / number of contacts: 2 Einheiten / units: 6	S	Part-no.: 181.874.100.200.001 Part-ID: 50276187	6,8	25
	B	Part-no.: 178.874.100.201.001 Part-ID: 50260492		
	S	Part-no.: 181.875.100.200.001 Part-ID: 50276188	5,5	16
	B	Part-no.: 178.875.100.201.001 Part-ID: 50260493		



Gary Reed
Director of Product Management