

# Product Change Notice

Date:	June 20, 2023
Overview:	Select part numbers have been discontinued and replaced
Reason for Change:	Updated tooling affecting the rotors
Affected Part No(s):	A4D250-AA04-02 (replaced by A4D250-AA36-02) A4D250-AI22-01 (replaced by A4D250-AI40-01) A4D300-AA02-01 (replaced by A4D300-AT04-01) A4D300-AB10-10 (replaced by A4D300-AS34-14)
Design Change Detail:	The parts listed above featured 12-slot rotors and have been replaced by models that feature a newer 24-slot design
Effective Date:	Immediately
Last Time Buy Deadline:	N/A
Pricing:	Per current price file
ebm-papst employee:	Jeannine Zenobi
Attachments:	N/A
Comments:	The replacement part numbers featuring the newer 24-slot design rotors are mechanically compatible for 1:1 replacement

Form No: 1274	Quality Record - No	Page 1 of 1
Rev. – Orig, Released 08/28/14	Retention Period – 1 year	Dept. Owner – Sales/Marketing