

Product Change Notice

Issue Date: 26-September-2023**Change Description:**

Introduction of additional production site for plating process of housing

Parts Affected:

QFBR-5978AZ-2

Description and Extent of Change:

The current plating supplier A was facing damages due to fire on-site and is currently not able to provide a plating process for the product's housing.

Therefore, a new plating supplier B will be introduced as additional source to ensure continuous supply of our product.

Current	New
Plating supplier A	Plating supplier B, to replace plating supplier A until-production is possible again at supplier A

Reasons for Change:

Plating of housings currently not possible at supplier A.

Effect of Change on Fit, Form, Function, Quality, or Reliability:

There is no change of plating material supplier, composition or process and no change of fit, form, function or reliability.

Effective Date of Change:

Product shipments using this change will begin after 10/02/2023. Timing of shipment of the changed part will vary by part number depending on customer demand, and inventory levels.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please acknowledge the receipt of the notice within 30 days of delivery. Lack of acknowledgement within 30 days constitutes acceptance of the change per JEDEC J-STD-046.