

## PRODUCT CHANGE NOTIFICATION

| Product Category  |                                      |      | 20230913-2     |               |             |  |  |
|---|--------------------------------------|------|----------------|---------------|-------------|--|--|
| Product Group   | POWER CONNECTORS GROUNDING AND STEEL |      |                |               |             |  |  |
| ISSUE DATE:   | 5-Sep-23                             |      |                |               |             |  |  |
| IMPACTED REGIONS:   | ✓ NA ✓                               | EMEA | ✓ LATAM        | ✓ AP          |             |  |  |
| REASON FOR CHANGE:  | ✓ DISCONTINUATION                    |      |                |               |             |  |  |
|   | OTHER                                |      |                |               |             |  |  |
| DESCRIPTION OF CHANGE: (Required)   |                                      |      |                |               |             |  |  |
| Obsolecence of Bi-Metalic Lugs series (BML2) for Japan marketplace. Part numbering system reflects China wire sizes versus Japan wire sizes.  Photos/Drawing (where applicable) N/A |                                      |      |                |               |             |  |  |
|   |                                      |      |                |               |             |  |  |
| DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:  |                                      |      |                |               |             |  |  |
| SCHED   | ULE FOR CHANGE                       |      | Year<br>(YYYY) | Month<br>(MM) | Day<br>(DD) |  |  |
| New product   | sample availability date             | e    |                |               |             |  |  |
| Old product   | discontinuation date*                |      | 2023           | 12            | 4           |  |  |
| *Important: A return material authorization (RMA) may be obtained for these affected part numbers   |                                      |      |                |               |             |  |  |

\*Important: A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

| IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable) |                |               |             |          |                 |  |  |
|--|----------------|---------------|-------------|----------|-----------------|--|--|
|  |                |               |             | Grouping |                 |  |  |
|  |                |               |             | (For     |                 |  |  |
|  | Compatibility  | Replacement   | Replacement | Complex  | Discontinuation |  |  |
| PART NUMBER  | Туре           | Part 1        | Part 2      | only)    | Date            |  |  |
| BML2-120-12  | No Replacement | NO-REPLACEMEN |             |          | 04-DEC-2023     |  |  |
| BML2-240-12  | No Replacement | NO-REPLACEMEN |             |          | 04-DEC-2023     |  |  |
| BML2-25-12   | No Replacement | NO-REPLACEMEN |             |          | 04-DEC-2023     |  |  |
| BML2-300-12  | No Replacement | NO-REPLACEMEN |             |          | 04-DEC-2023     |  |  |
| BML2-35-12   | No Replacement | NO-REPLACEMEN |             |          | 04-DEC-2023     |  |  |
| BML2-50-12   | No Replacement | NO-REPLACEMEN |             |          | 04-DEC-2023     |  |  |
| BML2-70-12   | No Replacement | NO-REPLACEMEN |             |          | 04-DEC-2023     |  |  |
| BML2-95-12   | No Replacement | NO-REPLACEMEN |             |          | 04-DEC-2023     |  |  |