

PRODUCT CHANGE NOTIFICATION

Product Category POWER CONNECTORS **20230908-4**

Product Group POWER CONNECTORS GROUNDING AND STEEL

ISSUE DATE: 8-Sep-23

IMPACTED REGIONS: ☒ NA ☒ EMEA ☒ LATAM ☒ AP

REASON FOR CHANGE: ☒ DISCONTINUATION
☐ OTHER

DESCRIPTION OF CHANGE: (Required)

Introduction of more parts per box for our CB, LAM2, LAMA, LIAS, LICC power and grounding mechanical connector families. They will be moving from 3 -100 pcs per box to 5 -250 pcs per box and will not be able to be ordered in smaller increments.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2023	9	15
Old product discontinuation date*	2023	12	15

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)	Compatibility Type	Replacement Part 1
-------------------------	--------------------	--------------------

CB175-38-QY	Direct	CB175-38-L
CB70-14-CY	Direct	CB70-14-190
LAM2A1/0-14-6Y	Direct	LAM2A1/0-14-Q
LAM2A2/0-14-6Y	Direct	LAM2A2/0-14-Q
LAM2A250-38-6Y	Direct	LAM2A250-38-X
LAM2A350-12-6Y	Direct	LAM2A350-12-5
LAM2B350-12-3Y	Direct	LAM2B350-12-8
LAMA1/0-14-QY	Direct	LAMA1/0-14-L
LAMA2/0-14-QY	Direct	LAMA2/0-14-L
LAMA2-14-QY	Direct	LAMA2-14-C
LAMA500-38-6Y	Direct	LAMA500-38-5
LAMA6-14-QY	Direct	LAMA6-14-C
LIAS250-56-Q	Direct	LIAS250-56-X
LICC4-22-C	Direct	LICC4-22-TL
LICC4-22TP-C	Direct	LICC4-22TP-TL