

Product Change Notice

The change(s) will be applied on the affected products, if you need more information or special support, please contact PM: Cindy Huang (TEL: +886-2-2792-7818, ext: 1476; e-Mail:

cindy.huang@advantech.com.tw)

1. Reason for the Change: Key component EOL.

2. Affected Product: ASMB-815 series, and T part numbers that use same PCB as standard products

3. Impact on Application:

Item	Impact
Impact on Mechanical Design	No
Impact on Software Compatibility	No
Impact on Environment Characteristics	No
Impact on Board Certifications	No
Physical Outlook Change	No
Ordering P/N Change	Yes
Cut-in Implement	Running Change

4. Description of the Change(s):

Affected Models	Current Component	New Component	Category	Outlook Difference	Reason
ASMB-815	1410027341-01/ IR3557MTRPBF	1410026550-02/ TDA21460	HW	No	Key components EOL
	1410022160/ IR3897MTR1PBF	1410026524-01/ TPS82085SILR			
	1410025715-01/ PX3517	1410026550-02/ TDA21460			
	1410021062/ RTL8201EL-VC	1410022672-01/ RTL8201F-VB			
	19A2S81510-01/ PCB A102-1	19A2S81511-01/ PCB A102-2			

5. Implementation & Schedule of the Change(s):

Affected Models	ECOM Number	Estimated Effective Date	Cut-in Implement	Change Description
ASMB-815-00A1E ASMB-815I-00A1E ASMB-815T2-00A1E ASMB-815I-00A1U ASMB-815T2-00A1U	EPO-032251	Sep 2023	Running Change	- Change power solution IR3557MTRPBF to TDA21460 - Change power solution IR3897MTR1PBF to TPS82085SILR - Change power solution PX3517 to TDA21460 - Change BMC LAN chip RTL8201EL-VC to RTL8201F-VB

*Note: Cut-in progress depends on factory production schedule, what listed in this table is ESTIMATED time-frame.



Enabling an Intelligent Planet

研華股份有限公司
Advantech Co., Ltd.

台北市內湖區瑞光路26巷20弄1號
No.1, Alley 20, Lane 26, Rueiguang Road
Neihu, District, Taipei, Taiwan 114, R.O.C.
Tel: 886-2-2792-7818 Fax: 886-2-2794-7301
www.advantech.com

Contact Windows

PM	Cindy Huang / cindy.huang@advantech.com.tw / 511-1476
AE	AE.ISG.ACL@advantech.com