

PRODUCT CHANGE NOTIFICATION

Product Category POWER AND CONNECTIVITY 20230926-1

Product Group INTELLIGENT INFRASTRUCTURE

ISSUE DATE: 26-Sep-23

IMPACTED REGIONS: ☒ NA ☒ EMEA ☒ LATAM ☒ AP

REASON FOR CHANGE: ☒ DISCONTINUATION
☐ OTHER

DESCRIPTION OF CHANGE: (Required)

With the introduction of the High Density, Dual Rated, Combination Outlet offer and in alignment with the Panduit 80/20 strategy, The Dual Sided PDUs as well as some 415V Single Rated PDUs are being discontinued. As an added benefit, this move resolves much confusion in the marketplace with the “side mounting only” criteria of the Dual Sided PDUs as well as streamlines the supply chain by offering dual rated parts which can be used in multiple theaters.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2023	6	1
Old product discontinuation date*	2023	12	15

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

CUSTOMER SERVICE CONTACTS

ASIA PACIFIC	AUSTRALIA: 1-800 7263848 AUS-CSVM@panduit.com	CHINA: 400-820-1900 CHN-CustomerService@panduit.com	HONG KONG: 800-965768 CHN-CustomerService@panduit.com
	INDIA: 000 800 6501844 (Fixed) 000 800 6500369 (Mobile) SGP-Customer_Service@panduit.com	INDONESIA: 001 803 65 7571 SGP-Customer_Service@panduit.com	JAPAN: +81-3-6863-6000 JPN-CS@panduit.com
	KOREA: 02-2182-7300 KOR-CustomerService@panduit.com	MALAYSIA 1800 801435 SGP-Customer_Service@panduit.com	SINGAPORE: 1-800-7263848 SGP-Customer_Service@panduit.com
	TAIWAN: 0080 165 1487 SGP-Customer_Service@panduit.com	THAILAND: 001-800-65-6385 SGP-Customer_Service@panduit.com	
LATIN AMERICA	BRAZIL 08000562613 (Toll Free) BRA-custservice@panduit.com	MEXICO: +52-33-37776000 x80520 01 800 360 86 00 (Toll Free) MEX-customerservice@panduit.com	OTHER LA COUNTRIES: Phone USA 1-708-532-1800 TP-CS-INTERNATIONAL@panduit.com
NORTH AMERICA	USA & CANADA: 1-800-777-3300 cs@panduit.com	EMEA FORM C2-1003 DATE: 06 APR 21 APPR. MURILLO	EMEA: +44 208 6017219 EMEA-CustomerServices@panduit.com

		Discontinuation
IMPACTED PART NUMBER(s)	Replacement Part 1	Date
P24B32M	P24B14M	15-DEC-2023
P24D30M	P24D31M	15-DEC-2023
P24D33M	P24D34M	15-DEC-2023
P48B33M	P42D20M	15-DEC-2023
P48B45M	P42B11M	15-DEC-2023
P48D32M	P42D22M	15-DEC-2023
P48D35M	P42D20M	15-DEC-2023
P48D44M	P42D04M	15-DEC-2023
P48E10M	P48E20M	15-DEC-2023
P48E13M	P42E24M	15-DEC-2023
P48F09M	P36FA0M-BL1C	15-DEC-2023
P48F19M	P42G20M	15-DEC-2023
P48G09M	P48G30M	15-DEC-2023
P48G21M	P42G20M	15-DEC-2023
P48D07M	P48D20M	15-DEC-2023
P06D01M	NO-REPLACEMENT	15-DEC-2023
P06D03M	NO-REPLACEMENT	15-DEC-2023
P24D02M	P48D20M	15-DEC-2023
P24D05M	P48D20M	15-DEC-2023
P36D01M	P48D20M	15-DEC-2023
P36D03M	P48D20M	15-DEC-2023
P48D04M	P48D20M	15-DEC-2023
P48D08M	P48D20M	15-DEC-2023
P42D05M	P48D20M	15-DEC-2023
P42D08M	P48D20M	15-DEC-2023
P24E05M	P48E20M	15-DEC-2023
P24E07M	P48E20M	15-DEC-2023
P24E08M	P48E20M	15-DEC-2023
P24E09M	P48E20M	15-DEC-2023
P24E10M	P48E20M	15-DEC-2023
P24E11M	P48E20M	15-DEC-2023
P36E01M	P48E20M	15-DEC-2023
P36E03M	P48E20M	15-DEC-2023
P36E04M	P48E20M	15-DEC-2023
P36E05M	P48E20M	15-DEC-2023
P48E03M	P48E20M	15-DEC-2023
P48E11M	P48E20M	15-DEC-2023
P48E05M	P48E20M	15-DEC-2023
P48E12M	P48E20M	15-DEC-2023
P36G01M	P36G33M	15-DEC-2023
P36G03M	P36G33M	15-DEC-2023
P36G04M	P36G33M	15-DEC-2023
P36G05M	P36G33M	15-DEC-2023
P24G09M	P36G33M	15-DEC-2023
P24G13M	P36G33M	15-DEC-2023

P24G14M	P36G33M	15-DEC-2023
P24G15M	P36G33M	15-DEC-2023
P24G16M	P36G33M	15-DEC-2023
P24G17M	P36G33M	15-DEC-2023
P48G03M	P48G30M	15-DEC-2023
P48G12M	P48G30M	15-DEC-2023
P48G05M	P48G30M	15-DEC-2023
P48G13M	P48G30M	15-DEC-2023
P24F09M	P36FA0M-BL1C	15-DEC-2023
P24F11M	P36FA0M-BL1C	15-DEC-2023
P24F12M	P36FA0M-BL1C	15-DEC-2023
P24F13M	P36FA0M-BL1C	15-DEC-2023
P24F14M	P36FA0M-BL1C	15-DEC-2023
P24F15M	P36FA0M-BL1C	15-DEC-2023
P36F01M	P36FA0M-BL1C	15-DEC-2023
P36F03M	P36FA0M-BL1C	15-DEC-2023
P36F04M	P36FA0M-BL1C	15-DEC-2023
P36F05M	P36FA0M-BL1C	15-DEC-2023
P48F03M	P48F30M-BL1C	15-DEC-2023
P48F11M	P48F30M-BL1C	15-DEC-2023
P48F05M	P48F30M-BL1C	15-DEC-2023
P48F12M	P48F30M-BL1C	15-DEC-2023
P06B01M	NO-REPLACEMENT	15-DEC-2023
P06B05M	NO-REPLACEMENT	15-DEC-2023
P24B01M	P48D20M	15-DEC-2023
P24B03M	P48D20M	15-DEC-2023
P36B01M	P48D20M	15-DEC-2023
P36B03M	P48D20M	15-DEC-2023
P48B08M	P48D20M	15-DEC-2023
P54B01M	P48D20M	15-DEC-2023
P54B02M	P48D20M	15-DEC-2023
MA012	NO-REPLACEMENT	15-DEC-2023