

Product Termination Notification

Product Group: SF/Tue Oct 17, 2023/PTN-SF-353-2023-REV-0



Discontinuation of Transformers and Inductors with lack of demand and obsolescente risk

For further information, please contact your regional Vishay office.

CONTACT INFORMATION

Americas	Europe	Asia
Pierre Lesur	Pierre Lesur	Pierre Lesur
71 chemin de la Mauniere	71 chemin de la Mauniere	71 chemin de la Mauniere
-	-	-
Hyeres France 83400	Hyeres France 83400	Hyeres France 83400
Phone: +33494123050	Phone: +33494123050	Phone: +33494123050
Fax: +33494123051	Fax: +33494123051	Fax: +33494123051
pierre.lesur@vishay.com	pierre.lesur@vishay.com	pierre.lesur@vishay.com

Description of Change: Obsolescence. In conformance with our Product Life management procedure, and due to lack of customer demand for more than 6 years, amplified by potential obsolescence risk on raw material, Sfernice Division is transferring old Transformers and Inductors to an End of Product Life status

Reason for Change: Lack of demand

Expected Influence on Quality/Reliability/Performance: none

Part Numbers/Series/Families Affected: Please see materials list on the succeeding page.

Vishay Brand(S): Vishay Sfernice

Time Schedule:

Last Time Buy Date: Wed Apr 17, 2024 Last Time Ship Date: Thu Oct 17, 2024

Sample Availability: none

Product Identification: none

Qualification Data: none

This PTN is considered approved, without further notification, unless we receive specific customer concerns before Thu Nov 16, 2023 or as specified by contract.

Issued By: Pierre Lesur, pierre.lesur@vishay.com



Product Termination Notification

Product Group: SF/Tue Oct 17, 2023/PTN-SF-353-2023-REV-0



TORWIPDB11D000843	PLA51LA32	IPLA32L1R0KD	IPLA32L2R0KD	LINPTVFB00A001377
PLAC100P250	IPLA32L3R0KD	TORWIVNB00D000576	LINPIVFB00C002108	TORWINSB00D002068
IPLA32L4R0KD	LINWIMFB00D000531	LINSTVFB00A001484	TORWINSB00D002068D	LINPIVFB00C002109
TORPIPFB00A001631	LINPIVFB00C002107	TORPIPFB00A001632	TORWTVDB27D001403	LINSTVFB00A001582
LINPTVFB00A001433	TORWDVDB00A001328	LINPTVNB00A001701	TORWDVDB00A001330	LINWIMFB00D000532
TORWTVNB00A002117	PLA32PA455D002050D	TORPTPSB23D001220	TORWTCSB00C002072	LINSTNFB00C001785
TORWTCSB00C002071	TORWINFB00M000919	LINPINFB00M000278	TORWINFB00M001047	TORWDNSB00M001336
TORWINFB00M000914	TORWINFB00M001048			