



Product Change Notification / ALAN-20AYEA392

Date:

22-Nov-2023

Product Category:

Clock and Timing - High Speed Communication, Linear Regulators, Low-Med Voltage Power Modules, Power Management - PMIC, Power Management - Power Switches, Power MOSFET Drivers, Switching Regulators

PCN Type:

Manufacturing Change

Notification Subject:

CCB 6621 Initial Notice: Qualification of UNIG as a new assembly site for selected UCS21xx, MIC23xx, MIC24xx, SPN01xx, MIC28xx, MIC33xx, MIC53xx, MIC50xx, MIC94xx, MIC74xx, SPN02xx, MIC44xx, MIC95xx, MIC30xx, and SPN95xx device families available in multiple packages.

Affected CPNs:

[ALAN-20AYEA392_Affected_CPN_11222023.pdf](#)

[ALAN-20AYEA392_Affected_CPN_11222023.csv](#)

Notification Text:

PCN Status:Initial Notification

PCN Type:Manufacturing Change

Microchip Parts Affected:Please open one of the files found in the Affected CPNs section.

Note: For your convenience Microchip includes identical files in two formats (.pdf and .xls)

Description of Change:Qualification of UNIG as a new assembly site for selected UCS21xx, MIC23xx, MIC24xx, SPN01xx, MIC28xx, MIC33xx, MIC53xx, MIC50xx, MIC94xx, MIC74xx, SPN02xx, MIC44xx, MIC95xx, MIC30xx, and SPN95xx device families available in multiple packages.

Pre and Post Change Summary:

Method to Identify Change:Traceability code

Qualification Plan:Please open the attachments included with this PCN labeled as PCN_#_Qual_Plan.

Revision History:November 22, 2023: Issued initial notification.

The change described in this PCN does not alter Microchip's current regulatory compliance regarding the material content of the applicable products.

Attachments:

[PCN_ALAN-20AYEA392 Qual Plan.pdf](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

ALAN-20AYEA392 - CCB 6621 Initial Notice: Qualification of UNIG as a new assembly site for selected UCS21xx, MIC23xx, MIC24xx, SPN01xx, MIC28xx, MIC33xx, MIC53xx, MIC50xx, MIC94xx, MIC74xx, SPN02xx, MIC44xx, MIC95xx, MIC30xx, and SPN95xx device families available in multiple packages.

Affected Catalog Part Numbers (CPN)

UCS2114-1-V/LX
UCS2114-1A-V/LX
UCS2114T-1-V/LX
MIC23650YFT-TR
MIC23656YFT-TR
MIC23656-FAYFT-TR
MIC23656-HAYFT-TR
MIC23656-SAYFT-TR
MIC23350YFT-TR
MIC23356YFT-TR
MIC23356-FAYFT-TR
MIC23356-HAYFT-TR
MIC23356-SAYFT-TR
MIC24045-KDYFL
MIC24045-KDYFL-TR
SPN015011-TR
MIC2877-AYFT-TR
MIC2877-4.75YFT-TR
MIC23451-AAAYFL-T5
MIC23451-AAAYFL-TR
MIC33264YGK-T5
MIC33264YGK-TR
MIC5380-PPYFT-TR
MIC5019YFT-T5
MIC5019YFT-TR
MIC5381-PPYFT-TR
MIC2877-5.25YFT-TR
MIC2877-5.5YFT-TR
MIC28513-2YFL-T5
MIC28513-2YFL-TR
MIC94043YFL-TR
MIC94045YFL-TR
MIC33263YGK-T5
MIC33263YGK-TR
MIC5380-MGYFT-TR
MIC94040YFL-TR
MIC24045-DIYFL
MIC24045-DIYFL-TR
MIC7400
MIC7400YFL-T5
MIC7400YFL-TR
MIC7400-0001YFL-TR
MIC7400-0004YFL-TR
MIC7400-0011YFL-TR
MIC7400-0012YFL-TR
MIC7400-0001YFL-T5

ALAN-20AYEA392 - CCB 6621 Initial Notice: Qualification of UNIG as a new assembly site for selected UCS21xx, MIC23xx, MIC24xx, SPN01xx, MIC28xx, MIC33xx, MIC53xx, MIC50xx, MIC94xx, MIC74xx, SPN02xx, MIC44xx, MIC95xx, MIC30xx, and SPN95xx device families available in multiple packages.

MIC7401

MIC7401YFL-T5
MIC7401YFL-TR
MIC7401-0001YFL-TR
MIC7401-0006YFL-T5
MIC7401-0006YFL-TR
MIC7401-0007YFL-T5
MIC7401-0007YFL-TR
MIC7401-0008YFL-T5
MIC7401-0008YFL-TR
MIC7401-0010YFL-TR
MIC7401-0009YFL-T5
MIC7401-0009YFL-TR
MIC5381-G4YFT-TR
MIC7401-0001YFL-T5
MIC7401-0002YFL-T5
MIC7401-0002YFL-TR
MIC7401-0003YFL-T5
MIC7401-0003YFL-TR
MIC7401-0004YFL-T5
MIC7401-0004YFL-TR
MIC28511-2YFL-T5
MIC28511-2YFL-TR
MIC5380-LLYFT-TR
MIC5380-SSYFT-TR
MIC94082YFT-TR
MIC94085YFT-TR
SPN025013-TR
MIC24045-EIYFL
MIC24045-EIYFL-TR
MIC33M350YMP-TR
MIC33M356-FAYMP-TR
MIC33M356-HAYMP-TR
MIC33M356-SAYMP-TR
MIC28512-1YFL-T5
MIC28512-1YFL-TR
MIC94080YFT-TR
MIC5380-M4YFT-TR
MIC94041YFL-TR
MIC5380-NGYFT-TR
MIC4415YFT-TR
MIC4415YFT-T5
MIC7400-0005YFL
MIC7400-0006YFL
MIC7400-0007YFL
MIC7400-0008YFL
MIC7400-0009YFL
MIC7400-0020YFL
MIC7400-0011YFL

ALAN-20AYEA392 - CCB 6621 Initial Notice: Qualification of UNIG as a new assembly site for selected UCS21xx, MIC23xx, MIC24xx, SPN01xx, MIC28xx, MIC33xx, MIC53xx, MIC50xx, MIC94xx, MIC74xx, SPN02xx, MIC44xx, MIC95xx, MIC30xx, and SPN95xx device families available in multiple packages.

MIC7400-0012YFL

MIC7400-0002YFL-T5

MIC7400-0002YFL-TR

MIC7400-0003YFL-T5

MIC7400-0003YFL-TR

MIC7400-0004YFL-T5

MIC7400-0005YFL-T5

MIC7400-0005YFL-TR

MIC7400-0006YFL-T5

MIC7400-0006YFL-TR

MIC7400-0007YFL-T5

MIC7400-0007YFL-TR

MIC7400-0008YFL-T5

MIC7400-0008YFL-TR

MIC7400-0009YFL-T5

MIC7400-0009YFL-TR

MIC7400-0020YFL-T5

MIC7400-0020YFL-TR

MIC7400-0011YFL-T5

MIC7400-0012YFL-T5

MIC94044YFL-TR

MIC28513-1YFL-T5

MIC28513-1YFL-TR

MIC5380-G4YFT-TR

MIC5381-MGYFT-TR

MIC5381-M4YFT-TR

MIC24045-JFYFL

MIC24045-JFYFL-TR

MIC2877-5.0YFT-TR

MIC94083YFT-TR

MIC5380-KHYFT-TR

MIC95410YFL-TR

MIC95410YFL-T5

MIC94081YFT-TR

MIC94084YFT-TR

SPN025012-TR

MIC28512-2YFL-T5

MIC28512-2YFL-TR

MIC33163YGJ-T5

MIC33163YGJ-TR

MIC3003GFL

MIC3003GFL-TR

SPN950003

SPN950003-TR

MIC24046YFL-TR

MIC24046YFL-T5

MIC33164YGJ-T5

MIC33164YGJ-TR

MIC4414YFT-TR

ALAN-20AYEA392 - CCB 6621 Initial Notice: Qualification of UNIG as a new assembly site for selected UCS21xx, MIC23xx, MIC24xx, SPN01xx, MIC28xx, MIC33xx, MIC53xx, MIC50xx, MIC94xx, MIC74xx, SPN02xx, MIC44xx, MIC95xx, MIC30xx, and SPN95xx device families available in multiple packages.

MIC4414YFT-T5

MIC24045-2ZYFL

MIC24045-2ZYFL-TR

MIC28511-1YFL-T5

MIC28511-1YFL-TR

MIC94042YFL-TR

MIC24046-HYFL-TR

MIC5381-SSYFT-TR