

## Product Change Notice

**Issue Date: 25-October-2023****Change Description:**

Introduction of second source for DMI MCU

**Parts Affected:**

AFBR-57B4APZ  
AFBR-57B4APZC

**Description and Extent of Change:**

To reduce supply chain risks and ensure continuous supply of our product, a second supplier of the DMI MCU with integrated EEPROM got qualified. A new PCB and 4-pin ROSA are introduced in the part version using the second supplier of MCU. Revision marking behind the date code on the product label will change to “C” for parts containing MCU from the second supplier.

<b>Current</b>	<b>New</b>
First MCU supplier, external EEPROM, 5-pin ROSA, PCB. Label revision marking “B”.	Second MCU supplier, MCU with integrated EEPROM, 4-pin ROSA, PCB. Label revision marking “C”.

**Reasons for Change:**

Assurance of supply.

**Effect of Change on Fit, Form, Function, Quality, or Reliability:**

There is no change of fit, form, function or reliability.

**Effective Date of Change:**

Product shipments using this change will begin after **22-April-2024**. Timing of shipment of the changed part will vary by part number depending on customer demand, and inventory levels.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please acknowledge the receipt of the notice within 30 days of delivery. Lack of acknowledgement within 30 days constitutes acceptance of the change per JEDEC J-STD-046.