



Product / Process Change Notification (PCN)

PCN ID#: 212

Title: Supplier change for pole in speed & position sensors

Change: Permanent

Honeywell Contact

Name: Hernandez, Luis

E-mail: Luis.Hernandez@Honeywell.com

Title: Sr Quality Engineer

Product Information

Affected parts and revisions:

• 3015A • 3015A17 • 3015A35 • 3015HTB • 3015HTB15 • 3015S13 • 3015S13-36 • 3015SS13 • 3015SS25 • 3025 • 3025A17 • 3025A35 • 3025S13 • 3025SS13 • 3025SS25 • 3070A • 3070A35 • 3080 • 3090A • 3090A=RR • 3090A35 • 58423LV • 724839 • 725455 • 725733 • 726324 • 727456 • 727546-04 • 727546-04=MAC • 727546-04=MAC1 • 727621-01 • 727878-01 • 727880-01 • 727882-01 • 727883-01 • 728020-02 • 728096-01 • 728189-01 • 728189-02 • 728223-01 • MA230SAN • MA233SAN • MA240SAN • MA240SAN=DON • MA243HT • MA243SAN • MA3055 • MA3055S10 • MMA230SAN • MMA233SAN • MMA240SAN • MMA243SAN • X206983 • X212491-ST

Does the part number change? False

Type of Change:

Supplier- distributor

Change Description:

Current pole supplier is closing their operations, thus a new supplier is required for the poles used in the part numbers mentioned above. The new vendor will supply the material as per the current drawing, this means that there won't be any change in the material, dimensions, or any other spec. New pole will be validated by SQE following the standard PPAP process.

Reason for change:

Change of pole supplier (current supplier is closing their operations)

Justification for change:

Current pole supplier is closing their operations, thus a new supplier is required.

Product Identification to distinguish the change:

Date Code

Samples (If required): Will be available

Change Implementation Date: 2023-10-30

Honeywell is committed to providing you with a superior level of customer service. Please e- mail to contact listed above for additional information regarding this communication.

G-AST-FRM-QA.2

EFFECTIVE DATE: 3-29-22

REVISION: 0