



## Product / Process Change Notification (PCN)

**PCN ID#:** 226

**Title:** use screw LS20777 instead of LS20575

**Change:** Temporary deviation

### Honeywell Contact

Name: Dzul, Jorge

E-mail: Jorge.Dzul@Honeywell.com

Title: Sr Quality Engineer

### Product Information

#### Affected parts and revisions:

LSYAC4LX-FP LSD2F LSYCC3KP-FP LSA3K-1B LSYAC5KP-FP LSYAC6B-4N LSV3K BX4N4L LS2D4L LSXN4L LS3A1A  
LSQYMC7N361 1CPSA5 BX4A3K-1A LSL6C-4N LSYAC3KP-FP LSYNB3KQ-3BFP LSA1A LSXA4L LSXZ3M BFL1-AW2  
LSYAC3KQ-FP LSYAB2B LSXM4N5 LSA2B LSM6D LSR1A LSXYAB4L LSE3K BXA4L LSYMB4N LSXF3K LS4A2B  
LSXA7L LSYAB6B LS2YDB4K LSM7N LSC7L LSE6C5 BX4A4L LSYPB1A LSYUB1A13-2D LSYAB6B-1B BXM4N  
LSYPB4L LSYNC3KP-FP LSYDB3K LSA9A LSJ3K-7M LSXH4L LS2D4K LSL7M

**Does the part number change?** False

#### Type of Change:

Material

#### Change Description:

Current supplier is having some logistic issues to continue supplying the screw LS20575 used for a different model, Honeywell completed an evaluation for an alternate screw in order to avoid future material shortage, making the necessary adjustments to prevent a customer line down. Alternate material is in compliance with the technical spec, except for the slotted head. this change affects only form.

#### Reason for change:

Current supplier is having some logistic issues to continue supplying the screw LS20575

#### Justification for change:

Honeywell completed an evaluation for an alternate screw in order to avoid future material shortage.

#### Product Identification to distinguish the change:

2346

**Samples (If required):** Not applicable

**Change Implementation Date:** 2023-11-17

Honeywell is committed to providing you with a superior level of customer service. Please e- mail to [contact](#)

listed above for additional information regarding this communication.

G-AST-FRM-QA.2

EFFECTIVE DATE: 3-29-22

REVISION: 0