

Issue Date: Dec 08nd, 2023

Dear Valued Customer,

This PCN C0477 notice is to inform you of a change of some items that you have purchased from Littelfuse.

Description of the Change:

Due to a shortage of the black insulator material used on the bottom of the 75900 and M-290 Series manual battery disconnect switches, we will temporarily be substituting the raw material with an existing alternative component. This change is needed to ensure business continuity and avoid supply chain disruptions. There will be no change in fit, form or function of the finished goods. The only difference is in the color. The alternative component is red.

Reason for The Change:

Due to unavailability of black-colored raw material from our supplier, we are facing a shortage with a lead time of 2 months.

Effective Date of the Change:

December 12, 2023

What You Need to Do:

Coordinate with your customer service representative to obtain exact quantities impacted. Please, notify your customers who have purchased these P/Ns in the past.

If you have any questions, please feel free to contact your Littelfuse Customer Service or Inside Sales Representative. We appreciate your business and our continued partnership.

Sincerely,

Renata Cebada

Associate Product Manager
Commercial Vehicle Products