



Product Change Notification / MFOL-13IYMK921

Date:

14-Dec-2023

Product Category:

EtherCAT, Ethernet Switches

PCN Type:

Manufacturing Change

Notification Subject:

CCB 6715 Initial Notice: Qualification of MTAI as an additional assembly site for selected LAN9254, LAN9352 and LAN9355 device families available in 80L TQFP (12x12x1mm) package.

Affected CPNs:

[MFOL-13IYMK921_Affected_CPN_12142023.pdf](#)
[MFOL-13IYMK921_Affected_CPN_12142023.csv](#)

Notification Text:

PCN Status:Initial Notification

PCN Type:Manufacturing Change

Microchip Parts Affected:Please open one of the files found in the Affected CPNs section.
Note: For your convenience Microchip includes identical files in two formats (.pdf and .xls)

Description of Change:

Qualification of MTAI as an additional assembly site for selected LAN9254, LAN9352 and LAN9355 device families available in 80L TQFP (12x12x1mm) package.

Pre and Post Change Summary:

	Pre Change	Post Change
--	------------	-------------

Method to Identify Change:Traceability code

Qualification Plan:Please open the attachments included with this PCN labeled as PCN_#_Qual_Plan.

Revision History:December 14, 2023: Issued initial notification.

The change described in this PCN does not alter Microchip's current regulatory compliance regarding the material content of the applicable products.

Attachments:

[PCN_MFOL-13IYMK921_Qual Plan.pdf](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

LAN9352/PT
LAN9352I/PT
LAN9355/PT
LAN9355I/PT
LAN9254-V/JRX
LAN9254/JRX
LAN9254-I/JRX
LAN9352T/PT
LAN9254T-V/JRX
LAN9254T/JRX
LAN9254T-I/JRX
LAN9355T/PT
LAN9352TI/PT
LAN9355TI/PT