

		Issued By: Jason Yost
		Author: Jason Yost
		-
Change affects whole product family?	No	
	W 1 66 6 10	
Part #'s affected (See attached if entire product fa	mily is affected)	
507-5820-0747-600F		
507-5821-0747-600F		
507-5824-0747-600F		
Description of Observe		
Description of Change:		
Components going EOL.		
Reason for Change:		
Subassembly component MOQ raised to a volume	that can not be justified	to continue production
oubassembly component wow raised to a volume	finat can not be justined	to continue production.
Properties of Old vs. Changed Product:		
N/A		
,		
Disposition of Old Product:		
	N/A	
Expected Implementation Date: Immedi	iate	
Customer Feedback Expected by: N/A		
Additional Comments: (Include Potential Risks if A	Appropriate)	
Supporting Qualification Data:		
Attached as necessary		

Customer Product/Process Change Notification

PCN #

Issued Date: 29-Dec-23

112926

Fig. 5