



January 11, 2024

Product Advisory #1908

Part Numbers VL-EBXx-41xxx Copperhead

This is a formal notification regarding products supplied by VersaLogic Corp. Our records indicate that your company has purchased this product.

Please read this notice thoroughly to determine what impact this change may have on you with regard to your currently owned product or future purchases from VersaLogic Corp.

Affected Products

Products	Description	Old Revision Level	New Revision Level
VL-EBXs-41EAF	"Copperhead" Dual core computer board	1.03	1.04
VL-EBXs-41SAK	"Copperhead" Dual core computer board	1.03	1.04
VL-EBXe-41EHF	"Copperhead" Dual core computer board	1.03	1.04
VL-EBXe-41EJP	"Copperhead" Quad core computer board	1.03	1.04
VL-EBXe-41ELF	"Copperhead" I3 Dual core computer board	1.03	1.04
VL-EBXe-41SJF	"Copperhead" Quad core computer board	1.03	1.04
VL-EBXe-41EMF	"Copperhead" Celeron computer board	1.03	1.04
VL-EBXE-41SLK	"Copperhead" I3 Dual core computer board	1.03	1.04
VL-EBXe-41SMK	"Copperhead" Celeron computer board	1.03	1.04

Changes Made to Products

An on-board flash chip was updated to an equivalent as the previous part is no longer available.

***Customer Impact***

None. The revised product will operate identically to the previous version.

Fielded Units

Use As-Is

Additional Information

For additional information or assistance related to this change, please contact VersaLogic Technical Support at Support@VersaLogic.com or call (503) 747-2261.