

PROCESS CHANGE NOTICE (PCN)					
PCN Number: 24001		Means of distinguishing changed devices:			
Date Issued: 1/23/2024		Product Mark:			
Date Effective: 1/23/2024		Back Mark			
Date Issued (+90 days): 4/22/2024		□ Date Code			
		Other			
		Attachment: Yes □ No ⊠			
Product(s) Affected:					
88LX5151A0-	88LX5152A0-	88LX5152A0-	88LX5153A0-		
BUU2C000	BUU2C000	BUU2C000-A196	BUU2C000		
88LX5153A0- BUU2C000-A196	88LX5153A0-BUU2I000	MXL5153SL-AY-T			
Description of Change:					
MaxLinear is replacing new	memory die supplier (NANYA	a) as Windbond already PDN	the current memory die.		
Is there a change to form, below.	fit, function and reliability of	the parts? Yes ☐ No ☒ If	yes, please comment		
Purpose of Change:					
MaxLinear is replacing new	memory die supplier (NANYA	as Windbond already PDN	the current memory die.		
Change Details:					
Current	Nov	//Δdd			

Current	New/Add		
Memory die vendor	Memory die vendor		
Winbond, Taiwan	NANYA, Taiwan		



Reliability/Qualification Summary:

Test	Ref Spec/ Condition	Readpoint	Sample Size	Results
PCON	Preconditioning – MSL3 JESD22-A113 30°C/60% RH, 192Hrs + 3x Reflow	Post Reflow	3Lots, 50ea/lot	Passed
uHAS	Highly Accelerated Stress Test (with PCON) JESD22-A118 130°C / 85%RH / 96 hrs	96 Hrs	3Lots, 25ea/lot	Passed
TC	Temp Cycle (with PCON) JESD22-A104 Cond B: -55°C / 125°C	700 Cycles	3Lots, 25ea/lot	Passed
HTS	High Temp Storage JEDC22-A103 Ta = 150°C	1000 Hrs	3Lots, 25ea/lot	Passed

Samples and Support

Contact our Customer Support team by creating a support ticket at http://www.maxlinear.com/support/createcase

Phone: 1-760-692-0711

Customers are advised to acknowledge receipt of this notice. Lack of acknowledgement within 30 days confurther action.	•
Please email this form to the contact above after con	pleting the following information:
Customer:	_
Name:	-
Title:	-
Date:	-
E-Mail:	
Phone:	
Fax:	
Approval for shipments prior to effective date	
Customer Comments (Optional):	